

# OEM Guide Page

## HWH SpaceMaker Equipment for **FRONTLINE COMM. CORP** Vehicles

(File: MR402700.DOC | Revised: 06APR17)

[> Printable PDF File](#)

**PROCEDURE:**

1. Locate the HWH identification tag on the SpaceMaker mechanism to get the correct mechanism part number.
2. Find the correct SpaceMaker mechanism part number in the left column below.
3. Refer to the listed HWH Parts Manual Page for general replacement parts information and item number arrangements .
4. Note that two-cylinder mechanisms with a synchronizing cylinder have two part numbers. One number is for the left assembly and one is for the right assembly. If the mechanism assembly originally had one number, that number is listed with the new numbers.

<b>SLIDE-OUT Mechanisms</b>	
<b>MECHANISM</b> <i>AP38251</i> <i>AP38252</i>	<p><b>UNIVERSAL STRAIGHT OUT – 30.0” STROKE (WITH SYNCHRONIZING CYLINDER)</b>  <b>AP43482 AND AP45763 KITS</b>  <b>SEE &gt; <a href="#">MR412685.HTML</a> FOR DRAWING AND PARTS INFORMATION.</b></p> <p>CYLINDER ASSEMBLY_____ ITEM 1 - RAP92076 (30.5” STROKE)  REPLACES AP38072</p> <p>SYNCHRONIZING CYLINDER_____ ITEM 3 - RAP92077 (10.540” STROKE)  REPLACES AP37881</p> <p>TUBE KIT_____ ITEM 2 - RAP92079 - REPLACES AP38267</p> <p>HOSE ASSEMBLIES_____ ITEM 4 - RAP24632 (AP24632)  ITEM 5 - RAP24638 (AP24638)</p>
<b>MECHANISM</b> <i>AP39645</i> <i>AP39646</i>	<p><b>UNIVERSAL LEVEL IN / LEVEL OUT – 26.0” STROKE (WITH SYNCHRONIZING CYLINDER)</b>  <b>AP45762, AP45766, AP47100 AND AP45767 KITS</b>  <b>SEE &gt; <a href="#">MR412685.HTML</a> FOR DRAWING AND PARTS INFORMATION.</b></p> <p>CYLINDER ASSEMBLY_____ ITEM 1 - RAP92076 (30.5” STROKE)  REPLACES AP38072</p> <p>SYNCHRONIZING CYLINDER_____ ITEM 3 - RAP93560 (9.130” STROKE)  REPLACES AP45880</p> <p>TUBE KIT_____ ITEM 2 - RAP92079 - REPLACES AP38267</p> <p>HOSE ASSEMBLIES_____ ITEM 4 - RAP24632 (AP24632)  ITEM 5 - RAP24638 (AP24638)</p>
<b>MECHANISM</b> <i>AP45166</i>	<p><b>SUBFLOOR ASSEMBLY – 104.5” WIDE – PART OF AP45762 KIT</b></p> <p>CYLINDER W/SEQ. VALVE ASSY._ RAP93561 (8.25” STROKE)- REPLACES AP45830</p>
<b>MECHANISM</b> <i>AP45855</i>	<p><b>SUBFLOOR ASSEMBLY – 94.0” WIDE – PART OF AP45766 KIT</b></p> <p>CYLINDER W/SEQ. VALVE ASSY._ RAP93561 (8.25” STROKE)- REPLACES AP45830</p>
<b>MECHANISM</b> <i>AP45856</i>	<p><b>SUBFLOOR ASSEMBLY – 107.0” WIDE – PART OF AP45767 KIT</b></p> <p>CYLINDER W/SEQ. VALVE ASSY._ RAP93561 (8.25” STROKE)- REPLACES AP45830</p>
<b>MECHANISM</b> <i>AP46820</i>	<p><b>SUBFLOOR ASSEMBLY – 92.5” WIDE</b></p> <p>CYLINDER W/SEQ. VALVE ASSY._ RAP93562 (7.25” STROKE)- REPLACES AP47075</p>
<b>MECHANISM</b> <i>AP47118</i>	<p><b>SUBFLOOR ASSEMBLY – 93.25” WIDE</b></p> <p>CYLINDER W/SEQ. VALVE ASSY._ RAP93562 (7.25” STROKE)- REPLACES AP47075</p>

<b>MECHANISM</b> AP47119	<b>SUBFLOOR ASSEMBLY – 106.25” WIDE</b> CYLINDER W/SEQ. VALVE ASSY._ RAP93562 (7.25” STROKE)- REPLACES AP47075
<b>MECHANISM</b> AP48994	<b>SUBFLOOR ASSEMBLY – 110.35” WIDE</b> CYLINDER W/SEQ. VALVE ASSY._ RAP93562 (7.25” STROKE)- REPLACES AP47075
<b>MECHANISM</b> AP50437	<b>SUBFLOOR ASSEMBLY – 104.35” WIDE</b> CYLINDER W/SEQ. VALVE ASSY._ RAP93562 (7.25” STROKE)- REPLACES AP47075
<b>MECHANISM</b> AP51200	<b>SUBFLOOR ASSEMBLY – 75.35” WIDE</b> CYLINDER W/SEQ. VALVE ASSY._ RAP93562 (7.25” STROKE)- REPLACES AP47075
<b>MECHANISM</b> AP52181	<b>SUBFLOOR ASSEMBLY – 110.35” WIDE</b> CYLINDER W/SEQ. VALVE ASSY._ RAP93562 (7.25” STROKE)- REPLACES AP47075
<b>MECHANISM</b> AP52575	<b>SUBFLOOR ASSEMBLY – 94.0” WIDE</b> CYLINDER W/SEQ. VALVE ASSY._ RAP93562 (7.25” STROKE)- REPLACES AP47075
<b>MECHANISM</b> AP52576	<b>SUBFLOOR ASSEMBLY – 107.0” WIDE</b> CYLINDER W/SEQ. VALVE ASSY._ RAP93562 (7.25” STROKE)- REPLACES AP47075
<b>MECHANISM</b> AP52966	<b>SUBFLOOR ASSEMBLY – 136.0” WIDE</b> CYLINDER W/SEQ. VALVE ASSY._ RAP93558 (7.25” STROKE)- REPLACES AP46085 CYLINDER ASSEMBLY_____ RAP93559 (7.25” STROKE)- REPLACES AP46093 HOSE ASSEMBLIES_____ RAP4062 (AP4062) RAP4075 (AP4075) RAP4073 (AP4073) RAP4073 (AP4073) RAP4075 (AP4075) RAP4159 (AP4159)
<b>MECHANISM</b> AP52970	<b>SUBFLOOR ASSEMBLY – 136.0” WIDE</b> CYLINDER W/SEQ. VALVE ASSY._ RAP93558 (7.25” STROKE)- REPLACES AP46085 CYLINDER ASSEMBLY_____ RAP93559 (7.25” STROKE)- REPLACES AP46093 HOSE ASSEMBLIES_____ RAP4062 (AP4062) RAP4075 (AP4075) RAP4073 (AP4073) RAP4073 (AP4073) RAP4075 (AP4075) RAP4159 (AP4159)
<b>MECHANISM</b> AP53667	<b>SUBFLOOR ASSEMBLY – 120.0” WIDE</b> CYLINDER W/SEQ. VALVE ASSY._ RAP93562 (7.25” STROKE)- REPLACES AP47075