

# ROOM EXTENSION ASSEMBLIES GUIDE PAGE "MONACO COACH CORPORATION" (PAGE 2 OF 4)

PROCEDURE: SEE "MONACO COACH CORPORATION" (PAGE 1 OF 4)

MECHANISM AP25142 AP25143	<b>DUAL CYLINDER ROOM EXTENSION - 30.5" STROKE (WITH SYNCHRONIZING CYLINDER) - AP25141 KIT</b>  <b>SEE MR41.2005 FOR DRAWING AND PARTS INFORMATION.</b> CYLINDER ASSEMBLY _____ ITEM 1 - RAP90971 (37.5" STROKE) - REPLACES AP25201 SYNCHRONIZING CYLINDER _____ ITEM 3 - RAP90442 (12.570" STROKE) - REPLACES AP16484 TUBE KIT _____ ITEM 2 - RAP90480 - REPLACES AP13252
MECHANISM AP26892 AP26893	<b>LATERAL ARM ROOM EXTENSION - 18.0" STROKE (WITH TORSION BAR) - AP26891 KIT</b>  <b>SEE MR41.2825 FOR DRAWING AND PARTS INFORMATION.</b> CYLINDER ASSEMBLY _____ ITEM 1 - RAP91203 (6.150" STROKE) - REPLACES AP26255 TUBE KIT _____ ITEM 2 - RAP91226 - REPLACES AP27031 HOSE ASSEMBLIES _____ ITEM 4 - RAP91574 (AP24627) ITEM 5 - RAP91573 (AP32672)
MECHANISM AP27707 AP27708	<b>X-SLIDE ROOM EXTENSION - 17.75" STROKE - AP27706 KIT</b>  <b>SEE MR41.2670 FOR DRAWING AND PARTS INFORMATION.</b> CYLINDER ASSEMBLY _____ ITEM 1 - RAP91007 (8.10" STROKE) - REPLACES AP27723 TUBE KIT _____ ITEM 2 - RAP91229 - REPLACES AP27587 HOSE ASSEMBLIES _____ ITEM 4 - RAP91528 (AP24654) ITEM 5 - RAP90321 (AP24653)
MECHANISM AP28586 AP28587	<b>LATERAL ARM ROOM EXTENSION - 16.0" STROKE - AP28585 KIT</b>  <b>SEE MR41.2825 FOR DRAWING AND PARTS INFORMATION.</b> CYLINDER ASSEMBLY _____ ITEM 1 - RAP91203 (6.150" STROKE) - REPLACES AP26255 TUBE KIT _____ ITEM 2 - RAP91226 - REPLACES AP27031 HOSE ASSEMBLIES _____ ITEM 4 - RAP91554 (AP24641) ITEM5 - RAP90428 (AP24642)
MECHANISM AP28776 AP28777	<b>LATERAL ARM ROOM EXTENSION - 17.25" STROKE - AP28775 KIT</b>  <b>SEE MR41.2825 FOR DRAWING AND PARTS INFORMATION.</b> CYLINDER ASSEMBLY _____ ITEM 1 - RAP91203 (6.150" STROKE) - REPLACES AP26255 TUBE KIT _____ ITEM 2 - RAP91226 - REPLACES AP27031 HOSE ASSEMBLIES _____ ITEM 4 - RAP91554 (AP24641) ITEM 5 - RAP90428 (AP24642)
MECHANISM AP28781 AP28782	<b>LATERAL ARM ROOM EXTENSION - 17.625" STROKE - AP28780 KIT</b>  <b>SEE MR41.2825 FOR DRAWING AND PARTS INFORMATION.</b> CYLINDER ASSEMBLY _____ ITEM 1 - RAP91203 (6.150" STROKE) - REPLACES AP26255 TUBE KIT _____ ITEM 2 - RAP91226 - REPLACES AP27031 HOSE ASSEMBLIES _____ ITEM 4 - RAP90322 (AP24651) ITEM 5 - RAP90821 (AP24652)
MECHANISM AP29855	<b>GENERATOR SLIDE - 24.0" STROKE (CYLINDER ONLY) - AP29856 KIT</b>  CYLINDER ASSEMBLY _____ RAP92507 (24.0" STROKE) - REPLACES AP29855
MECHANISM AP30761	<b>CYLINDER ASSEMBLY - 16.0" STROKE</b>  CYLINDER ASSEMBLY _____ RAP92470 (16.0" STROKE) - REPLACES AP30761
MECHANISM AP30763	<b>CYLINDER ASSEMBLY - 30.0" STROKE</b>  CYLINDER ASSEMBLY _____ RAP91666 (30.0" STROKE) - REPLACES AP30763
MECHANISM AP30948 AP30949 OR AP31226	<b>LATERAL ARM ROOM EXTENSION - 17.625" STROKE - AP30947 AND AP31225 KITS</b>  <b>SEE MR41.2825 FOR DRAWING AND PARTS INFORMATION.</b> CYLINDER ASSEMBLY _____ ITEM 1 - RAP91203 (6.150" STROKE) - REPLACES AP26255 TUBE KIT _____ ITEM 2 - RAP91226 - REPLACES AP27031 HOSE ASSEMBLIES _____ ITEM 4 - RAP91528 (AP24654) ITEM 5 - RAP90321 (AP24653)