

OEM Guide Page

HWH SpaceMaker Equipment for **ROGUE COACH CONVERTERS Vehicles**

(File: MR406250.DOC | Revised: 24APR17)

[> Printable PDF File](#)

> [Door Lift Mechanisms](#)
 > [Slide-Out Mechanisms](#)

PROCEDURE:

1. Locate the HWH identification tag on the SpaceMaker mechanism to get the correct mechanism part number.
2. Find the correct SpaceMaker mechanism part number in the left column below.
3. Refer to the listed HWH Parts Manual Page for general replacement parts information and item number arrangements.
4. Note that two-cylinder mechanisms with a synchronizing cylinder have two part numbers. One number is for the left assembly and one is for the right assembly. If the mechanism assembly originally had one number, that number is listed with the new numbers.

DOOR LIFT Mechanisms	
MECHANISM AP13309	COMPARTMENT DOOR ADD ON KIT – 24.0” STROKE – AP12622 KIT CYLINDER ASSEMBLY_____ RAP90900 (24.0” STROKE) – REPLACES AP13309

SLIDE-OUT Mechanisms	
MECHANISM AP10137	DUAL CYLINDER ROOM EXTENSION – 37.0” STROKE (WITH RACK SENSING VALVE) AP10145 KIT SEE > MR411534.HTML FOR DRAWING AND PARTS INFORMATION. CYLINDER ASSEMBLY_____ ITEM 1 - RAP90069 (37.0” STROKE) REPLACES AP2340 HOSE ASSEMBLIES_____ ITEM 7 - RAP4073 (AP4073) ITEM 8 - RAP2446 (AP2446) ITEM 9 - RAP4074 (AP4074) ITEM 10- RAP4065 (AP4065)
MECHANISM AP11399	SINGLE CYLINDER ROOM EXTENSION – 24.0” STROKE – AP11565 KIT CYLINDER ASSEMBLY_____ ITEM 1 - RAP90355 (24.4” STROKE) REPLACES AP11400 HOSE ASSEMBLIES_____ ITEM 4 - RAP4059 (AP4059) ITEM 5 - RAP5351 (AP5351)
MECHANISM AP11405	CYLINDER ASSEMBLY – 80.0” STROKE CYLINDER ASSEMBLY_____ RAP90655 (80.0” STROKE)–REPLACES AP11405
MECHANISM AP11447	DUAL CYLINDER ROOM EXTENSION - 36.0” STROKE (WITH RACK SENSING VALVE) AP11448 AND AP11565 KITS SEE > MR411534.HTML FOR DRAWING AND PARTS INFORMATION. CYLINDER ASSEMBLY_____ ITEM 1 - RAP90112 (39.0” STROKE) REPLACES AP11105 HOSE ASSEMBLIES_____ ITEM 7 - RAP4728 (AP4728) ITEM 8 - RAP4158 (AP4158) ITEM 9 - RAP4074 (AP4074) ITEM 10- RAP4065 (AP4065)

MECHANISM AP13149	DUAL CYLINDER ROOM EXTENSION – 36.0” STROKE (WITH RACK SENSING VALVE) AP13148 KIT SEE > MR411536.HTML FOR DRAWING AND PARTS INFORMATION. CYLINDER ASSEMBLY_____ ITEM 1 - RAP90112 (39.0” STROKE) REPLACES AP11105 HOSE ASSEMBLIES_____ ITEM 7 - RAP4728 (AP4728) ITEM 8 - RAP4158 (AP4158) ITEM 9 - RAP4074 (AP4074) ITEM 10- RAP4065 (AP4065)
MECHANISM AP18902	SINGLE CYLINDER ROOM EXTENSION – 24.0” STROKE –AP18901 KIT SEE > MR411100.HTML FOR DRAWING AND PARTS INFORMATION. CYLINDER ASSEMBLY_____ ITEM 1 - RAP91021 (27.0” STROKE) REPLACES AP28682 HOSE ASSEMBLIES_____ ITEM 3 - RAP50907 (AP50907) ITEM 4 - RAP16434 (AP16434)
MECHANISM AP18908 AP18909	DUAL CYLINDER ROOM EXTENSION – 32.0” STROKE (WITH SYNCHRONIZING CYLINDER) AP18907 KIT SEE > MR412005.HTML FOR DRAWING AND PARTS INFORMATION. CYLINDER ASSEMBLY_____ ITEM 1 - RAP90665 (32.5” STROKE) REPLACES AP18137 SYNCHRONIZING CYLINDER_____ ITEM 3 - RAP90466 (12.980” STROKE) REPLACES AP14301 TUBE KIT_____ ITEM 2 - RAP90480 - REPLACES AP13252
MECHANISM AP18911 AP18912	DUAL CYLINDER FLAT FLOOR ROOM EXTENSION – 32.0” STROKE (WITH SYNC. CYL.) AP18910 KIT SEE > MR412200.HTML FOR DRAWING AND PARTS INFORMATION. CYLINDER ASSEMBLY_____ ITEM 1 - RAP90696 (36.0” STROKE) REPLACES AP19256 SYNCHRONIZING CYLINDER_____ ITEM 3 - RAP90466 (12.980” STROKE) REPLACES AP14301 HOSE ASSEMBLY_____ ITEM 2 - RAP24648 (AP24648)
MECHANISM AP21465	CYLINDER ASSEMBLY – 45.4” STROKE CYLINDER ASSEMBLY_____ AP21465 (45.4” STROKE)–CONTACT HWH CORP.
MECHANISM AP21467	CYLINDER ASSEMBLY – 40.0” STROKE CYLINDER ASSEMBLY_____ AP21467 (40.0” STROKE)–CONTACT HWH CORP.