

ROOM EXTENSION ASSEMBLIES GUIDE PAGE "SVI TRUCKS"

PROCEDURE:

1. Locate the HWH identification tag on the room extension mechanism to get the correct room extension part number.
2. Find the correct room extension part number in the left column below.
3. Refer to the proper parts page for general replacement parts information and item number arrangements.
4. Two cylinder room extensions with a synchronizing cylinder have two room extension part numbers. One is for the left assembly, one is for the right assembly. If the room extension assembly originally had one number, that number is listed with the new numbers.

MECHANISM AP38944 AP38945	UNIVERSAL LEVEL OUT - 30.0" STROKE (WITH SYNC. CYLINDER) - AP40346 AND AP42509 KITS SEE MR41.2690 FOR DRAWING AND PARTS INFORMATION. CYLINDER ASSEMBLY _____ ITEM 1 - RAP92076 (30.5" STROKE) - REPLACES AP38072 LIFT CYLINDER ASSEMBLY _____ ITEM 11 - RAP92260 (2.75" LIFT) - REPLACES AP38604 SYNCHRONIZING CYLINDER _____ ITEM 3 - RAP92077 (10.540" STROKE) - REPLACES AP37881 LIFT SYNCHRONIZING CYLINDER _____ ITEM 12 - RAP92316 - REPLACES AP38264 TUBE KIT _____ ITEM 2 - RAP92079 - REPLACES AP38267 HOSE ASSEMBLIES _____ ITEM 4 - RAP90872 (AP24632) ITEM 5 - RAP91421 (AP24818)
MECHANISM AP43166 AP43167	UNIVERSAL STRAIGHT OUT - 30.0" STROKE (WITH SYNC. CYLINDER) - AP51232 SEE MR41.2685 FOR DRAWING AND PARTS INFORMATION. CYLINDER ASSEMBLY _____ ITEM 1 - RAP92076 (30.5" STROKE) - REPLACES AP38072 SYNCHRONIZING CYLINDER _____ ITEM 3 - RAP93303 (10.540" STROKE) - REPLACES AP46064 TUBE KIT _____ ITEM 2 - RAP92079 - REPLACES AP38267 HOSE ASSEMBLIES _____ ITEM 4 - RAP90872 (AP24632) ITEM 5 - RAP91421 (AP24818)
MECHANISM AP51183	PLATFORM LIFT WITH THREE CYLINDERS - 126.25" WIDE SEE MR41.4010 FOR DRAWING AND PARTS INFORMATION. CYLINDER W/ SEQ. VALVE ASSY. _____ ITEM 1 - RAP93139 (4.8" STROKE) - REPLACES AP44387 CYLINDER ASSEMBLY _____ ITEMS 2 - RAP93140 (4.8" STROKE) - REPLACES AP44395