

ROOM EXTENSION ASSEMBLIES GUIDE PAGE "WESTERN SHELTER MOBILITY"

PROCEDURE:

1. Locate the HWH identification tag on the room extension mechanism to get the correct room extension part number.
2. Find the correct room extension part number in the left column below.
3. Refer to the proper parts page for general replacement parts information and item number arrangements.
4. Two cylinder room extensions with a synchronizing cylinder have two room extension part numbers. One is for the left assembly, one is for the right assembly. If the room extension assembly originally had one number, that number is listed with the new numbers.

MECHANISM AP28421	CYLINDER KIT / FLOOR - 7.385" STROKE - AP28420 KIT
	CYLINDER ASSEMBLY _____ RAP92481 (7.385" STROKE) - REPLACES AP28421
MECHANISM AP34811 AP34812	DUAL CYLINDER ROOM EXTENSION - 69.0" STROKE (WITH SYNCHRONIZING CYLINDER) - AP34810 KIT
	<p>SEE MR41.2011 FOR DRAWING AND PARTS INFORMATION.</p> CYLINDER ASSEMBLY _____ ITEM 1 - RAP91784 (70.0" STROKE) - REPLACES AP34827 SYNCHRONIZING CYLINDER _____ ITEM 3 - RAP91798 (26.570" STROKE) - REPLACES AP34839 TUBE KIT _____ ITEM 2 - RAP91785 - REPLACES AP34828
MECHANISM AP40753 AP40754	UNIVERSAL LEVEL OUT - 30.0" STROKE (WITH SYNCHRONIZING CYLINDER) - AP45666 KIT
	<p>SEE MR41.2690 FOR DRAWING AND PARTS INFORMATION.</p> CYLINDER ASSEMBLY _____ ITEM 1 - RAP92076 (30.5" STROKE) - REPLACES AP38072 LIFT CYLINDER ASSEMBLY _____ ITEM 11 - RAP92261 (3.50" LIFT) - REPLACES AP40746 SYNCHRONIZING CYLINDER _____ ITEM 3 - RAP92077 (10.540" STROKE) - REPLACES AP37881 LIFT SYNCHRONIZING CYLINDER _____ ITEM 12 - RAP92503 - REPLACES AP40832 TUBE KIT _____ ITEM 2 - RAP92079 - REPLACES AP38267 HOSE ASSEMBLIES _____ ITEM 4 - RAP90872 (AP24632) ITEM 5 - RAP91421 (AP24818)
MECHANISM AP47632 AP47633	DUAL CYLINDER ROOM EXTENSION - 44.0" STROKE (WITH SYNCHRONIZING CYLINDER) - AP47631 KIT
	<p>SEE MR41.2000 FOR DRAWING AND PARTS INFORMATION.</p> CYLINDER ASSEMBLY _____ ITEM 1 - RAP92918 (45.0" STROKE) - REPLACES AP47655 SYNCHRONIZING CYLINDER _____ ITEM 3 - RAP92919 (15.510" STROKE) - REPLACES AP47639 TUBE KIT _____ ITEM 2 - RAP90481 - REPLACES AP15379
MECHANISM AP48852 AP48853	UNIVERSAL LEVEL OUT - 20.0" STROKE (WITH SYNCHRONIZING CYLINDER) - AP48603 KIT
	<p>SEE MR41.2690 FOR DRAWING AND PARTS INFORMATION.</p> CYLINDER ASSEMBLY _____ ITEM 1 - RAP92076 (30.5" STROKE) - REPLACES AP38072 LIFT CYLINDER ASSEMBLY _____ ITEM 11 - RAP92261 (3.50" LIFT) - REPLACES AP40746 SYNCHRONIZING CYLINDER _____ ITEM 3 - RAP92099 (7.010" STROKE) - REPLACES AP39221 LIFT SYNCHRONIZING CYLINDER _____ ITEM 12 - RAP92503 - REPLACES AP40832 TUBE KIT _____ ITEM 2 - RAP92079 - REPLACES AP38267 HOSE ASSEMBLIES _____ ITEM 4 - RAP90872 (AP24632) ITEM 5 - RAP91421 (AP24818)