

OEM Guide Page

HWH SpaceMaker Equipment for **WESTERN SHELTER MOBILITY Vehicles**

(File: MR409120.DOC | Revised: 10MAY17)

[> Printable PDF File](#)

PROCEDURE:

1. Locate the HWH identification tag on the SpaceMaker mechanism to get the correct mechanism part number.
2. Find the correct SpaceMaker mechanism part number in the left column below.
3. Refer to the listed HWH Parts Manual Page for general replacement parts information and item number arrangements.
4. Note that two-cylinder mechanisms with a synchronizing cylinder have two part numbers. One number is for the left assembly and one is for the right assembly. If the mechanism assembly originally had one number, that number is listed with the new numbers.

SLIDE-OUT Mechanisms	
MECHANISM AP28421	<p>CYLINDER KIT / FLOOR – 7.385” STROKE – AP28420 KIT</p> <p>CYLINDER ASSEMBLY_____ RAP92481 (7.385” STROKE) –REPLACES AP28421</p>
MECHANISM AP34811 AP34812	<p>DUAL CYLINDER ROOM EXTENSION – 69.0” STROKE (WITH SYNCHRONIZING CYL.) AP34810 KIT SEE > MR412011.HTML FOR DRAWING AND PARTS INFORMATION.</p> <p>CYLINDER ASSEMBLY_____ ITEM 1 - RAP91784 (70.0” STROKE) REPLACES AP34827</p> <p>SYNCHRONIZING CYLINDER_____ ITEM 3 - RAP91798 (26.570” STROKE) REPLACES AP34839</p> <p>TUBE KIT_____ ITEM 2 - RAP91785 - REPLACES AP34828</p>
MECHANISM AP40753 AP40754	<p>UNIVERSAL LEVEL OUT – 30.0” STROKE (WITH SYNCHRONIZING CYLINDER) AP45666 KIT SEE > MR412690.HTML FOR DRAWING AND PARTS INFORMATION.</p> <p>CYLINDER ASSEMBLY_____ ITEM 1 - RAP92076 (30.5” STROKE) REPLACES AP38072</p> <p>LIFT CYLINDER ASSEMBLY_____ ITEM 11 - RAP92261 (3.50” LIFT) REPLACES AP40746</p> <p>SYNCHRONIZING CYLINDER_____ ITEM 3 - RAP92077 (10.540” STROKE) REPLACES AP37881</p> <p>LIFT SYNCHRONIZING CYLINDER_ ITEM 12 - RAP92503 - REPLACES AP40832</p> <p>TUBE KIT_____ ITEM 2 - RAP92079 - REPLACES AP38267</p> <p>HOSE ASSEMBLIES_____ ITEM 4 - RAP24632 (AP24632) ITEM 5 - RAP24638 (AP24638)</p>
MECHANISM AP47632 AP47633	<p>DUAL CYLINDER ROOM EXTENSION – 44.0” STROKE (WITH SYNCHRONIZING CYL.) AP47631 KIT SEE > MR412000.HTML FOR DRAWING AND PARTS INFORMATION.</p> <p>CYLINDER ASSEMBLY_____ ITEM 1 - RAP92918 (45.0” STROKE) REPLACES AP47655</p> <p>SYNCHRONIZING CYLINDER_____ ITEM 3 - RAP92919 (15.510” STROKE) REPLACES AP47639</p> <p>TUBE KIT_____ ITEM 2 - RAP90481 - REPLACES AP15379</p>

MECHANISM AP48852 AP48853	UNIVERSAL LEVEL OUT – 20.0” STROKE (WITH SYNCHRONIZING CYLINDER) AP48603 KIT SEE > MR412690.HTML FOR DRAWING AND PARTS INFORMATION CYLINDER ASSEMBLY_____ ITEM 1 - RAP92076 (30.5” STROKE) REPLACES AP38072 LIFT CYLINDER ASSEMBLY_____ ITEM 11 - RAP92261 (3.50” LIFT) REPLACES AP40746 SYNCHRONIZING CYLINDER_____ ITEM 3 - RAP92099 (7.010” STROKE) REPLACES AP39221 LIFT SYNCHRONIZING CYLINDER_ ITEM 12 - RAP92503 - REPLACES AP40832 TUBE KIT_____ ITEM 2 - RAP92079 - REPLACES AP38267 HOSE ASSEMBLIES_____ ITEM 4 - RAP24632 (AP24632) ITEM 5 - RAP24638 (AP24638)
--	---