

ROOM EXTENSION ASSEMBLIES GUIDE PAGE "WHITTAKER COACHBUILDERS" (PAGE 1 OF 2)

PROCEDURE:

1. Locate the HWH identification tag on the room extension mechanism to get the correct room extension part number.
2. Find the correct room extension part number in the left column below.
3. Refer to the proper parts page for general replacement parts information and item number arrangements.
4. Two cylinder room extensions with a synchronizing cylinder have two room extension part numbers. One is for the left assembly, one is for the right assembly. If the room extension assembly originally had one number, that number is listed with the new numbers.

MECHANISM AP24083 AP24084	<p>DUAL CYLINDER ROOM EXTENSION - 39.5" STROKE (WITH SYNCHRONIZING CYLINDER) -AP24082 KIT</p> <p>SEE MR41.2000 FOR DRAWING AND PARTS INFORMATION.</p> <p>CYLINDER ASSEMBLY _____ ITEM 1 - RAP91239 (40.5" STROKE) - REPLACES AP24107 SYNCHRONIZING CYLINDER _____ ITEM 3 - RAP91018 (16.175" STROKE) - REPLACES AP24085 TUBE ASSEMBLIES _____ ITEM 2 - RAP90481 - REPLACES AP15379</p>
MECHANISM AP38251 AP38252	<p>UNIVERSAL STRAIGHT OUT - 30.0" STROKE (WITH SYNCHRONIZING CYLINDER) - AP40019 KIT</p> <p>SEE MR41.2685 FOR DRAWING AND PARTS INFORMATION.</p> <p>CYLINDER ASSEMBLY _____ ITEM 1 - RAP92076 (30.5" STROKE) - REPLACES AP38072 SYNCHRONIZING CYLINDER _____ ITEM 3 - RAP92077 (10.540" STROKE) - REPLACES AP37881 TUBE KIT _____ ITEM 2 - RAP92079 - REPLACES AP38267 HOSE ASSEMBLIES _____ ITEM 4 - RAP90872 (AP24632) ITEM 5 - RAP91421 (AP24818)</p>
MECHANISM AP41437 AP41438	<p>DUAL CYLINDER ROOM EXTENSION - 43.5" STROKE (WITH SYNCHRONIZING CYLINDER) - AP41436 KIT</p> <p>SEE MR41.2000 FOR DRAWING AND PARTS INFORMATION.</p> <p>CYLINDER ASSEMBLY _____ ITEM 1 - RAP92499 (44.5" STROKE) - REPLACES AP40624 SYNCHRONIZING CYLINDER _____ ITEM 3 - RAP92500 (17.795" STROKE) - REPLACES AP40571 TUBE ASSEMBLIES _____ ITEM 2 - RAP90481 - REPLACES AP15379</p>
MECHANISM AP45559 AP45560	<p>DUAL CYLINDER ROOM EXTENSION - 30.0" STROKE (WITH SYNCHRONIZING CYLINDER) - AP45558 KIT</p> <p>SEE MR41.2000 FOR DRAWING AND PARTS INFORMATION.</p> <p>CYLINDER ASSEMBLY _____ ITEM 1 - RAP92920 (31.0" STROKE) - REPLACES AP45561 SYNCHRONIZING CYLINDER _____ ITEM 3 - RAP92077 (10.540" STROKE) - REPLACES AP37881 TUBE KIT _____ ITEM 2 - RAP90481 - REPLACES AP15379</p>
MECHANISM AP45905 AP45906	<p>DUAL CYLINDER ROOM EXTENSION - 18.0" STROKE (WITH SYNCHRONIZING CYLINDER) - AP45882 KIT</p> <p>SEE MR41.2005 FOR DRAWING AND PARTS INFORMATION.</p> <p>CYLINDER ASSEMBLY _____ ITEM 1 - RAP92921 (23.875" STROKE) - REPLACES AP45903 SYNCHRONIZING CYLINDER _____ ITEM 3 - RAP92369 (6.300" STROKE) - REPLACES AP39267 TUBE KIT _____ ITEM 2 - RAP90480 - REPLACES AP13252</p>
MECHANISM AP47442 AP47443	<p>DUAL CYLINDER ROOM EXTENSION - 20.0" STROKE (WITH SYNCHRONIZING CYLINDER) - AP47441 KIT</p> <p>SEE MR41.2005 FOR DRAWING AND PARTS INFORMATION.</p> <p>CYLINDER ASSEMBLY _____ ITEM 1 - RAP92922 (25.875" STROKE) - REPLACES AP47464 SYNCHRONIZING CYLINDER _____ ITEM 3 - RAP92099 (7.010" STROKE) - REPLACES AP39221 TUBE KIT _____ ITEM 2 - RAP90480 - REPLACES AP13252</p>
MECHANISM AP50953 AP50954	<p>DUAL CYLINDER ROOM EXTENSION - 30.0" STROKE (WITH SYNCHRONIZING CYLINDER) - AP50952 KIT</p> <p>SEE MR41.2011 FOR DRAWING AND PARTS INFORMATION.</p> <p>CYLINDER ASSEMBLY _____ ITEM 1 - RAP91239 (45.0" STROKE) - REPLACES AP24107 SYNCHRONIZING CYLINDER _____ ITEM 3 - RAP92077 (10.540" STROKE) - REPLACES AP37881 TUBE ASSEMBLIES _____ ITEM 2 - RAP90481 - REPLACES AP15379</p>