ROOM EXTENSION ASSEMBLIES
GUIDE PAGE
"HWH - GENERIC"

PROCEDURE:

1. Locate the HWH identification tag on the room extension mechanism to get the correct room extension part number.

2. Find the correct room extension part number in the left column below.

3. Refer to the proper parts page for general replacement parts information and item number arrangements.

4. Two cylinder room extensions with a synchronizing cylinder have two room extension part numbers. One number is for the left assembly, one is for the right assembly. If the room extension assembly originally had one number, that number is listed with the new numbers.

MECHANISM AP10265	**DUAL CYLINDER ROOM EXTENSION - 34.0" STROKE - AP10754 KIT**
	CYLINDER ASSEMBLY _____ AP2113 - CONTACT HWH CORPORATION FOR REPLACEMENT
MECHANISM AP12228	**DUAL CYLINDER ROOM EXTENSION - 39.0" STROKE (WITH RACK SENSING VALVE) - AP12227 KIT**
	SEE MR41.1536 FOR DRAWING AND PARTS INFORMATION. **CYLINDER ASSEMBLY** _____ ITEM 1 - RAP90007 (39.0" STROKE) - REPLACES AP1700 **HOSE ASSEMBLIES** _____ ITEM 7 - RAP4073 (AP4073) ITEM 9 - RAP90215 (AP10912) ITEM 8 - RAP90003 (AP2446) ITEM 10 - RAP90126 (AP10913)
MECHANISM AP15190	**CYLINDER ASSEMBLY - 21.0" STROKE - REPLACED BY AP30188**
	CYLINDER ASSEMBLY _____ RAP90512 (21.0" STROKE) - REPLACES AP15190
MECHANISM AP17326	**CYLINDER ASSEMBLY - 29.67" STROKE**
	CYLINDER ASSEMBLY _____ RAP92497 (29.67" STROKE) - REPLACES AP17326
MECHANISM AP24705	**SINGLE CYLINDER ROOM EXTENSION - 30.0" STROKE - AP24704 KIT**
	SEE MR41.1100 FOR DRAWING AND PARTS INFORMATION. **CYLINDER ASSEMBLY** _____ ITEM 1 - RAP90949 (31.0" STROKE) - REPLACES AP28727 **HOSE ASSEMBLIES** ITEM 3 - RAP90872 (AP24632) ITEM 4 - RAP90871 (AP24628)
MECHANISM AP28685	**CYLINDER ASSEMBLY - 30.25" STROKE**
	CYLINDER ASSEMBLY _____ CONTACT HWH CORPORATION FOR REPLACEMENT
MECHANISM AP38251 AP38252	**UNIVERSAL STRAIGHT OUT - 30.0" STROKE (WITH SYNC. CYLINDER) - AP39558 AND AP44013 KIT**
	SEE MR41.2685 FOR DRAWING AND PARTS INFORMATION. **CYLINDER ASSEMBLY** _____ ITEM 1 - RAP92076 (30.5" STROKE) - REPLACES AP38072 **SYNCHRONIZING CYLINDER** _____ ITEM 3 - RAP92077 (10.540" STROKE) - REPLACES AP37881 **TUBE KIT** _____ ITEM 2 - RAP92079 - REPLACES AP38267 **HOSE ASSEMBLIES** _____ ITEM 4 - RAP90872 (AP24632) ITEM 5 - RAP91421 (AP24818)
MECHANISM AP44925	**SADDLE RACK ASSEMBLY - AP45615 KIT**
	CYLINDER ASSEMBLY _____ RAP93339 (19.825" STROKE) - REPLACES AP46851 **HOSE ASSEMBLIES** _____ RAP93341 (AP46694) RAP93342 (AP24637)