OEM Guide Page
HWH SpaceMaker Equipment for MCL Vehicles

(File: MR403960.DOC | Revised: 18APR17)

> Printable PDF File

PROCEDURE:

1. Locate the HWH identification tag on the SpaceMaker mechanism to get the correct mechanism part number.
2. Find the correct SpaceMaker mechanism part number in the left column below.
3. Refer to the listed HWH Parts Manual Page for general replacement parts information and item number arrangements.
4. Note that two-cylinder mechanisms with a synchronizing cylinder have two part numbers. One number is for the left assembly and one is for the right assembly. If the mechanism assembly originally had one number, that number is listed with the new numbers.

SLIDE-OUT Mechanisms	
MECHANISM *AP35182* *AP35183*	**X-SLIDE ROOM EXTENSION – 25.0" STROKE (WITH SYNCHRONIZING CYLINDER)** **AP35188 KIT** **SEE > MR412670.HTML FOR DRAWING AND PARTS INFORMATION.** CYLINDER ASSEMBLY_____ ITEM 1 – RAP91350 (11.40″ STROKE) REPLACES AP27865 SYNCHRONIZING CYLINDER_____ ITEM 3 – RAP91701 (4.300″ STROKE) REPLACES AP30260 TUBE KIT_____ ITEM 2 – RAP91229 – REPLACES AP27587 HOSE ASSEMBLIES_____ ITEM 4 – RAP24627 (AP24627) ITEM 5 – RAP24627 (AP24627)
MECHANISM *AP39529* *AP39530*	**X-SLIDE ROOM EXTENSION – 30.75" STROKE (WITH SYNCHRONIZING CYLINDER)** **AP37895 KIT** **SEE > MR412670.HTML FOR DRAWING AND PARTS INFORMATION.** CYLINDER ASSEMBLY_____ ITEM 1 – RAP91352 (13.90″ STROKE) REPLACES AP27513 SYNCHRONIZING CYLINDER_____ ITEM 3 – RAP90725 (5.460″ STROKE) REPLACES AP15043 TUBE KIT_____ ITEM 2 – RAP91229 – REPLACES AP27587 HOSE ASSEMBLIES_____ ITEM 4 – RAP24627 (AP24627) ITEM 5 – RAP24627 (AP24627)