OEM Guide Page
HWH SpaceMaker Equipment for PACLIGHT ELECTRONICS Vehicles

(File: MR405390.DOC | Revised: 20APR17)

> Printable PDF File

PROCEDURE:

1. Locate the HWH identification tag on the SpaceMaker mechanism to get the correct mechanism part number.
2. Find the correct SpaceMaker mechanism part number in the left column below.
3. Refer to the listed HWH Parts Manual Page for general replacement parts information and item number arrangements.
4. Note that two-cylinder mechanisms with a synchronizing cylinder have two part numbers. One number is for the left assembly and one is for the right assembly. If the mechanism assembly originally had one number, that number is listed with the new numbers.

SLIDE-OUT Mechanisms	
MECHANISM *AP19309* *AP19310*	**DUAL CYLINDER ROOM EXTENSION – 48.0" STROKE (WITH SYNCHRONIZING CYLINDER) AP39729 KIT** **SEE > MR412000.HTML FOR DRAWING AND PARTS INFORMATION.** CYLINDER ASSEMBLY_____ ITEM 1 – RAP90479 (49.0″ STROKE) REPLACES AP15317 SYNCHRONIZING CYLINDER_____ ITEM 3 – RAP90462 (19.575″ STROKE) REPLACES AP14500 TUBE KIT_____ ITEM 2 – RAP90481 – REPLACES AP15379
MECHANISM *AP23213*	**CYLINDER KIT – 36.0" STROKE (WITH SYNCHRONIZING CYLINDER) – AP43237 KIT** CYLINDER ASSEMBLY_____ RAP90696 (36.0″ STROKE)- REPLACES AP19256 SYNCHRONIZING CYLINDER_____ RAP90474 (14.630″STROKE)-REPLACES AP12484
MECHANISM *AP35844*	**CYLINDER KIT – 34.0" STROKE (WITH SYNCHRONIZING CYLINDER) – AP35850 KIT** CYLINDER ASSEMBLY_____ RAP92541 (34.0″ STROKE)- REPLACES AP35855 SYNCHRONIZING CYLINDER_____ RAP90664 (13.910″STROKE)-REPLACES AP19186