OEM Guide Page
HWH SpaceMaker Equipment for VARIO MOBILE Vehicles

(File: MR408750.DOC | Revised: 09MAY17)

> Printable PDF File

PROCEDURE:

1. Locate the HWH identification tag on the SpaceMaker mechanism to get the correct mechanism part number.
2. Find the correct SpaceMaker mechanism part number in the left column below.
3. Refer to the listed HWH Parts Manual Page for general replacement parts information and item number arrangements.
4. Note that two-cylinder mechanisms with a synchronizing cylinder have two part numbers. One number is for the left assembly and one is for the right assembly. If the mechanism assembly originally had one number, that number is listed with the new numbers.

SLIDE-OUT Mechanisms	
MECHANISM *AP27853* *AP27854*	**X-SLIDE ROOM EXTENSION – 20.0" STROKE (WITH SYNCHRONIZING CYLINDER)** **AP28167 KIT** **SEE > MR412670.HTML FOR DRAWING AND PARTS INFORMATION.** CYLINDER ASSEMBLY_____ ITEM 1 – RAP91208 (9.20″ STROKE) REPLACES AP27862 SYNCHRONIZING CYLINDER_____ ITEM 3 – RAP90587 (3.455″ STROKE) REPLACES AP17199 TUBE ASSEMBLY_____ ITEM 2 – RAP91229 – REPLACES AP27587 HOSE ASSEMBLIES_____ ITEM 4 – RAP24627 (AP24627) ITEM 5 – RAP24627 (AP24627)
MECHANISM *AP33123* *AP33124*	**X-SLIDE ROOM EXTENSION KIT – 18.0" STROKE (WITH SYNCHRONIZING CYLINDER)** **AP33122 KIT** **SEE > MR412670.HTML FOR DRAWING AND PARTS INFORMATION.** CYLINDER ASSEMBLY_____ ITEM 1 – RAP91007 (8.10″ STROKE) REPLACES AP27723 SYNCHRONIZING CYLINDER_____ ITEM 3 – RAP91006 (2.970″ STROKE) REPLACES AP27302 TUBE ASSEMBLY_____ ITEM 2 – RAP91229 – REPLACES AP27587 HOSE ASSEMBLIES_____ ITEM 4 – RAP24627 (AP24627) ITEM 5 – RAP24627 (AP24627)
MECHANISM *AP37665*	**SINGLE CYLINDER ROOM EXTENSION – 18.0" STROKE – AP37664 KIT** **SEE > MR411100.HTML FOR DRAWING AND PARTS INFORMATION.** CYLINDER ASSEMBLY_____ ITEM 1 – RAP91667 (28.5″ STROKE) REPLACES AP28688 HOSE ASSEMBLIES_____ ITEM 3 – RAP50907 (AP50907) ITEM 4 – RAP16434 (AP16434)