OEM Guide Page
HWH SpaceMaker Equipment for MIDWEST MOBILE TECH. INC. Vehicles

(File: MR404000.DOC | Revised: 18APR17)

> Printable PDF File

PROCEDURE:

1. Locate the HWH identification tag on the SpaceMaker mechanism to get the correct mechanism part number.
2. Find the correct SpaceMaker mechanism part number in the left column below.
3. Refer to the listed HWH Parts Manual Page for general replacement parts information and item number arrangements.
4. Note that two-cylinder mechanisms with a synchronizing cylinder have two part numbers. One number is for the left assembly and one is for the right assembly. If the mechanism assembly originally had one number, that number is listed with the new numbers.

SLIDE-OUT Mechanisms	
MECHANISM *AP12300*	**DUAL CYLINDER ROOM EXTENSION – 73.0" STROKE (WITH RACK SENSING VALVE)** **AP12299 KIT** **SEE > MR411532.HTML FOR DRAWING AND PARTS INFORMATION.** CYLINDER ASSEMBLY_____ ITEM 1 – RAP90115 (73.0″ STROKE) REPLACES AP1662 HOSE ASSEMBLIES_____ ITEM 6 – RAP5352 (AP5352) ITEM 7 – RAP2446 (AP2446) ITEM 8 – RAP6115 (AP6115) ITEM 9 – RAP6216 (AP6216)
MECHANISM *AP25250* *AP25251*	**DUAL CYLINDER ROOM EXTENSION – 60.0" STROKE (WITH SYNCHRONIZING CYLINDER)** **AP25249 KIT** **SEE > MR412006.HTML FOR DRAWING AND PARTS INFORMATION.** CYLINDER ASSEMBLY_____ ITEM 1 – RAP91191 (61.0″ STROKE) REPLACES AP20586 SYNCHRONIZING CYLINDER_____ ITEM 3 – RAP91233 (23.10″ STROKE) REPLACES AP19966 TUBE KIT_____ ITEM 2 – RAP91221 – REPLACES AP17321
MECHANISM *AP25828* *AP25829*	**DUAL CYLINDER ROOM EXTENSION - 24.0" STROKE (WITH SYNCHRONIZING CYLINDER)** **AP25827 KIT** **SEE > MR412005.HTML FOR DRAWING AND PARTS INFORMATION.** CYLINDER ASSEMBLY_____ ITEM 1 – RAP90484 (24.5″ STROKE) REPLACES AP15252 SYNCHRONIZING CYLINDER_____ ITEM 3 – RAP90472 (9.685″ STROKE) REPLACES AP13224 TUBE KIT_____ ITEM 2 – RAP90480 – REPLACES AP13252