# ROOM EXTENSION ASSEMBLIES
# GUIDE PAGE
# "REXHALL EAST"

**PROCEDURE:**

1. Locate the HWH identification tag on the room extension mechanism to get the correct room extension part number.

2. Find the correct room extension part number in the left column below.

3. Refer to the proper parts page for general replacement parts information and item number arrangements.

4. Two cylinder room extensions with a synchronizing cylinder have two room extension part numbers. One number is for the left assembly, one is for the right assembly. If the room extension assembly originally had one number, that number is listed with the new numbers.

| | |
|---|---|
| **MECHANISM AP11433** | **DUAL CYLINDER ROOM EXTENSION - 39.0" STROKE (WITH RACK SENSING VALVE) - AP11434 KIT**<br>**SEE MR41.1536 FOR DRAWING AND PARTS INFORMATION.**<br>**CYLINDER ASSEMBLY** _____ ITEM 1 - RAP90007 (39.0" STROKE) - REPLACES AP1700<br>**HOSE ASSEMBLIES** _____ ITEM 7 - RAP4159 (AP4159) ITEM 9 - RAP4827 (AP4827)<br>ITEM 8 - RAP90110 (AP2522) ITEM 10 - RAP90119 (AP11212) |
| **MECHANISM AP13572** | **SINGLE CYLINDER ROOM EXTENSION - 25.0" STROKE - AP13571 KIT**<br>**SEE MR41.1000 FOR DRAWING AND PARTS INFORMATION.**<br>**CYLINDER ASSEMBLY** _____ ITEM 1 - RAP90031 (25.0" STROKE) - REPLACES AP1911<br>**TUBE KIT** _____ ITEM 2 - RAP90029 - REPLACES AP2369 |
| **MECHANISM AP13908** | **DUAL CYLINDER ROOM EXTENSION - 39.0" STROKE (WITH RACK SENSING VALVE) - AP13907 KIT**<br>**SEE MR41.1536 FOR DRAWING AND PARTS INFORMATION.**<br>**CYLINDER ASSEMBLY** _____ ITEM 1 - RAP90112 (39.0" STROKE) - REPLACES AP11105<br>**HOSE ASSEMBLIES** _____ ITEM 7 - RAP4159 (AP4159) ITEM 9 - RAP4827 (AP4827)<br>ITEM 8 - RAP90110 (AP2522) ITEM 10 - RAP90119 (AP11212) |
| **MECHANISM AP19251 AP19252** | **DUAL CYLINDER ROOM EXTENSION - 41.5" STROKE (WITH SYNCHRONIZING CYLINDER) - AP15211 KIT**<br>**SEE MR41.2015 FOR DRAWING AND PARTS INFORMATION.**<br>**CYLINDER ASSEMBLY** _____ ITEM 1 - RAP90488 (35.0" STROKE) - REPLACES AP15224<br>**SYNCHRONIZING CYLINDER** _____ ITEM 3 - RAP90464 (14.01" STROKE) - REPLACES AP14368<br>**TUBE KIT** _____ ITEM 2 - RAP90480 - REPLACES AP13252 |
| **MECHANISM AP19257 AP19258** | **DUAL CYLINDER ROOM EXTENSION - 25.0" STROKE (WITH SYNCHRONIZING CYLINDER) - AP16496 KIT**<br>**SEE MR41.2015 FOR DRAWING AND PARTS INFORMATION.**<br>**CYLINDER ASSEMBLY** _____ ITEM 1 - RAP90488 (35.0" STROKE) - REPLACES AP15224<br>**SYNCHRONIZING CYLINDER** _____ ITEM 3 - RAP90440 (10.095" STROKE) - REPLACES AP16509<br>**TUBE KIT** _____ ITEM 2 - RAP90480 - REPLACES AP13252 |