OEM Guide Page
HWH SpaceMaker Equipment for ROADMASTER CUSTOM MOTOR COACH Vehicles

(File: MR406100.DOC | Revised: 24APR17)

> Printable PDF File

PROCEDURE:

1. Locate the HWH identification tag on the SpaceMaker mechanism to get the correct mechanism part number.
2. Find the correct SpaceMaker mechanism part number in the left column below.
3. Refer to the listed HWH Parts Manual Page for general replacement parts information and item number arrangements.
4. Note that two-cylinder mechanisms with a synchronizing cylinder have two part numbers. One number is for the left assembly and one is for the right assembly. If the mechanism assembly originally had one number, that number is listed with the new numbers.

SLIDE-OUT Mechanisms	
MECHANISM *AP25730* *AP25731*	VERTICAL ARM ROOM EXTENSION **– 24.0" STROKE (WITH SYNCHRONIZING CYLINDER)** **AP25729 KIT** **SEE >** MR412500.HTML **FOR DRAWING AND PARTS INFORMATION.** CYLINDER ASSEMBLY_____ ITEM 1 – RAP91200 (10.172″ STROKE) REPLACES AP24733 SYNCHRONIZING CYLINDER_____ ITEM 6 – RAP91019 (3.935″ STROKE) REPLACES AP13180 TUBE KIT_____ RAP91224–REPLACES AP23196 HOSE ASSEMBLIES_____ ITEM 4 – RAP24643 (AP24643) ITEM 5 – RAP24647 (AP24647)
MECHANISM *AP32458* *AP32459*	LATERAL ARM ROOM EXTENSION **– 20.0" STROKE (WITH SYNCHRONIZING CYLINDER)** **AP32457 KIT** **SEE >** MR412825.HTML **FOR DRAWING AND PARTS INFORMATION.** CYLINDER ASSEMBLY_____ ITEM 1 – RAP91351 (6.775″ STROKE) REPLACES AP27997 SYNCHRONIZING CYLINDER_____ ITEM 3 – RAP90524 (2.385″ STROKE) REPLACES AP14881 TUBE KIT_____ ITEM 2 – RAP91774 – REPLACES AP28035 HOSE ASSEMBLIES_____ ITEM 4 – RAP24627 (AP24627) ITEM 5 – RAP24627 (AP24627)
MECHANISM *AP32572* *AP32573*	UNIVERSAL SLIDE OUT ROOM EXTENSION **– 25.0" STROKE (WITH SYNC. CYLINDER)** **AP32571 KIT** **SEE >** MR412680.HTML **FOR DRAWING AND PARTS INFORMATION.** CYLINDER ASSEMBLY_____ ITEM 1 – RAP91702 (34.0″ STROKE) REPLACES AP31461 SYNCHRONIZING CYLINDER_____ ITEM 3 – RAP90440 (10.095″ STROKE) REPLACES AP16509 TUBE KIT_____ ITEM 2 – RAP91703 – REPLACES AP31486 HOSE ASSEMBLIES_____ ITEM 4 – RAP24638 (AP24638) ITEM 5 – RAP24632 (AP24632)