ROOM EXTENSION ASSEMBLIES
GUIDE PAGE
"ROGUE COACH CONVERTERS"

PROCEDURE:

1. Locate the HWH identification tag on the room extension mechanism to get the correct room extension part number.

2. Find the correct room extension part number in the left column below.

3. Refer to the proper parts page for general replacement parts information and item number arrangements.

4. Two cylinder room extensions with a synchronizing cylinder have two room extension part numbers. One numberis for the left assembly, one is for the right assembly. If the room extension assembly originally had one number, that number is listed with the new numbers.

MECHANISM AP10137	**DUAL CYLINDER ROOM EXTENSION - 37.0" STROKE (WITH RACK SENSING VALVE) - AP10145 KIT**
	SEE MR41.1534 FOR DRAWING AND PARTS INFORMATION. **CYLINDER ASSEMBLY** _____ ITEM 1 - RAP90069 (37.0" STROKE) - REPLACES AP2340 **HOSE ASSEMBLIES** _____ ITEM 7 - RAP4073 (AP4073) ITEM 9 - RAP4074 (AP4074) ITEM 8 - RAP90003 (AP2446) ITEM 10 - RAP90078 (AP4065)
MECHANISM AP11399	**SINGLE CYLINDER ROOM EXTENSION - 24.0" STROKE - AP11565 KIT**
	SEE MR41.1005 FOR DRAWING AND PARTS INFORMATION. **CYLINDER ASSEMBLY** _____ ITEM 1 - RAP90355 (24.4" STROKE) - REPLACES AP11400 **HOSE ASSEMBLIES** _____ ITEM 4 - RAP4059 (AP4059) ITEM 5 - RAP90356 (AP5351)
MECHANISM AP11405	**CYLINDER ASSEMBLY - 80.0" STROKE**
	CYLINDER ASSEMBLY _____ RAP90655 (80.0" STROKE) - REPLACES AP11405
MECHANISM AP11447	**DUAL CYLINDER ROOM EXTENSION - 36.0" STROKE (WITH RACK SENSING VALVE) - AP11448 AND AP11565 KITS**
	SEE MR40.1534 FOR DRAWING AND PARTS INFORMATION. **CYLINDER ASSEMBLY** _____ ITEM 1 - RAP90112 (39.0" STROKE) - REPLACES AP11105 **HOSE ASSEMBLIES** _____ ITEM 7 - RAP90353 (AP4728) ITEM 9 - RAP4074 (AP4074) ITEM 8 - RAP90347 (AP11560) ITEM 10 - RAP90078 (AP4065)
MECHANISM AP13149	**DUAL CYLINDER ROOM EXTENSION - 36.0" STROKE (WITH RACK SENSING VALVE) - AP13148 KIT**
	SEE MR41.1536 FOR DRAWING AND PARTS INFORMATION. **CYLINDER ASSEMBLY** _____ ITEM 1 - RAP90112 (39.0" STROKE) - REPLACES AP11105 **HOSE ASSEMBLIES** _____ ITEM 7 - RAP90353 (AP4728) ITEM 9 - RAP4074 (AP4074) ITEM 8 - RAP90347 (AP11560) ITEM 10 - RAP90078 (AP4065)
MECHANISM AP13309	**COMPARTMENT DOOR ADD ON KIT - 24.0" STROKE - AP12622 KIT**
	CYLINDER ASSEMBLY _____ RAP90900 (24.0" STROKE) - REPLACES AP13309
MECHANISM AP18902	**SINGLE CYLINDER ROOM EXTENSION - 24.0" STROKE - AP18901 KIT**
	SEE MR41.1100 FOR DRAWING AND PARTS INFORMATION. **CYLINDER ASSEMBLY** _____ ITEM 1 - RAP91021 (27.0" STROKE) - REPLACES AP28682 **HOSE ASSEMBLIES** _____ ITEM 3 - RAP91750 (AP13842) ITEM 4 - RAP91751 (AP16434)
MECHANISM AP18908 AP18909	**DUAL CYLINDER ROOM EXTENSION - 32.0" STROKE (WITH SYNCHRONIZING CYLINDER) - AP18907 KIT**
	SEE MR41.2005 FOR DRAWING AND PARTS INFORMATION. **CYLINDER ASSEMBLY** _____ ITEM 1 - RAP90665 (32.5" STROKE) - REPLACES AP18131 **SYNCHRONIZING CYLINDER** _____ ITEM 3 - RAP90466 (12.980" STROKE) - REPLACES AP14301 **TUBE KIT** _____ ITEM 2 - RAP90480 - REPLACES AP13252
MECHANISM AP18911 AP18912	**DUAL CYLINDER FLAT FLOOR ROOM EXTENSION - 32.0" STROKE (WITH SYNC. CYLINDER) - AP18910 KIT**
	SEE MR41.2200 FOR DRAWING AND PARTS INFORMATION. **CYLINDER ASSEMBLY** _____ ITEM 1 - RAP90696 (36.0" STROKE) - REPLACES AP19256 **SYNCHRONIZING CYLINDER** _____ ITEM 3 - RAP90466 (12.980" STROKE) - REPLACES AP14301 **HOSE ASSEMBLIES** _____ ITEM 2 - RAP91561 - REPLACES AP24648
MECHANISM AP21465	**CYLINDER ASSEMBLY - 45.4" STROKE**
	CYLINDER ASSEMBLY _____ AP21465 (45.4" STROKE) - CONTACT HWH CORPORATION
MECHANISM AP21467	**CYLINDER ASSEMBLY - 40.0" STROKE**
	CYLINDER ASSEMBLY _____ AP21467 (40.0" STROKE) - CONTACT HWH CORPORATION