OEM Guide Page
HWH SpaceMaker Equipment for SUNDANCE COACH Vehicles

(File: MR407100.DOC | Revised: 26APR17)

> Printable PDF File

PROCEDURE:

1. Locate the HWH identification tag on the SpaceMaker mechanism to get the correct mechanism part number.
2. Find the correct SpaceMaker mechanism part number in the left column below.
3. Refer to the listed HWH Parts Manual Page for general replacement parts information and item number arrangements.
4. Note that two-cylinder mechanisms with a synchronizing cylinder have two part numbers. One number is for the left assembly and one is for the right assembly. If the mechanism assembly originally had one number, that number is listed with the new numbers.

SLIDE-OUT Mechanisms	
MECHANISM *AP15770* *OR* *AP19305* *AP19306*	**DUAL CYLINDER ROOM EXTENSION – 36.0" STROKE (WITH SYNCHRONIZING CYLINDER)** **AP15769 KIT** **SEE > MR412000.HTML FOR DRAWING AND PARTS INFORMATION.** CYLINDER ASSEMBLY_____ ITEM 1 – RAP90518 (36.5″ STROKE) REPLACES AP15251 SYNCHRONIZING CYLINDER_____ ITEM 3 – RAP90474 (14.63″ STROKE) REPLACES AP12484 TUBE KIT_____ ITEM 2 – RAP90480 – REPLACES AP13252
MECHANISM *AP17019* *OR* *AP19313* *AP19314*	**DUAL CYLINDER ROOM EXTENSION – 24.0" STROKE (WITH SYNCHRONIZING CYLINDER)** **AP17018 KIT** **SEE > MR412005.HTML FOR DRAWING AND PARTS INFORMATION.** CYLINDER ASSEMBLY_____ ITEM 1 – RAP90484 (24.5″ STROKE) REPLACES AP15252 SYNCHRONIZING CYLINDER_____ ITEM 3 – RAP90472 (9.685″ STROKE) REPLACES AP13224 TUBE KIT_____ ITEM 2 – RAP90480 – REPLACES AP13252
MECHANISM *AP22862*	**SINGLE CYLINDER ROOM EXTENSION – 18.0" STROKE – AP22861 KIT** **SEE > MR411100.HTML FOR DRAWING AND PARTS INFORMATION.** CYLINDER ASSEMBLY_____ ITEM 1 – RAP91021 (27.0″ STROKE) REPLACES AP28682 HOSE ASSEMBLIES_____ ITEM 3 – RAP24632 (AP24632) ITEM 4 – RAP53984 (AP53984)
MECHANISM *AP23091*	**SINGLE CYLINDER ROOM EXTENSION – 24.0" STROKE – AP23090 KIT** **SEE > MR411100.HTML FOR DRAWING AND PARTS INFORMATION.** CYLINDER ASSEMBLY_____ ITEM 1 – RAP91021 (27.0″ STROKE) REPLACES AP28682 HOSE ASSEMBLIES_____ ITEM 3 – RAP24632 (AP24632) ITEM 4 – RAP53984 (AP53984)
MECHANISM *AP25194* *AP25195*	**VERTICAL ARM ROOM EXTENSION – 24.0" STROKE (WITH SYNCHRONIZING CYLINDER)** **AP25193 KIT** **SEE > MR412505.HTML FOR DRAWING AND PARTS INFORMATION.** CYLINDER ASSEMBLY_____ ITEM 1 – RAP91201 (10.172″ STROKE) REPLACES AP25030 SYNCHRONIZING CYLINDER_____ ITEM 6 – RAP91019 (3.935″ STROKE) REPLACES AP13180 HOSE ASSEMBLIES_____ ITEM 4 – RAP24643 (AP24643) ITEM 5 – RAP24647 (AP24647)