OEM Guide Page
HWH SpaceMaker Equipment for TESCHNER MOTORHOMES MFG. Vehicles

(File: MR407400.DOC | Revised: 26APR17)

> Printable PDF File

PROCEDURE:

1. Locate the HWH identification tag on the SpaceMaker mechanism to get the correct mechanism part number.
2. Find the correct SpaceMaker mechanism part number in the left column below.
3. Refer to the listed HWH Parts Manual Page for general replacement parts information and item number arrangements.
4. Note that two-cylinder mechanisms with a synchronizing cylinder have two part numbers. One number is for the left assembly and one is for the right assembly. If the mechanism assembly originally had one number, that number is listed with the new numbers.

SLIDE-OUT Mechanisms	
MECHANISM *AP30055*	SINGLE CYLINDER ROOM EXTENSION **– 30.0" STROKE – AP30054 KIT** **SEE > MR411100.HTML FOR DRAWING AND PARTS INFORMATION.** CYLINDER ASSEMBLY_____ ITEM 1 – RAP91805 (31.0″ STROKE) REPLACES AP28687 HOSE ASSEMBLIES_____ ITEM 4 – RAP53984 (AP53984) ITEM 5 – RAP24632 (AP24632)
MECHANISM *AP36873* *AP36874*	UNIVERSAL STRAIGHT OUT **– 24.0" STROKE (WITH SYNCHRONIZING CYLINDER)** **AP36020 KIT** **SEE > MR412680.HTML FOR DRAWING AND PARTS INFORMATION.** CYLINDER ASSEMBLY_____ ITEM 1 – RAP91702 (34.0″ STROKE) REPLACES AP31461 SYNCHRONIZING CYLINDER_____ ITEM 3 – RAP90472 (9.685″ STROKE) REPLACES AP13224 TUBE KIT_____ ITEM 2 – RAP91703 – REPLACES AP31486 HOSE ASSEMBLIES_____ ITEM 4 – RAP24632 (AP24632) ITEM 5 – RAP24638 (AP24638)