OEM Guide Page
HWH SpaceMaker Equipment for UNIVERSAL SPECIALTY VEHICLES

(File: MR408500.DOC | Revised: 09MAY17)

> Printable PDF File

PROCEDURE:

1. Locate the HWH identification tag on the SpaceMaker mechanism to get the correct mechanism part number.
2. Find the correct SpaceMaker mechanism part number in the left column below.
3. Refer to the listed HWH Parts Manual Page for general replacement parts information and item number arrangements.
4. Note that two-cylinder mechanisms with a synchronizing cylinder have two part numbers. One number is for the left assembly and one is for the right assembly. If the mechanism assembly originally had one number, that number is listed with the new numbers.

SLIDE-OUT Mechanisms	
MECHANISM *AP38251* *AP38252*	**UNIVERSAL STRAIGHT OUT – 30.0" STROKE (WITH SYNCHRONIZING CYLINDER)** **AP41814 KIT** **SEE > MR412685.HTML FOR DRAWING AND PARTS INFORMATION.** CYLINDER ASSEMBLY_____ ITEM 1 – RAP92076 (30.5″ STROKE) REPLACES AP38072 SYNCHRONIZING CYLINDER_____ ITEM 3 – RAP92077 (10.540″ STROKE) REPLACES AP37881 TUBE KIT_____ ITEM 2 – RAP92079 – REPLACES AP38267 HOSE ASSEMBLIES_____ ITEM 4 – RAP24632 (AP24632) ITEM 5 – RAP24638 (AP24638)
MECHANISM *AP38944* *AP38945*	**UNIVERSAL LEVEL OUT – 30.0" STROKE (WITH SYNCHRONIZING CYLINDER)** **AP41813 KIT** **SEE > MR412690.HTML FOR DRAWING AND PARTS INFORMATION.** CYLINDER ASSEMBLY_____ ITEM 1 - RAP92076 (30.5″ STROKE) REPLACES AP38072 LIFT CYLINDER ASSEMBLY_____ ITEM 11 – RAP92260 (2.75″ LIFT) REPLACES AP38604 SYNCHRONIZING CYLINDER_____ ITEM 3 - RAP92077 (10.540″ STROKE) REPLACES AP37881 LIFT SYNCHRONIZING CYLINDER_ ITEM 12 – RAP92316 – REPLACES AP38264 TUBE KIT_____ ITEM 2 - RAP92079 – REPLACES AP38267 HOSE ASSEMBLIES_____ ITEM 4 – RAP24632 (AP24632) ITEM 5 - RAP24638 (AP24638)

STEP Systems	
MECHANISM *AP40595*	**STEP COVER CYLINDER ASSEMBLY – 34.5" STROKE – AP46521 STEP COVER ASSY.** **SEE > MR415000.HTML FOR DRAWING AND PARTS INFORMATION.** CYLINDER ASSEMBLY_____ ITEM 1 – RAP92117 (34.5″ STROKE) REPLACES AP40595 HOSE ASSEMBLY_____ ITEM 2 – RAP4059 (AP4059)