ROOM EXTENSION ASSEMBLIES
GUIDE PAGE
"VAN AMERICA / ROCKWOOD"

PROCEDURE:

1. Locate the HWH identification tag on the room extension mechanism to get the correct room extension part number.

2. Find the correct room extension part number in the left column below.

3. Refer to the proper parts page for general replacement parts information and item number arrangements.

4. Two cylinder room extensions with a synchronizing cylinder have two room extension part numbers. One number is for the left assembly, one is for the right assembly. If the room extension assembly originally had one number, that number is listed with the new numbers.

MECHANISM	DUAL CYLINDER ROOM EXTENSION - 39.0" STROKE (WITH RACK SENSING VALVE) - AP10560 KIT
AP10378	**SEE MR41.1530 FOR DRAWING AND PARTS INFORMATION.** **CYLINDER ASSEMBLY** _____ ITEM 1 - RAP90007 (39.0" STROKE) - REPLACES AP1700 **HOSE ASSEMBLIES** _____ ITEM 7 - RAP4073 (AP4073) ITEM 9 - RAP90001 (AP2445) ITEM 8 - RAP90003 (AP2446) ITEM 10 - RAP90004 (AP2443)