

| | |
|---|---|
| MECHANISM AP13511 AP13512 | VERTICAL ARM ROOM EXTENSION – 20.0” STROKE (WITH SYNCHRONIZING CYLINDER) AP13513 KIT SEE > MR41.2500.HTML FOR DRAWING AND PARTS INFORMATION. CYLINDER ASSEMBLY_____ ITEM 1 - RAP90324 (7.95” STROKE) REPLACES AP11097 SYNCHRONIZING CYLINDER_____ ITEM 6 - RAP90326 (3.165” STROKE) REPLACES AP11360 HOSE ASSEMBLIES_____ ITEM 4 - RAP24651 (AP24651) ITEM 5 - RAP24653 (AP24653) |
| MECHANISM AP14374 | DUAL CYLINDER ROOM EXTENSION – 39.0” STROKE (WITH RACK SENSING VALVE) AP10261 KIT SEE > MR41.1538.HTML FOR DRAWING AND PARTS INFORMATION. CYLINDER ASSEMBLY_____ ITEM 1 - RAP90112 (39.0” STROKE) REPLACES AP11105 HOSE ASSEMBLIES_____ ITEM 7 - RAP4073 (AP4073) ITEM 8 - RAP2446 (AP2446) ITEM 9 - RAP5352 (AP5352) ITEM 10- RAP16172 (AP16172) |
| MECHANISM AP16467 OR AP19262 AP19263 | DUAL CYLINDER ROOM EXTENSION – 32.0” STROKE (WITH SYNCHRONIZING CYLINDER) AP16466 KIT SEE > MR41.2030.HTML FOR DRAWING AND PARTS INFORMATION. CYLINDER ASSEMBLY_____ ITEM 1 - RAP90515 (38.5” STROKE) REPLACES AP16762 SYNCHRONIZING CYLINDER_____ ITEM 3 - RAP90466 (12.98” STROKE) REPLACES AP14301 TUBE KIT_____ ITEM 2 - RAP90480 - REPLACES AP13252 |
| MECHANISM AP16469 OR AP19271 AP19272 | DUAL CYLINDER ROOM EXTENSION – 19.0” STROKE (WITH SYNCHRONIZING CYLINDER) AP16468 KIT SEE > MR41.2030.HTML FOR DRAWING AND PARTS INFORMATION. CYLINDER ASSEMBLY_____ ITEM 1 - RAP90516 (25.5” STROKE) REPLACES AP16760 SYNCHRONIZING CYLINDER_____ ITEM 3 - RAP90441 (7.625” STROKE) REPLACES AP16388 TUBE KIT_____ ITEM 2 - RAP90480 - REPLACES AP13252 |
| MECHANISM AP16672 | SINGLE CYLINDER ROOM EXTENSION – 17.0” STROKE (GUIDED) – AP16671 KIT SEE > MR41.1100.HTML FOR DRAWING AND PARTS INFORMATION. CYLINDER ASSEMBLY_____ ITEM 1 - RAP90688 (27.0” STROKE) REPLACES AP15818 HOSE ASSEMBLIES_____ ITEM 3 - RAP24632 (AP24632) ITEM 4 - RAP53984 (AP53984) |
| MECHANISM AP17295 OR AP19269 AP19270 | DUAL CYLINDER ROOM EXTENSION – 24.0” STROKE (WITH SYNCHRONIZING CYLINDER) AP17294 KIT SEE > MR41.2030.HTML FOR DRAWING AND PARTS INFORMATION. CYLINDER ASSEMBLY_____ ITEM 1 - RAP90629 (30.5” STROKE) REPLACES AP17365 SYNCHRONIZING CYLINDER_____ ITEM 3 - RAP90631 (9.17” STROKE) REPLACES AP19106 TUBE KIT_____ ITEM 2 - RAP90480 - REPLACES AP13252 |
| MECHANISM AP17442 OR AP19264 AP19265 | DUAL CYLINDER ROOM EXTENSION – 17.0” STROKE (WITH SYNC. CYLINDER) AP17441 KIT SEE > MR41.2030.HTML FOR DRAWING AND PARTS INFORMATION. CYLINDER ASSEMBLY_____ ITEM 1 - RAP90633 (23.5” STROKE) REPLACES AP17444 SYNCHRONIZING CYLINDER_____ ITEM 3 - RAP90632 (6.8” STROKE) REPLACES AP17443 TUBE KIT_____ ITEM 2 - RAP90480 - REPLACES AP13252 |

| | |
|--|--|
| MECHANISM AP19146 AP19147 | DUAL CYLINDER ROOM EXTENSION – 22.5” STROKE (WITH SYNCHRONIZING CYLINDER) AP19145 KIT SEE > MR41.2030.HTML FOR DRAWING AND PARTS INFORMATION. CYLINDER ASSEMBLY_____ ITEM 1 - RAP90659 (29.0” STROKE) REPLACES AP19156 SYNCHRONIZING CYLINDER_____ ITEM 3 - RAP90631 (9.17” STROKE) REPLACES AP19106 TUBE KIT_____ ITEM 2 - RAP90480 - REPLACES AP13252 |
| MECHANISM AP19783 AP19784 | VERTICAL ARM ROOM EXTENSION – 17.0” STROKE (WITH SYNCHRONIZING CYLINDER) AP19782 KIT SEE > MR41.2505.HTML FOR DRAWING AND PARTS INFORMATION. CYLINDER ASSEMBLY_____ ITEM 1 - RAP90387 (6.68” STROKE) REPLACES AP14283 SYNCHRONIZING CYLINDER_____ ITEM 6 - RAP90383 (2.565” STROKE) REPLACES AP14281 HOSE ASSEMBLIES_____ ITEM 4 - RAP49438 (AP49438) ITEM 5 - RAP24652 (AP24652) |
| MECHANISM AP19786 | SINGLE CYLINDER ROOM EXTENSION – 17.0” STROKE (GUIDED – LIMIT SWITCHES) AP19785 KIT SEE > MR41.1101.HTML FOR DRAWING AND PARTS INFORMATION. CYLINDER ASSEMBLY_____ ITEM 1 - RAP90818 (28.5” STROKE) REPLACES AP19995 HOSE ASSEMBLIES_____ ITEM 3 - RAP50907 (AP50907) ITEM 4 - RAP16434 (AP16434) |
| KIT NUMBER AP22376 | TRAIN DRIVE ROOM EXTENSION – (4) CYLINDERS – 17.0” STROKE (WITH SYNCHRONIZING CYLINDER) SEE > MR41.2650.HTML FOR DRAWING AND PARTS INFORMATION. CYLINDER ASSEMBLY_____ ITEM 1 - RAP90823 (17.5” STROKE) REPLACES AP21499 SYNCHRONIZING CYLINDER_____ ITEM 5 - RAP90825 (2.40” STROKE) REPLACES AP22187 SEE > MR41.8001.HTML FOR ADD’L SYNC. CYL REPLACEMENT PARTS HOSE ASSEMBLIES_____ ITEM 1A - SPECIAL HOSE-CONTACT HWH ITEM 2 - RAP24671-REPLACES AP24671 (TOP RIGHT) ITEM 2 - RAP24671-REPLACES AP24671 (TOP LEFT) ITEM 2 - RAP24662-REPLACES AP24662 (BOTTOM LEFT) ITEM 2 - RAP24662 REPLACES AP24662 (BOTTOM RIGHT) |
| MECHANISM AP22641 | SINGLE CYLINDER ROOM EXTENSION – 24.0” STROKE (GUIDED) – AP22640 KIT SEE > MR41.1100.HTML FOR DRAWING AND PARTS INFORMATION. CYLINDER ASSEMBLY_____ ITEM 1 - RAP90688 (27.0” STROKE) REPLACES AP15818 HOSE ASSEMBLIES_____ ITEM 3 - RAP24632 (AP24632) ITEM 4 - RAP53984 (AP53984) |
| KIT NUMBER AP23935 | TRAIN DRIVE ROOM EXTENSION – (4) CYLINDERS – 17.0” STROKE (WITH SYNCHRONIZING CYLINDER) SEE > MR41.2650.HTML FOR DRAWING AND PARTS INFORMATION. CYLINDER ASSEMBLY_____ ITEM 1 - RAP90823 (17.5” STROKE) REPLACES AP21499 SYNCHRONIZING CYLINDER_____ ITEM 5 - RAP90825 (2.40” STROKE) REPLACES AP22187 SEE > MR41.8001.HTML FOR ADD’L SYNC. CYL. REPLACEMENT PARTS HOSE ASSEMBLIES_____ ITEM 1A - SPECIAL HOSE-CONTACT HWH ITEM 2 - RAP24662-REPLACES AP24662 (TOP RIGHT) ITEM 2 - RAP24662-REPLACES AP24662 (TOP LEFT) ITEM 2 - RAP24651-REPLACES AP24651 (BOTTOM LEFT) ITEM 2 - RAP24651-REPLACES AP24651 (BOTTOM RIGHT) |

| | |
|---|--|
| MECHANISM AP24353 | SINGLE ELECTRIC ACTUATOR ROOM EXTENSION – 24.0” STROKE – AP25322 KIT SEE > MR41.1105.HTML FOR DRAWING AND PARTS INFORMATION. NOTE: REFER TO COUNTRY COACH FOR ACTUATOR REPLACEMENT AND PARTS. |
| MECHANISM AP25748 AP25749 AP25750 AP25751 | ELECTRIC TRAIN DRIVE ROOM EXTENSION – (4) ACTUATORS – 17.0” STROKE AP25321 KIT SEE > MR41.2651.HTML FOR DRAWING AND PARTS INFORMATION. NOTE: REFER TO COUNTRY COACH FOR ACTUATOR REPLACEMENT AND PARTS. |
| MECHANISM AP25907 AP25908 | DUAL CYLINDER ROOM EXTENSION – 24.0” STROKE (WITH SYNCHRONIZING CYLINDER) AP25898 SEE > MR41.2030.HTML FOR DRAWING AND PARTS INFORMATION. CYLINDER ASSEMBLY_____ ITEM 1 - RAP90629 (30.5” STROKE) REPLACES AP17365 SYNCHRONIZING CYLINDER_____ ITEM 3 - RAP90631 (9.170” STROKE) REPLACES AP19106 TUBE KIT_____ ITEM 2 - RAP90480 - REPLACES AP13252 |
| MECHANISM AP26205 AP26206 | LATERAL ARM ROOM EXTENSION – 20.0” STROKE (WITH TORSION BAR) – AP26204 KIT SEE > MR41.2825.HTML FOR DRAWING AND PARTS INFORMATION. CYLINDER ASSEMBLY_____ ITEM 1 - RAP91351 (6.775” STROKE) REPLACES AP27997 TUBE KIT_____ ITEM 2 - RAP91774 - REPLACES AP28035 HOSE ASSEMBLIES_____ ITEM 4 - RAP24627 (AP24627) ITEM 5 - RAP24627 (AP24627) |
| MECHANISM AP26776 | SINGLE CYLINDER ROOM EXTENSION – 23.0” STROKE – AP26051 KIT SEE > MR41.1100.HTML FOR DRAWING AND PARTS INFORMATION. CYLINDER ASSEMBLY_____ ITEM 1 - RAP91021 (27.0” STROKE) REPLACES AP28682 HOSE ASSEMBLIES_____ ITEM 3 - RAP24634 (AP24634) ITEM 4 - RAP24630 (AP24630) |
| MECHANISM AP27371 AP27372 | DUAL CYLINDER LEVEL OUT ROOM EXTENSION – 32.0” STROKE (WITH SYNC. CYL.) AP26060 KIT SEE > MR41.2200.HTML FOR DRAWING AND PARTS INFORMATION. CYLINDER ASSEMBLY_____ ITEM 1 - RAP91218 (33.0” STROKE) REPLACES AP27375 SYNCHRONIZING CYLINDER_____ ITEM 3 - RAP90466 (12.98” STROKE) REPLACES AP14301 TUBE KIT_____ ITEM 2 - RAP91024 - REPLACES AP26587 |
| MECHANISM AP27856 AP27858 OR AP28459 AP28464 | X-SLIDE ROOM EXTENSION – 20.0” STROKE (WITH SYNCHRONIZING CYLINDER) AP28222 AND AP28880 KIT SEE > MR41.2670.HTML FOR DRAWING AND PARTS INFORMATION. CYLINDER ASSEMBLY_____ ITEM 1 - RAP91208 (9.20” STROKE) REPLACES AP27862 SYNCHRONIZING CYLINDER_____ ITEM 3 - RAP90587 (3.455” STROKE) REPLACES AP17199 TUBE KIT_____ ITEM 2 - RAP91229 - REPLACES AP27587 HOSE ASSEMBLIES_____ ITEM 4 - RAP24627 (AP24627) ITEM 5 - RAP24627 (AP24627) |
| MECHANISM AP27801 | SINGLE CYLINDER GENERATOR EXTENSION – 26.0” STROKE – AP26069 KIT CYLINDER ASSEMBLY_____ RAP91022 (26.5” STROKE)- REPLACES AP27546 TUBE KIT_____ RAP91023 - REPLACES AP27998 |

| | |
|--|--|
| MECHANISM AP28637 AP28638 | DUAL CYLINDER LEVEL OUT ROOM EXTENSION – 32.0” STROKE (WITH SYNCHRONIZING CYLINDER) AP28636 SEE > MR41.2200.HTML FOR DRAWING AND PARTS INFORMATION. CYLINDER ASSEMBLY_____ ITEM 1 - RAP91218 (33.0” STROKE) REPLACES AP27375 SYNCHRONIZING CYLINDER_____ ITEM 3 - RAP90466 (12.980” STROKE) REPLACES AP14301 TUBE KIT_____ ITEM 2 - RAP91024 - REPLACES AP26587 |
| MECHANISM AP29183 AP29184 | X-SLIDE ROOM EXTENSION – 32.0” STROKE (WITH SYNCHRONIZING CYLINDER) AP29289 KIT SEE > MR41.2670.HTML FOR DRAWING AND PARTS INFORMATION. CYLINDER ASSEMBLY_____ ITEM 1 - RAP91210 (14.30” STROKE) REPLACES AP29191 SYNCHRONIZING CYLINDER_____ ITEM 3 - RAP90726 (5.750” STROKE) REPLACES AP15042 TUBE KIT_____ ITEM 2 - RAP91230 - REPLACES AP29192 HOSE ASSEMBLIES_____ ITEM 4 - RAP24627 (AP24627) ITEM 5 - RAP24627 (AP24627) |
| MECHANISM AP30905 AP30906 | LATERAL ARM ROOM EXTENSION – 14.0” STROKE (WITH SYNCHRONIZING CYLINDER) AP30904 KIT SEE > MR41.2825.HTML FOR DRAWING AND PARTS INFORMATION. CYLINDER ASSEMBLY_____ ITEM 1 - RAP91203 (6.150” STROKE) REPLACES AP26255 SYNCHRONIZING CYLINDER_____ ITEM 3 - RAP91754 (1.485” STROKE) REPLACES AP30957 TUBE KIT_____ ITEM 2 - RAP91226 - REPLACES AP27031 HOSE ASSEMBLIES_____ ITEM 4 - RAP24639 (AP24639) ITEM 5 - RAP23738 (AP23738) |
| MECHANISM AP31905 AP31906 | X-SLIDE ROOM EXTENSION – 20.0” STROKE (WITH SYNCHRONIZING CYLINDER) AP31904 KIT SEE > MR41.2670.HTML FOR DRAWING AND PARTS INFORMATION. CYLINDER ASSEMBLY_____ ITEM 1 - RAP91208 (9.20” STROKE) REPLACES AP27862 SYNCHRONIZING CYLINDER_____ ITEM 3 - RAP90587 (3.455” STROKE) REPLACES AP17199 TUBE KIT_____ ITEM 2 - RAP91229 - REPLACES AP27587 HOSE ASSEMBLIES_____ ITEM 4 - RAP24627 (AP24627) ITEM 5 - RAP24627 (AP24627) |
| MECHANISM AP31989 AP31990 | UNIVERSAL SLIDE OUT ROOM EXTENSION – 20.0” STROKE (WITH SYNC. CYLINDER) AP31988 KIT SEE > MR41.2680.HTML FOR DRAWING AND PARTS INFORMATION. CYLINDER ASSEMBLY_____ ITEM 1 - RAP91702 (34.00” STROKE) REPLACES AP31461 SYNCHRONIZING CYLINDER_____ ITEM 3 - RAP90616 (8.240” STROKE) REPLACES AP18122 TUBE KIT_____ ITEM 2 - RAP91703 - REPLACES AP31486 HOSE ASSEMBLIES_____ ITEM 4 - RAP24638 (AP24638) ITEM 5 - RAP24632 (AP24632) |
| MECHANISM AP32065 AP32066 | UNIVERSAL SLIDE OUT ROOM EXTENSION – 29.175” STROKE (WITH SYNC. CYLINDER) AP32064 KIT SEE > MR41.2680.HTML FOR DRAWING AND PARTS INFORMATION. CYLINDER ASSEMBLY_____ ITEM 1 - RAP91760 (36.00” STROKE) REPLACES AP31645 SYNCHRONIZING CYLINDER_____ ITEM 3 - RAP90690 (11.780” STROKE) REPLACES AP17966 TUBE KIT_____ ITEM 2 - RAP92080 - REPLACES AP31651 HOSE ASSEMBLIES_____ ITEM 4 - RAP24641 (AP24641) ITEM 5 - RAP24634 (AP24634) |

| | |
|--|---|
| MECHANISM AP32114 AP32115 | LATERAL ARM ROOM EXTENSION – 14.0” STROKE (WITH SYNCHRONIZING CYLINDER) AP32113 KIT SEE > MR41.2825.HTML FOR DRAWING AND PARTS INFORMATION. CYLINDER ASSEMBLY_____ ITEM 1 - RAP91203 (6.150” STROKE) REPLACES AP26255 SYNCHRONIZING CYLINDER_____ ITEM 3 - RAP91754 (1.485” STROKE) REPLACES AP30957 TUBE KIT_____ ITEM 2 - RAP91226 - REPLACES AP27031 HOSE ASSEMBLIES_____ ITEM 4 - RAP24643 (AP24643) ITEM 5 - RAP24644 (AP24644) |
| MECHANISM AP33316 AP33317 | UNIVERSAL SLIDE OUT ROOM EXTENSION – 24.0” STROKE (WITH SYNC. CYLINDER) AP33652 KIT SEE > MR41.2680.HTML FOR DRAWING AND PARTS INFORMATION. CYLINDER ASSEMBLY_____ ITEM 1 - RAP91702 (34.0” STROKE) REPLACES AP31461 SYNCHRONIZING CYLINDER_____ ITEM 3 - RAP90472 (9.685” STROKE) REPLACES AP13224 TUBE KIT_____ ITEM 2 - RAP91703 - REPLACES AP31486 HOSE ASSEMBLIES_____ ITEM 4 - RAP24632 (AP24632) ITEM 5 - RAP24638 (AP24638) |
| MECHANISM AP33322 AP33323 | UNIVERSAL SLIDE OUT ROOM EXTENSION – 30.0” STROKE (WITH SYNC. CYLINDER) AP33653 KIT SEE > MR41.2680.HTML FOR DRAWING AND PARTS INFORMATION. CYLINDER ASSEMBLY_____ ITEM 1 - RAP91702 (34.0” STROKE) REPLACES AP31461 SYNCHRONIZING CYLINDER_____ ITEM 3 - RAP90473 (12.155” STROKE) REPLACES AP13192 TUBE KIT_____ ITEM 2 - RAP91703 - REPLACES AP31486 HOSE ASSEMBLIES_____ ITEM 4 - RAP24632 (AP24632) ITEM 5 - RAP24638 (AP24638) |
| MECHANISM AP35102 | SINGLE CYLINDER ROOM EXTENSION – 24.0” STROKE – AP35101 KIT SEE > MR41.1100.HTML FOR DRAWING AND PARTS INFORMATION. CYLINDER ASSEMBLY_____ ITEM 1 - RAP91753 (25.0” STROKE) REPLACES AP35069 HOSE ASSEMBLIES_____ ITEM 3 - RAP24632 (AP24632) ITEM 4 - RAP53984 (AP53984) |
| MECHANISM AP35190 AP35191 | UNIVERSAL SLIDE OUT ROOM EXTENSION – 20.0” STROKE (WITH SYNC. CYLINDER) AP40629 KIT SEE > MR41.2680.HTML FOR DRAWING AND PARTS INFORMATION. CYLINDER ASSEMBLY_____ ITEM 1 - RAP91702 (34.0” STROKE) REPLACES AP31461 SYNCHRONIZING CYLINDER_____ ITEM 3 - RAP92099 (7.010” STROKE) REPLACES AP39221 TUBE KIT_____ ITEM 2 - RAP91703 - REPLACES AP31486 HOSE ASSEMBLIES_____ ITEM 4 - RAP24638 (AP24638) ITEM 5 - RAP24632 (AP24632) |
| MECHANISM AP35752 AP35753 | UNIVERSAL SLIDE OUT ROOM EXTENSION - 24.0” STROKE (WITH SYNC. CYLINDER) AP35758 KIT SEE > MR41.2680.HTML FOR DRAWING AND PARTS INFORMATION. CYLINDER ASSEMBLY_____ ITEM 1 - RAP91702 (34.0” STROKE) REPLACES AP31461 SYNCHRONIZING CYLINDER_____ ITEM 3 - RAP90472 (9.685” STROKE) REPLACES AP13224 TUBE KIT_____ ITEM 2 - RAP91703 - REPLACES AP31486 HOSE ASSEMBLIES_____ ITEM 4 - RAP24632 (AP24632) ITEM 5 - RAP24638 (AP24638) |

| | |
|--|---|
| MECHANISM AP36362 AP36363 | UNIVERSAL LEVEL OUT ROOM EXTENSION – 30.0” STROKE (WITH SYNC. CYLINDER) AP36361 KIT SEE > MR41.2683.HTML FOR DRAWING AND PARTS INFORMATION. CYLINDER ASSEMBLY_____ ITEM 1 - RAP91702 (34.0” STROKE) REPLACES AP31461 LIFT CYLINDER ASSEMBLY_____ ITEM 10 - RAP91992 (2.75” LIFT) REPLACES AP34390 SYNCHRONIZING CYLINDER_____ ITEM 3 - RAP90473 (12.155” STROKE) REPLACES AP13192 TUBE KIT_____ ITEM 2 - RAP91703 - REPLACES AP31486 HOSE ASSEMBLIES_____ ITEM 4 - RAP24632 (AP24632) ITEM 5 - RAP24638 (AP24638) LIFT SYNCHRONIZING CYL._____ ITEM 11 - RAP92473 - REPLACES AP34576 CENTER LIFT CYLINDER_____ ITEM 12 - RAP92279 - REPLACES AP35823 |
| MECHANISM AP39962 AP39963 | LATERAL ARM ROOM EXTENSION – 13.0” STROKE (WITH SYNCHRONIZING CYLINDER) AP39944 KIT SEE > MR41.2825.HTML FOR DRAWING AND PARTS INFORMATION. CYLINDER ASSEMBLY_____ ITEM 1 - RAP91203 (6.150” STROKE) REPLACES AP26255 SYNCHRONIZING CYLINDER_____ ITEM 3 - RAP92477 (1.230” STROKE) REPLACES AP40045 TUBE KIT_____ ITEM 2 - RAP91226 - REPLACES AP27031 HOSE ASSEMBLIES_____ ITEM 4 - RAP23738 (AP23738) ITEM 5 - RAP23738 (AP23738) |
| MECHANISM AP42164 | DECK ROOM EXTENSION – 26.0” STROKE (WITH SYNCHRONIZING CYLINDER) AP41980 KIT CYLINDER ASSEMBLY_____ RAP92478 (26.5” STROKE)-REPLACES AP42461 SYNCHRONIZING CYLINDER_____ RAP92469 (9.130” STROKE)-REPLACES AP39275 HOSE ASSEMBLIES_____ RAP23738 (AP23738) RAP25086 (AP25086) MANUAL RETRACT SCREW_____ RAP91643 - REPLACES AP29770 |