

ROOM EXTENSION ASSEMBLIES GUIDE PAGE "COUNTRY COACH" (PAGE 2 OF 5)

PROCEDURE: SEE "COUNTRY COACH" (PAGE 1 OF 5)

MECHANISM AP16469 OR AP19271 AP19272	<p>DUAL CYLINDER ROOM EXTENSION - 19.0" STROKE (WITH SYNCHRONIZING CYLINDER) - AP16468 KIT</p> <p>SEE MR41.2030 FOR DRAWING AND PARTS INFORMATION.</p> <p>CYLINDER ASSEMBLY _____ ITEM 1 - RAP90516 (25.5" STROKE) - REPLACES AP16760 SYNCHRONIZING CYLINDER _____ ITEM 3 - RAP90441 (7.625" STROKE) - REPLACES AP16388 TUBE KIT _____ ITEM 2 - RAP90480 - REPLACES AP13252</p>
MECHANISM AP16672	<p>SINGLE CYLINDER ROOM EXTENSION - 17.0" STROKE (GUIDED) - AP16671 KIT</p> <p>SEE MR41.1100 FOR DRAWING AND PARTS INFORMATION.</p> <p>CYLINDER ASSEMBLY _____ ITEM 1 - RAP90688 (27.0" STROKE) - REPLACES AP15818 HOSE ASSEMBLIES _____ ITEM 3 - RAP90872 (AP24632) _____ ITEM 4 - RAP90871 (AP24628)</p>
MECHANISM AP17295 OR AP19269 AP19270	<p>DUAL CYLINDER ROOM EXTENSION - 24.0" STROKE (WITH SYNCHRONIZING CYLINDER) - AP17294 KIT</p> <p>SEE MR41.2030 FOR DRAWING AND PARTS INFORMATION.</p> <p>CYLINDER ASSEMBLY _____ ITEM 1 - RAP90629 (30.5" STROKE) - REPLACES AP17365 SYNCHRONIZING CYLINDER _____ ITEM 3 - RAP90631 (9.17" STROKE) - REPLACES AP19106 TUBE KIT _____ ITEM 2 - RAP90480 - REPLACES AP13252</p>
MECHANISM AP17442 OR AP19264 AP19265	<p>DUAL CYLINDER ROOM EXTENSION - 17.0" STROKE (WITH SYNCHRONIZING CYLINDER) - AP17441 KIT</p> <p>SEE MR41.2030 FOR DRAWING AND PARTS INFORMATION.</p> <p>CYLINDER ASSEMBLY _____ ITEM 1 - RAP90633 (23.5" STROKE) - REPLACES AP17444 SYNCHRONIZING CYLINDER _____ ITEM 3 - RAP90632 (6.8" STROKE) - REPLACES AP17443 TUBE KIT _____ ITEM 2 - RAP90480 - REPLACES AP13252</p>
MECHANISM AP19146 AP19147	<p>DUAL CYLINDER ROOM EXTENSION - 22.5" STROKE (WITH SYNCHRONIZING CYLINDER) - AP19145 KIT</p> <p>SEE MR41.2030 FOR DRAWING AND PARTS INFORMATION.</p> <p>CYLINDER ASSEMBLY _____ ITEM 1 - RAP90659 (29.0" STROKE) - REPLACES AP19156 SYNCHRONIZING CYLINDER _____ ITEM 3 - RAP90631 (9.17" STROKE) - REPLACES AP19106 TUBE KIT _____ ITEM 2 - RAP90480 - REPLACES AP13252</p>
MECHANISM AP19783 AP19784	<p>VERTICAL ARM ROOM EXTENSION - 17.0" STROKE (WITH SYNCHRONIZING CYLINDER) - AP19782 KIT</p> <p>SEE MR41.2505 FOR DRAWING AND PARTS INFORMATION.</p> <p>CYLINDER ASSEMBLY _____ ITEM 1 - RAP90387 (6.68" STROKE) - REPLACES AP14283 SYNCHRONIZING CYLINDER _____ ITEM 6 - RAP90383 (2.565" STROKE) - REPLACES AP14281 HOSE ASSEMBLIES _____ ITEM 4 - RAP90820 (AP19887) ITEM 5 - RAP90821 (AP24652)</p>
MECHANISM AP19786	<p>SINGLE CYLINDER ROOM EXTENSION - 17.0" STROKE (GUIDED - LIMIT SWITCHES) - AP19785 KIT</p> <p>SEE MR41.1101 FOR DRAWING AND PARTS INFORMATION.</p> <p>CYLINDER ASSEMBLY _____ ITEM 1 - RAP90818 (28.5" STROKE) - REPLACES AP19995 HOSE ASSEMBLIES _____ ITEM 3 - RAP91750 (AP13842) ITEM 4 - RAP91751 (AP16434)</p>
KIT NUMBER AP22376	<p>TRAIN DRIVE ROOM EXTENSION - (4) CYLINDERS - 17.0" STROKE (WITH SYNCHRONIZING CYLINDER)</p> <p>SEE MR41.2650 FOR DRAWING AND PARTS INFORMATION.</p> <p>CYLINDER ASSEMBLY _____ ITEM 1 - RAP90823 (17.5" STROKE) - REPLACES AP21499 SYNCHRONIZING CYLINDER _____ ITEM 5 - RAP90825 (2.40" STROKE) - REPLACES AP22187 SEE MR41.8001 FOR ADDITIONAL SYNC CYL REPLACEMENT PARTS HOSE ASSEMBLIES _____ ITEM 1A - RAP90871 - REPLACES AP24628 HOSE ASSEMBLIES _____ ITEM 2 - RAP91547 - REPLACES AP24671 (TOP RIGHT) HOSE ASSEMBLIES _____ ITEM 2 - RAP91547 - REPLACES AP24671 (TOP LEFT) HOSE ASSEMBLIES _____ ITEM 2 - RAP91535 - REPLACES AP24661 (BOTTOM LEFT) HOSE ASSEMBLIES _____ ITEM 2 - RAP91535 - REPLACES AP24661 (BOTTOM RIGHT)</p>