

ROOM EXTENSION ASSEMBLIES GUIDE PAGE "COUNTRY COACH" (PAGE 3 OF 5)

PROCEDURE: SEE "COUNTRY COACH" (PAGE 1 OF 5)

MECHANISM AP22641	<p>SINGLE CYLINDER ROOM EXTENSION - 24.0" STROKE (GUIDED) - AP22640 KIT</p> <p>SEE MR41.1100 FOR DRAWING AND PARTS INFORMATION. CYLINDER ASSEMBLY _____ ITEM 1 - RAP90688 (27.0" STROKE) - REPLACES AP15818 HOSE ASSEMBLIES _____ ITEM 3 - RAP90872 (AP24632) ITEM 4 - RAP90871 (AP24628)</p>
KIT NUMBER AP23935	<p>TRAIN DRIVE ROOM EXTENSION - (4) CYLINDERS - 17.0" STROKE (WITH SYNCHRONIZING CYLINDER)</p> <p>SEE MR41.2650 FOR DRAWING AND PARTS INFORMATION. CYLINDER ASSEMBLY _____ ITEM 1 - RAP90823 (17.5" STROKE) - REPLACES AP21499 SYNCHRONIZING CYLINDER _____ ITEM 5 - RAP90825 (2.40" STROKE) - REPLACES AP22187 SEE MR41.8001 FOR ADDITIONAL SYNC CYL REPLACEMENT PARTS HOSE ASSEMBLIES _____ ITEM 1A - RAP90871 - REPLACES AP24628 HOSE ASSEMBLIES _____ ITEM 2 - RAP91535 - REPLACES AP24661 (TOP RIGHT) HOSE ASSEMBLIES _____ ITEM 2 - RAP91535 - REPLACES AP24661 (TOP LEFT) HOSE ASSEMBLIES _____ ITEM 2 - RAP90322 - REPLACES AP24651 (BOTTOM LEFT) HOSE ASSEMBLIES _____ ITEM 2 - RAP90322 - REPLACES AP24651 (BOTTOM RIGHT)</p>
MECHANISM AP24353	<p>SINGLE ELECTRIC ACTUATOR ROOM EXTENSION - 24.0" STROKE - AP25322 KIT</p> <p>SEE MR41.1105 FOR DRAWING AND PARTS INFORMATION. NOTE: REFER TO COUNTRY COACH FOR ACTUATOR REPLACEMENT AND PARTS.</p>
MECHANISM AP25748 AP25749 AP25750 AP25751	<p>ELECTRIC TRAIN DRIVE ROOM EXTENSION - (4) ACTUATORS - 17.0" STROKE - AP25321 KIT</p> <p>SEE MR41.2651 FOR DRAWING AND PARTS INFORMATION. NOTE: REFER TO COUNTRY COACH FOR ACTUATOR REPLACEMENT AND PARTS.</p>
MECHANISM AP25907 AP25908	<p>DUAL CYLINDER ROOM EXTENSION - 24.0" STROKE (GUIDED) - AP25898 KIT</p> <p>SEE MR41.2030 FOR DRAWING AND PARTS INFORMATION. CYLINDER ASSEMBLY _____ ITEM 1 - RAP90629 (30.5" STROKE) - REPLACES AP17365 SYNCHRONIZING CYLINDER _____ ITEM 3 - RAP90631 (9.170" STROKE) - REPLACES AP19106 TUBE KIT _____ ITEM 2 - RAP90480 - REPLACES AP13252</p>
MECHANISM AP26205 AP26206	<p>LATERAL ARM ROOM EXTENSION - 20.0" STROKE (WITH TORSION BAR) - AP26204 KIT</p> <p>SEE MR41.2825 FOR DRAWING AND PARTS INFORMATION. CYLINDER ASSEMBLY _____ ITEM 1 - RAP91351 (6.775" STROKE) - REPLACES AP27997 TUBE KIT _____ ITEM 2 - RAP91774 - REPLACES AP28035 HOSE ASSEMBLIES _____ ITEM 4 - RAP91574 (AP24627) ITEM 5 - RAP91573 (AP32672)</p>
MECHANISM AP26776	<p>SINGLE CYLINDER ROOM EXTENSION - 23.0" STROKE - AP26051 KIT</p> <p>SEE MR41.1100 FOR DRAWING AND PARTS INFORMATION. CYLINDER ASSEMBLY _____ ITEM 1 - RAP91021 (27.0" STROKE) - REPLACES AP28682 HOSE ASSEMBLIES _____ ITEM 3 - RAP90320 (AP24634) ITEM 4 - RAP90384 (AP24630)</p>
MECHANISM AP27371 AP27372	<p>DUAL CYLINDER LEVEL OUT ROOM EXTENSION - 32.0" STROKE (GUIDED) - AP26060 KIT</p> <p>SEE MR41.2200 FOR DRAWING AND PARTS INFORMATION. CYLINDER ASSEMBLY _____ ITEM 1 - RAP91218 (33.0" STROKE) REPLACES - AP27375 SYNCHRONIZING CYLINDER _____ ITEM 3 - RAP90466 (12.98" STROKE) REPLACES - AP14301 TUBE KIT _____ ITEM 2 - RAP91024 - REPLACES AP26587</p>
MECHANISM AP27856 AP27858 OR AP28459 AP28464	<p>X-SLIDE ROOM EXTENSION - 20.0" STROKE (WITH SYNCHRONIZING CYLINDER) - AP28222 AND AP28880 KIT</p> <p>SEE MR41.2670 FOR DRAWING AND PARTS INFORMATION. CYLINDER ASSEMBLY _____ ITEM 1 - RAP91208 (9.20" STROKE) REPLACES - AP27862 SYNCHRONIZING CYLINDER _____ ITEM 3 - RAP90587 (3.455" STROKE) REPLACES - AP17199 TUBE KIT _____ ITEM 2 - RAP91229 - REPLACES AP27587 HOSE ASSEMBLIES _____ ITEM 4 - RAP91574 (AP24627) ITEM 5 - RAP91573 (AP32672)</p>