

ROOM EXTENSION ASSEMBLIES GUIDE PAGE "COUNTRY COACH" (PAGE 4 OF 5)

PROCEDURE: SEE "COUNTRY COACH" (PAGE 1 OF 5)

MECHANISM AP27801	<p>SINGLE CYLINDER GENERATOR EXTENSION - 26.0" STROKE - AP26069 KIT</p> <p>CYLINDER ASSEMBLY _____ RAP91022 (26.5" STROKE) - REPLACES AP27546 TUBE KIT _____ RAP91023 - REPLACES AP27998</p>
MECHANISM AP28637 AP28638	<p>DUAL CYLINDER LEVEL OUT ROOM EXTENSION - 32.0" STROKE (WITH SYNC. CYLINDER) - AP28636 KIT</p> <p>SEE MR41.2200 FOR DRAWING AND PARTS INFORMATION. CYLINDER ASSEMBLY _____ ITEM 1 - RAP91218 (33.0" STROKE) - REPLACES AP27375 SYNCHRONIZING CYLINDER _____ ITEM 3 - RAP90466 (12.980" STROKE) - REPLACES AP14301 TUBE KIT _____ ITEM 2 - RAP91024 - REPLACES AP26587</p>
MECHANISM AP29183 AP29184	<p>X-SLIDE ROOM EXTENSION - 32.0" STROKE (WITH SYNCHRONIZING CYLINDER) - AP29289 KIT</p> <p>SEE MR41.2670 FOR DRAWING AND PARTS INFORMATION. CYLINDER ASSEMBLY _____ ITEM 1 - RAP91210 (14.30" STROKE) - REPLACES AP29191 SYNCHRONIZING CYLINDER _____ ITEM 3 - RAP90726 (5.750" STROKE) - REPLACES AP15042 TUBE KIT _____ ITEM 2 - RAP91230 - REPLACES AP29192 HOSE ASSEMBLY _____ ITEM 4 - RAP91574 (AP24627) ITEM 5 - RAP91573 (AP32672)</p>
MECHANISM AP30905 AP30906	<p>LATERAL ARM ROOM EXTENSION - 14.0" STROKE (WITH SYNCHRONIZING CYLINDER) - AP30904 KIT</p> <p>SEE MR41.2825 FOR DRAWING AND PARTS INFORMATION. CYLINDER ASSEMBLY _____ ITEM 1 - RAP91203 (6.150" STROKE) - REPLACES AP26255 SYNCHRONIZING CYLINDER _____ ITEM 3 - RAP91754 (1.485" STROKE) - REPLACES AP30957 TUBE KIT _____ ITEM 2 - RAP91226 - REPLACES AP27031 HOSE ASSEMBLIES _____ ITEM 4 - RAP91417 (AP24639) ITEM 5 - RAP91422 (AP24819)</p>
MECHANISM AP31905 AP31906	<p>X-SLIDE ROOM EXTENSION - 20.0" STROKE (WITH SYNCHRONIZING CYLINDER) - AP31904 KIT</p> <p>SEE MR41.2670 FOR DRAWING AND PARTS INFORMATION. CYLINDER ASSEMBLY _____ ITEM 1 - RAP91208 (9.20" STROKE) - REPLACES AP27862 SYNCHRONIZING CYLINDER _____ ITEM 3 - RAP90587 (3.455" STROKE) - REPLACES AP17199 TUBE KIT _____ ITEM 2 - RAP91229 - REPLACES AP27587 HOSE ASSEMBLIES _____ ITEM 4 - RAP91574 (AP24627) ITEM 5 - RAP91573 (AP32672)</p>
MECHANISM AP31989 AP31990	<p>UNIVERSIAL SLIDE OUT ROOM EXTENSION - 20.0" STROKE (WITH SYNC. CYLINDER) - AP31988 KIT</p> <p>SEE MR41.2680 FOR DRAWING AND PARTS INFORMATION. CYLINDER ASSEMBLY _____ ITEM 1 - RAP91702 (34.00" STROKE) - REPLACES AP31461 SYNCHRONIZING CYLINDER _____ ITEM 3 - RAP90616 (8.240" STROKE) - REPLACES AP18122 TUBE KIT _____ ITEM 2 - RAP91703 - REPLACES AP31486 HOSE ASSEMBLIES _____ ITEM 4 - RAP91421 (AP24818) ITEM 5 - RAP90872 (AP24632)</p>
MECHANISM AP32065 AP32066	<p>UNIVERSIAL SLIDE OUT ROOM EXTENSION - 29.175" STROKE (WITH SYNC. CYLINDER) - AP32064 KIT</p> <p>SEE MR41.2680 FOR DRAWING AND PARTS INFORMATION. CYLINDER ASSEMBLY _____ ITEM 1 - RAP91760 (36.00" STROKE) - REPLACES AP31645 SYNCHRONIZING CYLINDER _____ ITEM 3 - RAP90690 (11.780" STROKE) - REPLACES AP17966 TUBE KIT _____ ITEM 2 - RAP92080 - REPLACES AP31651 HOSE ASSEMBLIES _____ ITEM 4 - RAP91554 (AP24641) ITEM 5 - RAP90320 (AP24634)</p>
MECHANISM AP32114 AP32115	<p>LATERAL ARM ROOM EXTENSION - 14.0" STROKE (WITH SYNCHRONIZING CYLINDER) - AP32113 KIT</p> <p>SEE MR41.2825 FOR DRAWING AND PARTS INFORMATION. CYLINDER ASSEMBLY _____ ITEM 1 - RAP91203 (6.150" STROKE) - REPLACES AP26255 SYNCHRONIZING CYLINDER _____ ITEM 3 - RAP91754 (1.485" STROKE) - REPLACES AP30957 TUBE KIT _____ ITEM 2 - RAP91226 - REPLACES AP27031 HOSE ASSEMBLIES _____ ITEM 4 - RAP90386 (AP24643) ITEM 5 - RAP91555 (AP26472)</p>