

# ROOM EXTENSION ASSEMBLIES GUIDE PAGE "COUNTRY COACH" (PAGE 5 OF 5)

PROCEDURE: SEE "COUNTRY COACH" (PAGE 1 OF 5)

MECHANISM AP33316 AP33317	<b>UNIVERSAL SLIDE OUT ROOM EXTENSION - 24.0" STROKE (WITH SYNC. CYLINDER) - AP33652 KIT</b>  <b>SEE MR41.2680 FOR DRAWING AND PARTS INFORMATION.</b> CYLINDER ASSEMBLY _____ ITEM 1 - RAP91702 (34.0" STROKE) - REPLACES AP31461 SYNCHRONIZING CYLINDER _____ ITEM 3 - RAP90472 (9.685" STROKE) - REPLACES AP13224 TUBE KIT _____ ITEM 2 - RAP91703 - REPLACES AP31486 HOSE ASSEMBLIES _____ ITEM 4 - RAP90872 (AP24632) ITEM 5 - RAP91421 (AP24818)
MECHANISM AP33322 AP33323	<b>UNIVERSAL SLIDE OUT ROOM EXTENSION - 30.0" STROKE (WITH SYNC. CYLINDER) - AP33653 KIT</b>  <b>SEE MR41.2680 FOR DRAWING AND PARTS INFORMATION.</b> CYLINDER ASSEMBLY _____ ITEM 1 - RAP91702 (34.0" STROKE) - REPLACES AP31461 SYNCHRONIZING CYLINDER _____ ITEM 3 - RAP90473 (12.155" STROKE) - REPLACES AP13192 TUBE KIT _____ ITEM 2 - RAP91703 - REPLACES AP31486 HOSE ASSEMBLIES _____ ITEM 4 - RAP90872 (AP24632) ITEM 5 - RAP91421 (AP24818)
MECHANISM AP35102	<b>SINGLE CYLINDER ROOM EXTENSION - 24.0" STROKE - AP35101 KIT</b>  <b>SEE MR41.1100 FOR DRAWING AND PARTS INFORMATION.</b> CYLINDER ASSEMBLY _____ ITEM 1 - RAP91753 (25.0" STROKE) - REPLACES AP35069 HOSE ASSEMBLIES _____ ITEM 4 - RAP90871 (AP24628) ITEM 3 - RAP90872 (AP24632)
MECHANISM AP35190 AP35191	<b>UNIVERSAL SLIDE OUT ROOM EXTENSION - 20.0" STROKE (WITH SYNC. CYLINDER) - AP40629 KIT</b>  <b>SEE MR41.2680 FOR DRAWING AND PARTS INFORMATION.</b> CYLINDER ASSEMBLY _____ ITEM 1 - RAP91702 (34.0" STROKE) - REPLACES AP31461 SYNCHRONIZING CYLINDER _____ ITEM 3 - RAP92099 (7.010" STROKE) - REPLACES AP39221 TUBE KIT _____ ITEM 2 - RAP91703 - REPLACES AP31486 HOSE ASSEMBLIES _____ ITEM 4 - RAP91421 (AP24818) ITEM 5 - RAP90872 (AP24632)
MECHANISM AP35752 AP35753	<b>UNIVERSAL SLIDE OUT ROOM EXTENSION - 24.0" STROKE (WITH SYNC. CYLINDER) - AP35758 KIT</b>  <b>SEE MR41.2680 FOR DRAWING AND PARTS INFORMATION.</b> CYLINDER ASSEMBLY _____ ITEM 1 - RAP91702 (34.0" STROKE) - REPLACES AP31461 SYNCHRONIZING CYLINDER _____ ITEM 3 - RAP90472 (9.685" STROKE) - REPLACES AP13224 TUBE KIT _____ ITEM 2 - RAP91703 - REPLACES AP31486 HOSE ASSEMBLIES _____ ITEM 4 - RAP90872 (AP24632) ITEM 5 - RAP91421 (AP24818)
MECHANISM AP36362 AP36363	<b>UNIVERSAL LEVEL OUT ROOM EXTENSION - 30.0" STROKE (WITH SYNC. CYLINDER) - AP36361 KIT</b>  <b>SEE MR41.2683 FOR DRAWING AND PARTS INFORMATION.</b> CYLINDER ASSEMBLY _____ ITEM 1 - RAP91702 (34.0" STROKE) - REPLACES AP31461 LIFT CYLINDER ASSEMBLY _____ ITEM 10 - RAP91992 - REPLACES AP34390 (2.75" LIFT) SYNCHRONIZING CYLINDER _____ ITEM 3 - RAP90473 (12.155" STROKE) - REPLACES AP13192 TUBE KIT _____ ITEM 2 - RAP91703 - REPLACES AP31486 HOSE ASSEMBLIES _____ ITEM 4 - RAP90872 (AP24632) ITEM 5 - RAP91421 (AP24818) LIFT SYNCHRONIZING CYLINDER _____ ITEM 11 - RAP92473 - REPLACES AP34576 CENTER LIFT CYLINDER _____ ITEM 12 - RAP92279 - REPLACES AP35823
MECHANISM AP39962 AP39963	<b>LATERAL ARM ROOM EXTENSION - 13.0" STROKE (WITH SYNCHRONIZING CYLINDER) - AP39944 KIT</b>  <b>SEE MR41.2825 FOR DRAWING AND PARTS INFORMATION.</b> CYLINDER ASSEMBLY _____ ITEM 1 - RAP91203 (6.150" STROKE) - REPLACES AP26255 SYNCHRONIZING CYLINDER _____ ITEM 3 - RAP92477 (1.230" STROKE) - REPLACES AP40045 TUBE KIT _____ ITEM 2 - RAP91226 - REPLACES AP27031 HOSE ASSEMBLIES _____ ITEM 4 - RAP91422 (AP24819) ITEM 5 - RAP91433 (AP23738)
MECHANISM AP42164	<b>DECK ROOM EXTENSION - 26.0" STROKE (WITH SYNCHRONIZING CYLINDER) - AP41980 KIT</b>  CYLINDER ASSEMBLY _____ RAP92478 (26.5" STROKE) - REPLACES AP42461 SYNCHRONIZING CYLINDER _____ RAP92469 (9.130" STROKE) - REPLACES AP39275 HOSE ASSEMBLIES _____ RAP91422 (AP24819) RAP91241 (AP25086) MANUAL RETRACT SCREW _____ RAP91643 - REPLACES AP29770