## **OEM Guide Page HWH SpaceMaker Equipment for GENERAL TRUCK BODY Vehicles**

(File: MR402750.DOC | Revised: 24MAR17)

## > Printable PDF File

- > Slide-Out Mechanisms > Slide-Out "Platform Lift" Mechanisms

## **PROCEDURE:**

- 1. Locate the HWH identification tag on the SpaceMaker mechanism to get the correct mechanism part number.
- 2. Find the correct SpaceMaker mechanism part number in the left column below.
- 3. Refer to the listed HWH Parts Manual Page for general replacement parts information and item number arrangements.
- 4. Note that two-cylinder mechanisms with a synchronizing cylinder have two part numbers. One number is for the left assembly and one is for the right assembly. If the mechanism assembly originally had one number, that number is listed with the new numbers.

SLIDE-OUT Mechanisms		
MECHANISM AP34238 AP34239	AP36036 KIT	0" STROKE (WITH SYNCHRONIZING CYLINDER) WING AND PARTS INFORMATION.
	CYLINDER ASSEMBLY	ITEM 1 - RAP91702 (34.0" STROKE) REPLACES AP31461
	SYNCHRONIZING CYLINDER	ITEM 3 - RAP90473 (12.155" STROKE)  REPLACES AP13192
	TIBE KIT	_ ITEM 2 - RAP91703 - REPLACES AP31486
	HOSE ASSEMBLIES	ITEM 4 - RAP24632 (AP24632)
		ITEM 5 - RAP24638 (AP24638)
MECHANISM AP38251 AP38252	AP38542 KIT	0" STROKE (WITH SYNCHRONIZING CYLINDER) WING AND PARTS INFORMATION.
	CYLINDER ASSEMBLY	_ ITEM 1 - RAP92076 (30.5" STROKE) REPLACES AP38072
	SYNCHRONIZING CYLINDER	_ ITEM 3 - RAP92077 (10.540" STROKE)  REPLACES AP37881
	TUBE KIT	_ ITEM 2 - RAP92079 - REPLACES AP38267
	HOSE ASSEMBLIES	_ ITEM 4 - RAP24632 (AP24632)
		ITEM 5 - RAP24638 (AP24638)
MECHANISM AP38900 AP38901	AP41517 KIT	0" STROKE (WITH SYNCHRONIZING CYLINDER) WING AND PARTS INFORMATION.
711 30301	OLE > MINTEROS.ITTIME TOR BICA	MINO AND I ANTO INI OMILATION.
	CYLINDER ASSEMBLY	_ ITEM 1 - RAP92076 (30.5" STROKE)
	SYNCHRONIZING CYLINDER	_ ITEM 3 - RAP92275 (8.420" STROKE)
	TUBE KIT	REPLACES AP39271 ITEM 2 - RAP92079 - REPLACES AP38267
	HOSE ASSEMBLIES	ITEM 4 - RAP24632 (AP24632) ITEM 5 - RAP24638 (AP24638)

MECHANISM AP46700 AP46701	UNIVERSAL STRAIGHT OUT – 24.0" STROKE (WITH SYNCHRONIZING CYLINDER) AP48350 KIT SEE > MR412685.HTML FOR DRAWING AND PARTS INFORMATION.	
	CYLINDER ASSEMBLY ITEM 1 - RAP92076 (30.5" STROKE) REPLACES AP38072	
	SYNCHRONIZING CYLINDER ITEM 3 - RAP93333 (8.420" STROKE) REPLACES AP46674	
	TUBE KIT ITEM 2 - RAP92079 - REPLACES AP38267	
	HOSE ASSEMBLIES ITEM 4 - RAP24632 (AP24632) ITEM 5 - RAP24638 (AP24638)	

SLIDE-OUT "PLATFORM LIFT" Mechanisms			
MECHANISM	PLATFORM LIFT TWO-CYLINDER		
AP48352 (96-1/2")	SEE > MR414005.HTML FOR DRAWING AND PARTS INFORMATION.		
	CYLINDER W/SEQ. VALVE ASSY ITEM 1 - RAP93139 (4.8" STROKE)		
	REPLACES AP44387		
	CYLINDER ASSEMBLY ITEM 2 - RAP93140 (4.8" STROKE)		
	REPLACES AP44395		
MECHANISM	PLATFORM LIFT TWO-CYLINDER		
AP48353 (96-1/2")	SEE > MR414005.HTML FOR DRAWING AND PARTS INFORMATION.		
	CYLINDER W/SEQ. VALVE ASSY ITEM 1 - RAP93139 (4.8" STROKE)		
	REPLACES AP44387		
	CYLINDER ASSEMBLY ITEM 2 - RAP93140 (4.8" STROKE)		
	REPLACES AP44395		
MECHANISM	PLATFORM LIFT THREE-CYLINDER		
AP50094 (129-1/2")	SEE > MR414010.HTML FOR DRAWING AND PARTS INFORMATION.		
	CYLINDER W/SEQ. VALVE ASSY ITEM 1 - RAP93139 (4.8" STROKE)		
	REPLACES AP44387		
	CYLINDER ASSEMBLY ITEM 2 - RAP93140 (4.8" STROKE)		
	(QTY 2) REPLACES AP44395		