

OEM Guide Page

HWH SpaceMaker Equipment for **HWH - GENERIC Vehicles**

(File: MR403160.DOC | Revised: 07FEB18)

> [PrintFriendly PDF File](#)

PROCEDURE:

1. Locate the HWH identification tag on the SpaceMaker mechanism to get the correct mechanism part number.
2. Find the correct SpaceMaker mechanism part number in the left column below.
3. Refer to the listed HWH Parts Manual Page for general replacement parts information and item number arrangements.
4. Note that two-cylinder mechanisms with a synchronizing cylinder have two part numbers. One number is for the left assembly and one is for the right assembly. If the mechanism assembly originally had one number, that number is listed with the new numbers.

SLIDE-OUT Mechanisms	
MECHANISM AP10265	DUAL CYLINDER ROOM EXTENSION – 34.0” STROKE – AP10754 KIT CYLINDER ASSEMBLY_____ AP2113-CONTACT HWH CORP. FOR REPLACEMENT.
MECHANISM AP15190	CYLINDER ASSEMBLY – 21.0” STROKE – REPLACED BY AP30188 CYLINDER ASSEMBLY_____ RAP90512 (21.0” STROKE)-REPLACES AP15190
MECHANISM AP17326	CYLINDER ASSEMBLY – 29.67” STROKE CYLINDER ASSEMBLY_____ RAP92497 (29.67” STROKE)-REPLACES AP17326
MECHANISM AP24705	SINGLE CYLINDER ROOM EXTENSION – 30.0” STROKE – AP24704 KIT SEE > MR411100.HTML FOR DRAWING AND PARTS INFORMATION. CYLINDER ASSEMBLY_____ ITEM 1 - RAP90949 (31.0” STROKE) REPLACES AP28727 HOSE ASSEMBLIES_____ ITEM 3 - RAP24632 (AP24632) ITEM 4 - RAP53984 (AP53984)
MECHANISM AP28685	CYLINDER ASSEMBLY – 30.25” STROKE CYLINDER ASSEMBLY_____ CONTACT HWH CORPORATION FOR REPLACEMENT
MECHANISM AP38251 AP38252	UNIVERSAL STRAIGHT OUT – 30.0” STROKE (WITH SYNCHRONIZING CYLINDER) AP39558 AND AP44013 KITS SEE > MR412685.HTML FOR DRAWING AND PARTS INFORMATION. CYLINDER ASSEMBLY_____ ITEM 1 - RAP92076 (30.5” STROKE) REPLACES AP38072 SYNCHRONIZING CYLINDER_____ ITEM 3 - RAP92077 (10.540” STROKE) REPLACES AP37881 TUBE KIT_____ ITEM 2 - RAP92079 - REPLACES AP38267 HOSE ASSEMBLIES_____ ITEM 4 - RAP24632 (AP24632) ITEM 5 - RAP24638 (AP24638)

SADDLE RACKS	
MECHANISM AP44925	SADDLE RACK ASSEMBLY – AP45615 KIT CYLINDER ASSEMBLY_____ RAP93339 (19.825” STROKE) REPLACES AP46851 HOSE ASSEMBLIES_____ RAP50910 (AP50910) RAP50909 (AP50909)