

MECHANISM AP38251 AP38252	UNIVERSAL STRAIGHT OUT – 30.0” STROKE (WITH SYNCHRONIZING CYLINDER) AP41378 KIT SEE > MR412685.HTML FOR DRAWING AND PARTS INFORMATION. CYLINDER ASSEMBLY_____ ITEM 1 - RAP92076 (30.5” STROKE) REPLACES AP38072 SYNCHRONIZING CYLINDER_____ ITEM 3 - RAP92077 (10.540” STROKE) REPLACES AP37881 TUBE KIT_____ ITEM 2 - RAP92079 - REPLACES AP38267 HOSE ASSEMBLIES_____ ITEM 4 - RAP24632 (AP24632) ITEM 5 - RAP24638 (AP24638)
MECHANISM AP40006 AP40007	UNIVERSAL STRAIGHT OUT – 20.0” STROKE (WITH SYNCHRONIZING CYLINDER) AP41377 KIT SEE > MR412685.HTML FOR DRAWING AND PARTS INFORMATION. CYLINDER ASSEMBLY_____ ITEM 1 - RAP92076 (30.5” STROKE) REPLACES AP38072 SYNCHRONIZING CYLINDER_____ ITEM 3 - RAP92099 (7.010” STROKE) REPLACES AP39221 TUBE KIT_____ ITEM 2 - RAP92079 - REPLACES AP38267 HOSE ASSEMBLIES_____ ITEM 4 - RAP24632 (AP24632) ITEM 5 - RAP24638 (AP24638)
MECHANISM AP46436 AP46437	UNIVERSAL STRAIGHT OUT – 26.0” STROKE (WITH SYNCHRONIZING CYLINDER) AP51692 KIT SEE > MR412685.HTML FOR DRAWING AND PARTS INFORMATION. CYLINDER ASSEMBLY_____ ITEM 1 - RAP92076 (30.5” STROKE) REPLACES AP38072 SYNCHRONIZING CYLINDER_____ ITEM 3 - RAP92469 (9.13” STROKE) REPLACES AP39275 TUBE KIT_____ ITEM 2 - RAP92079 - REPLACES AP38267 HOSE ASSEMBLIES_____ ITEM 4 - RAP24632 (AP24632) ITEM 5 - RAP24638 (AP24638)

STEP Systems	
MECHANISM AP51938	STEP ASSEMBLY – 28.75” STROKE CYLINDER ASSEMBLIES_____ RAP93539 (24.5” STROKE)-REPLACES AP51810 RAP93540 (4.8” STROKE) -REPLACES AP52080 HOSE ASSEMBLIES_____ RAP50909 (AP50909) RAP51480 (AP51480) RAP51975 (AP51975) RAP48865 (AP48865) RAP16434 (AP16434) RAP52043 (AP52043)
MECHANISM AP52057	STEP ASSEMBLY – 36.0” STROKE CYLINDER ASSEMBLIES_____ RAP93541 (33.7” STROKE)-REPLACES AP52094 RAP93540 (4.8” STROKE)- REPLACES AP52080 HOSE ASSEMBLIES_____ RAP50556 (AP50556) RAP49244 (AP49244) RAP16434 (AP16434) RAP51975 (AP51975) RAP48866 (AP48866)
MECHANISM AP52642	STEP ASSEMBLY – 28.75” STROKE CYLINDER ASSEMBLIES_____ RAP93541 (33.7” STROKE)-REPLACES AP52094 RAP93540 (4.8” STROKE) -REPLACES AP52080 HOSE ASSEMBLIES_____ RAP50556 (AP50556) RAP49244 (AP49244) RAP51975 (AP51975) RAP52043 (AP52043)