

# OEM Guide Page

## HWH SpaceMaker Equipment for **KC CUSTOMS Vehicles**

(File: MR403470.DOC | Revised: 01AUG17)

[> Printable PDF File](#)

### PROCEDURE:

1. Locate the HWH identification tag on the SpaceMaker mechanism to get the correct mechanism part number.
2. Find the correct SpaceMaker mechanism part number in the left column below.
3. Refer to the listed HWH Parts Manual Page for general replacement parts information and item number arrangements.
4. Note that two-cylinder mechanisms with a synchronizing cylinder have two part numbers. One number is for the left assembly and one is for the right assembly. If the mechanism assembly originally had one number, that number is listed with the new numbers.

<b>SLIDE-OUT Mechanisms</b>	
<b>MECHANISM</b> AP27470	<b>SINGLE CYLINDER ROOM EXTENSION – 38.0” STROKE – AP27469 KIT</b> <b>SEE &gt; <a href="#">MR411006.HTML</a> FOR DRAWING AND PARTS INFORMATION.</b>  CYLINDER ASSEMBLY_____ ITEM 1 - RAP91196 (38.5” STROKE) REPLACES AP22092 TUBE KIT_____ ITEM 4 - RAP90480 - REPLACES AP13252
<b>MECHANISM</b> AP27472 AP27473	<b>DUAL CYLINDER ROOM EXTENSION– 38.0” STROKE (WITH SYNCHRONIZING CYLINDER)</b> <b>AP27471 KIT</b> <b>SEE &gt; <a href="#">MR412005.HTML</a> FOR DRAWING AND PARTS INFORMATION.</b>  CYLINDER ASSEMBLY_____ ITEM 1 - RAP91196 (38.50” STROKE) REPLACES AP22092 SYNCHRONIZING CYLINDER_____ ITEM 3 - RAP90639 (15.455” STROKE) REPLACES AP17498 TUBE KIT_____ ITEM 4 - RAP90480 - REPLACES AP13252