

# ROOM EXTENSION ASSEMBLIES GUIDE PAGE "LDS SYSTEMS INC" (PAGE 2 OF 2)

PROCEDURE: SEE "LDS SYSTEMS INC" (PAGE 1 OF 2)

MECHANISM AP32886 AP32887	<b>X-SLIDE ROOM EXTENSION - 25.0" STROKE (WITH SYNCHRONIZING CYLINDER) - AP32885 KIT</b>  <a href="#">SEE MR41.2670 FOR DRAWING AND PARTS INFORMATION.</a> CYLINDER ASSEMBLY _____ ITEM 1 - RAP91350 (11.40" STROKE) - REPLACES AP27865 SYNCHRONIZING CYLINDER _____ ITEM 3 - RAP91701 (4.300" STROKE) - REPLACES AP30260 TUBE KIT _____ ITEM 2 - RAP91229 - REPLACES AP27587 HOSE ASSEMBLIES _____ ITEM 4 - RAP91574 (AP24627) ITEM 5 - RAP91573 (AP32672)
MECHANISM AP32909 AP32910	<b>LATERAL ARM ROOM EXTENSION - 20.0" STROKE (WITH SYNCHRONIZING CYLINDER) - AP32911 KIT</b>  <a href="#">SEE MR41.2825 FOR DRAWING AND PARTS INFORMATION.</a> CYLINDER ASSEMBLY _____ ITEM 1 - RAP91351 (6.775" STROKE) - REPLACES AP27997 SYNCHRONIZING CYLINDER _____ ITEM 3 - RAP90524 (2.385" STROKE) - REPLACES AP14881 TUBE KIT _____ ITEM 2 - RAP91774 - REPLACES AP28035 HOSE ASSEMBLIES _____ ITEM 4 - RAP91574 (AP24627) ITEM 5 - RAP91562 (AP25677)
MECHANISM AP35576 AP35577	<b>DUAL CYLINDER ROOM EXTENSION - 55.0" STROKE (WITH SYNCHRONIZING CYLINDER) - AP35500 KIT</b>  <a href="#">SEE MR41.2006 FOR DRAWING AND PARTS INFORMATION.</a> CYLINDER ASSEMBLY _____ ITEM 1 - RAP91803 (56.0" STROKE) - REPLACES AP35634 SYNCHRONIZING CYLINDER _____ ITEM 3 - RAP91802 (21.160" STROKE) - REPLACES AP35668 TUBE KIT _____ ITEM 2 - RAP91804 - REPLACES AP35628
MECHANISM AP35634	<b>CYLINDER ASSEMBLY - 56.0" STROKE - AP47168 KIT</b>  CYLINDER ASSEMBLY _____ RAP91803 (56.0" STROKE) - REPLACES AP35634 SYNCHRONIZING CYLINDER _____ RAP91802 (21.160" STROKE) - REPLACES AP35668
MECHANISM AP45492	<b>CYLINDER ASSEMBLY - 47.25" STROKE - AP45481 KIT</b>  CYLINDER ASSEMBLY _____ RAP92925 (47.25" STROKE) - REPLACES AP45492 SYNCHRONIZING CYLINDER _____ RAP92927 (16.570" STROKE) - REPLACES AP45490
MECHANISM AP48668	<b>CYLINDER ASSEMBLY - 33.5" STROKE - AP48663 KIT</b>  CYLINDER ASSEMBLY _____ RAP92926 (39.5" STROKE) - REPLACES AP48668 SYNCHRONIZING CYLINDER _____ RAP92928 (13.910" STROKE) - REPLACES AP48667