

# OEM Guide Page

## HWH SpaceMaker Equipment for **LDV, INC. Vehicles**

(File: MR403615.DOC | Revised: 10APR17)

> [Printable PDF File](#)

### PROCEDURE:

1. Locate the HWH identification tag on the SpaceMaker mechanism to get the correct mechanism part number.
2. Find the correct SpaceMaker mechanism part number in the left column below.
3. Refer to the listed HWH Parts Manual Page for general replacement parts information and item number arrangements.
4. Note that two-cylinder mechanisms with a synchronizing cylinder have two part numbers. One number is for the left assembly and one is for the right assembly. If the mechanism assembly originally had one number, that number is listed with the new numbers.

<b>SLIDE-OUT Mechanisms</b>	
<b>MECHANISM</b> AP38251 AP38252	<b>UNIVERSAL STRAIGHT OUT – 30.0" STROKE (WITH SYNCHRONIZING CYLINDER)</b> <b>AP43801 KIT</b> <b>SEE &gt; <a href="#">MR412685.HTML</a> FOR DRAWING AND PARTS INFORMATION.</b>  CYLINDER ASSEMBLY_____ ITEM 1 - RAP92076 (30.5" STROKE) REPLACES AP38072 SYNCHRONIZING CYLINDER_____ ITEM 3 - RAP92077 (10.540" STROKE) REPLACES AP37881 TUBE KIT_____ ITEM 2 - RAP92079 - REPLACES AP38267 HOSE ASSEMBLIES_____ ITEM 4 - RAP24632 (AP24632) ITEM 5 - RAP24638 (AP24638)
<b>MECHANISM</b> AP38383 AP38384	<b>UNIVERSAL LEVEL OUT – 26.0" STROKE (WITH SYNCHRONIZING CYLINDER)</b> <b>AP38392 KIT</b> <b>SEE &gt; <a href="#">MR412690.HTML</a> FOR DRAWING AND PARTS INFORMATION.</b>  CYLINDER ASSEMBLY_____ ITEM 1 - RAP92076 (30.5" STROKE) REPLACES AP38072 LIFT CYLINDER ASSEMBLY_____ ITEM 11 - RAP92260 (2.75" LIFT) REPLACES AP38604 SYNCHRONIZING CYLINDER_____ ITEM 3 - RAP92469 (9.130" STROKE) REPLACES AP39275 LIFT SYNCHRONIZING CYL. _____ ITEM 12 - RAP92316 - REPLACES AP38264 TUBE KIT_____ ITEM 2 - RAP92079 - REPLACES AP38267 HOSE ASSEMBLIES_____ ITEM 4 - RAP24632 (AP24632) ITEM 5 - RAP24638 (AP24638)
<b>MECHANISM</b> AP39645 AP39646	<b>UNIVERSAL STRAIGHT OUT – 26.0" STROKE (WITH SYNCHRONIZING CYLINDER)</b> <b>AP43800 KIT</b> <b>SEE &gt; <a href="#">MR412685.HTML</a> FOR DRAWING AND PARTS INFORMATION.</b>  CYLINDER ASSEMBLY_____ ITEM 1 - RAP92076 (30.5" STROKE) REPLACES AP38072 SYNCHRONIZING CYLINDER_____ ITEM 3 - RAP92469 (9.130" STROKE) REPLACES AP39275 TUBE KIT_____ ITEM 2 - RAP92079 - REPLACES AP38267 HOSE ASSEMBLIES_____ ITEM 4 - RAP24632 (AP24632) ITEM 5 - RAP24638 (AP24638)

<b>MECHANISM</b> AP40753 AP40754	<b>UNIVERSAL LEVEL OUT – 30.0” STROKE (WITH SYNCHRONIZING CYLINDER)</b> <b>AP43624 KIT</b> <b>SEE &gt; <a href="#">MR412690.HTML</a> FOR DRAWING AND PARTS INFORMATION.</b>  CYLINDER ASSEMBLY_____ ITEM 1 - RAP92076 (30.5” STROKE) REPLACES AP38072 LIFT CYLINDER ASSEMBLY_____ ITEM 11 - RAP92261 (3.50” LIFT) REPLACES AP40746 SYNCHRONIZING CYLINDER_____ ITEM 3 - RAP92077 (10.540” STROKE) REPLACES AP37881 LIFT SYNCHRONIZING CYL. _____ ITEM 12 - RAP92503 - REPLACES AP40832 TUBE KIT_____ ITEM 2 - RAP92079 - REPLACES AP38267 HOSE ASSEMBLIES_____ ITEM 4 - RAP24632 (AP24632) ITEM 5 - RAP24638 (AP24638) CENTER LIFT CYLINDER_____ ITEM 13 - RAP92506 - REPLACES AP39601
<b>MECHANISM</b> AP43797 AP43798	<b>UNIVERSAL LEVEL OUT – 26.0” STROKE (WITH SYNCHRONIZING CYLINDER)</b> <b>AP43796 KIT</b> <b>SEE &gt; <a href="#">MR412690.HTML</a> FOR DRAWING AND PARTS INFORMATION.</b>  CYLINDER ASSEMBLY_____ ITEM 1 - RAP92076 (30.5” STROKE) REPLACES AP38072 LIFT CYLINDER ASSEMBLY_____ ITEM 11 - RAP92261 (3.50” LIFT) REPLACES AP40746 SYNCHRONIZING CYLINDER_____ ITEM 3 - RAP92469 (9.130” STROKE) REPLACES AP39275 LIFT SYNCHRONIZING CYL. _____ ITEM 12 - RAP92503 - REPLACES AP40832 TUBE KIT_____ ITEM 2 - RAP92079 - REPLACES AP38267 HOSE ASSEMBLIES_____ ITEM 4 - RAP24632 (AP24632) ITEM 5 - RAP24638 (AP24638) CENTER LIFT CYLINDER_____ ITEM 13 - RAP92506 - REPLACES AP39601