

OEM Guide Page

HWH SpaceMaker Equipment for **LOYALTY MOBILE Vehicles**

(File: MR403730.DOC | Revised: 13APR17)

> [Printable PDF File](#)

PROCEDURE:

1. Locate the HWH identification tag on the SpaceMaker mechanism to get the correct mechanism part number.
2. Find the correct SpaceMaker mechanism part number in the left column below.
3. Refer to the listed HWH Parts Manual Page for general replacement parts information and item number arrangements.
4. Note that two-cylinder mechanisms with a synchronizing cylinder have two part numbers. One number is for the left assembly and one is for the right assembly. If the mechanism assembly originally had one number, that number is listed with the new numbers.

SLIDE-OUT Mechanisms	
MECHANISM AP38251 AP38252	UNIVERSAL STRAIGHT OUT – 30.0” STROKE (WITH SYNCHRONIZING CYLINDER) AP40850 KIT SEE > MR412685.HTML FOR DRAWING AND PARTS INFORMATION. CYLINDER ASSEMBLY_____ ITEM 1 - RAP92076 (30.5” STROKE) REPLACES AP38072 SYNCHRONIZING CYLINDER_____ ITEM 3 - RAP92077 (10.540” STROKE) REPLACES AP37881 TUBE KIT_____ ITEM 2 - RAP92079 - REPLACES AP38267 HOSE ASSEMBLIES_____ ITEM 4 - RAP24632 (AP24632) ITEM 5 - RAP24638 (AP24638)
MECHANISM AP38900 AP38901	UNIVERSAL STRAIGHT OUT – 24.0” STROKE (WITH SYNCHRONIZING CYLINDER) AP45436, AP48216, AND AP49033 KITS SEE > MR412685.HTML FOR DRAWING AND PARTS INFORMATION. CYLINDER ASSEMBLY_____ ITEM 1 - RAP92076 (30.5” STROKE) REPLACES AP38072 SYNCHRONIZING CYLINDER_____ ITEM 3 - RAP92275 (8.420” STROKE) REPLACES AP39271 TUBE KIT_____ ITEM 2 - RAP92079 - REPLACES AP38267 HOSE ASSEMBLIES_____ ITEM 4 - RAP24632 (AP24632) ITEM 5 - RAP24638 (AP24638)
MECHANISM AP39182 AP39183	UNIVERSAL STRAIGHT OUT – 18.0” STROKE (WITH SYNCHRONIZING CYLINDER) AP46936 KIT SEE > MR412685.HTML FOR DRAWING AND PARTS INFORMATION. CYLINDER ASSEMBLY_____ ITEM 1 - RAP92076 (30.5” STROKE) REPLACES AP38072 SYNCHRONIZING CYLINDER_____ ITEM 3 - RAP92369 (6.300” STROKE) REPLACES AP39267 TUBE KIT_____ ITEM 2 - RAP92079 - REPLACES AP38267 HOSE ASSEMBLIES_____ ITEM 4 - RAP24632 (AP24632) ITEM 5 - RAP24638 (AP24638)
MECHANISM AP40395 AP40396	UNIVERSAL LEVEL OUT – 24.0” STROKE (WITH SYNCHRONIZING CYLINDER) AP41867 KIT SEE > MR412690.HTML FOR DRAWING AND PARTS INFORMATION. CYLINDER ASSEMBLY_____ ITEM 1 - RAP92076 (30.5” STROKE) REPLACES AP38072 LIFT CYLINDER ASSEMBLY_____ ITEM 11 - RAP92260 (2.75” LIFT) REPLACES AP38604 SYNCHRONIZING CYLINDER_____ ITEM 3 - RAP92275 (8.420” STROKE) REPLACES AP39271 LIFT SYNCHRONIZING CYLINDER_ ITEM 12 - RAP92316 - REPLACES AP38264 TUBE KIT_____ ITEM 2 - RAP92079 - REPLACES AP38267 HOSE ASSEMBLIES_____ ITEM 4 - RAP24632 (AP24632) ITEM 5 - RAP24638 (AP24638)

MECHANISM AP42937 AP42938	UNIVERSAL LEVEL OUT – 24.0” STROKE (WITH SYNCHRONIZING CYLINDER) AP42936 KIT SEE > MR412690.HTML FOR DRAWING AND PARTS INFORMATION. CYLINDER ASSEMBLY_____ ITEM 1 - RAP92076 (30.5” STROKE) REPLACES AP38072 LIFT CYLINDER ASSEMBLY_____ ITEM 11 - RAP92261 (3.50” LIFT) REPLACES AP40746 SYNCHRONIZING CYLINDER_____ ITEM 3 - RAP92275 (8.420” STROKE) REPLACES AP39271 LIFT SYNCHRONIZING CYLINDER_ ITEM 12 - RAP92503 - REPLACES AP40832 TUBE KIT_____ ITEM 2 - RAP92079 - REPLACES AP38267 HOSE ASSEMBLIES_____ ITEM 4 - RAP24632 (AP24632) ITEM 5 - RAP24638 (AP24638)
MECHANISM AP40753 AP40754	UNIVERSAL LEVEL OUT – 30.0” STROKE (WITH SYNCHRONIZING CYLINDER) AP44687 KIT SEE > MR412690.HTML FOR DRAWING AND PARTS INFORMATION. CYLINDER ASSEMBLY_____ ITEM 1 - RAP92076 (30.5” STROKE) REPLACES AP38072 LIFT CYLINDER ASSEMBLY_____ ITEM 11 - RAP92261 (3.50” LIFT) REPLACES AP40746 SYNCHRONIZING CYLINDER_____ ITEM 3 - RAP92077 (10.540” STROKE) REPLACES AP37881 LIFT SYNCHRONIZING CYLINDER_ ITEM 12 - RAP92503 - REPLACES AP40832 TUBE KIT_____ ITEM 2 - RAP92079 - REPLACES AP38267 HOSE ASSEMBLIES_____ ITEM 4 - RAP24632 (AP24632) ITEM 5 - RAP24638 (AP24638)
MECHANISM AP43733 AP43734	UNIVERSAL STRAIGHT OUT – 22.0” STROKE (WITH SYNCHRONIZING CYLINDER) AP49032 KIT SEE > MR412685.HTML FOR DRAWING AND PARTS INFORMATION. CYLINDER ASSEMBLY_____ ITEM 1 - RAP92076 (30.5” STROKE) REPLACES AP38072 SYNCHRONIZING CYLINDER_____ ITEM 3 - RAP92522 (7.710” STROKE) REPLACES AP43403 TUBE KIT_____ ITEM 2 - RAP92079 - REPLACES AP38267 HOSE ASSEMBLIES_____ ITEM 4 - RAP24632 (AP24632) ITEM 5 - RAP24638 (AP24638)
MECHANISM AP43797 AP43798	UNIVERSAL LEVEL OUT – 26.0” STROKE (WITH SYNCHRONIZING CYLINDER) AP52233 KIT SEE > MR412690.HTML FOR DRAWING AND PARTS INFORMATION. CYLINDER ASSEMBLY_____ ITEM 1 - RAP92076 (30.5” STROKE) REPLACES AP38072 LIFT CYLINDER ASSEMBLY_____ ITEM 11 - RAP92261 (3.50” LIFT) REPLACES AP40746 SYNCHRONIZING CYLINDER_____ ITEM 3 - RAP92469 (9.130” STROKE) REPLACES AP39275 LIFT SYNCHRONIZING CYLINDER_ ITEM 12 - RAP92503 - REPLACES AP40832 TUBE KIT_____ ITEM 2 - RAP92079 - REPLACES AP38267 HOSE ASSEMBLIES_____ ITEM 4 - RAP24632 (AP24632) ITEM 5 - RAP24638 (AP24638)
MECHANISM AP46691 AP46692	UNIVERSAL STRAIGHT OUT – 24.0” STROKE (WITH SYNCHRONIZING CYLINDER) AP48933 KIT SEE > MR412685.HTML FOR DRAWING AND PARTS INFORMATION. CYLINDER ASSEMBLY_____ ITEM 1 - RAP92076 (30.5” STROKE) REPLACES AP38072 SYNCHRONIZING CYLINDER_____ ITEM 3 - RAP92275 (8.420” STROKE) REPLACES AP39271 TUBE KIT_____ ITEM 2 - RAP92079 - REPLACES AP38267 HOSE ASSEMBLIES_____ ITEM 4 - RAP24632 (AP24632) ITEM 5 - RAP24638 (AP24638)

MECHANISM AP48852 AP48853	UNIVERSAL LEVEL OUT – 20.0” STROKE (WITH SYNCHRONIZING CYLINDER) AP49034 KIT SEE > MR412690.HTML FOR DRAWING AND PARTS INFORMATION. CYLINDER ASSEMBLY_____ ITEM 1 - RAP92076 (30.5” STROKE) REPLACES AP38072 LIFT CYLINDER ASSEMBLY_____ ITEM 11 - RAP92261 (3.50” LIFT) REPLACES AP40746 SYNCHRONIZING CYLINDER_____ ITEM 3 - RAP92099 (7.010” STROKE) REPLACES AP39221 LIFT SYNCHRONIZING CYLINDER_ ITEM 12 - RAP92503 - REPLACES AP40832 TUBE KIT_____ ITEM 2 - RAP92079 - REPLACES AP38267 HOSE ASSEMBLIES_____ ITEM 4 - RAP24632 (AP24632) ITEM 5 - RAP24638 (AP24638)
--	--