

OEM Guide Page

HWH SpaceMaker Equipment for **MARATHON COACH CORP. Vehicles**

(File: MR403865.DOC | Revised: 17APR17)

[> Printable PDF File](#)

PROCEDURE:

1. Locate the HWH identification tag on the SpaceMaker mechanism to get the correct mechanism part number.
2. Find the correct SpaceMaker mechanism part number in the left column below.
3. Refer to the listed HWH Parts Manual Page for general replacement parts information and item number arrangements.
4. Note that two-cylinder mechanisms with a synchronizing cylinder have two part numbers. One number is for the left assembly and one is for the right assembly. If the mechanism assembly originally had one number, that number is listed with the new numbers.

SLIDE-OUT Mechanisms	
MECHANISM AP12328	<p>CYLINDER ASSEMBLY – 13.8” STROKE</p> <p>CYLINDER ASSEMBLY_____ RAP91212 (13.8” STROKE)- REPLACES AP12328</p>
MECHANISM AP16984	<p>CYLINDER ASSEMBLY – 29.875” STROKE</p> <p>CYLINDER ASSEMBLY_____ RAP92911 (29.875” STROKE)-REPLACES AP16984 TUBE KIT_____ RAP92480 - REPLACES AP20193</p>
MECHANISM AP18490	<p>CYLINDER ASSEMBLY – 30.25” STROKE</p> <p>CYLINDER ASSEMBLY_____ RAP90946 (30.25” STROKE)-REPLACES AP18490</p>
MECHANISM AP25958 AP25959	<p>TRAIN DRIVE ROOM EXTENSION – (4) CYLINDERS -17.5” STROKE (WITH SYNC. CYL.) SEE > MR412650.HTML FOR DRAWING AND PARTS INFORMATION.</p> <p>CYLINDER ASSEMBLY_____ ITEM 1 - RAP92913 (17.5” STROKE) REPLACES AP25952</p> <p>SYNCHRONIZING CYLINDER_____ ITEM 5 - RAP91014 (2.4” STROKE) REPLACES AP25695</p> <p>SEE > MR418001.HTML FOR ADD'L SYNC. CYL. REPLACEMENT PARTS.</p> <p>HOSE ASSEMBLIES_____ ITEM 1A- SPECIAL HOSE, CONTACT HWH ITEM 2 - RAP91540 - REPLACES AP24570 (TOP) ITEM 2 - RAP91538 - REPLACES AP24571 (TOP) ITEM 2 - RAP91531 - REPLACES AP24568 (BOTTOM) ITEM 2 - RAP91530 - REPLACES AP24569 (BOTTOM)</p>
MECHANISM AP28144 AP28145	<p>VERTICAL ARM ROOM EXTENSION – 30.0” STROKE (WITH SYNCHRONIZING CYLINDER) SEE > MR412500.HTML FOR DRAWING AND PARTS INFORMATION.</p> <p>CYLINDER ASSEMBLY_____ ITEM 1 - RAP91197 (12.18” STROKE) REPLACES AP23170</p> <p>SYNCHRONIZING CYLINDER_____ ITEM 3 - RAP90450 (5.005” STROKE) REPLACES AP15416</p>