

OEM Guide Page

HWH SpaceMaker Equipment for **MATTMAN COMPANY** Vehicles

(File: MR403930.DOC | Revised: 18APR17)

[> Printable PDF File](#)

PROCEDURE:

1. Locate the HWH identification tag on the SpaceMaker mechanism to get the correct mechanism part number.
2. Find the correct SpaceMaker mechanism part number in the left column below.
3. Refer to the listed HWH Parts Manual Page for general replacement parts information and item number arrangements.
4. Note that two-cylinder mechanisms with a synchronizing cylinder have two part numbers. One number is for the left assembly and one is for the right assembly. If the mechanism assembly originally had one number, that number is listed with the new numbers.

SLIDE-OUT Mechanisms	
MECHANISM <i>AP34238</i> <i>AP34239</i>	<p>UNIVERSAL STRAIGHT OUT – 30.0” STROKE (WITH SYNCHRONIZING CYLINDER) AP34640 KIT SEE > MR412680.HTML FOR DRAWING AND PARTS INFORMATION.</p> <p>CYLINDER ASSEMBLY_____ ITEM 1 - RAP91702 (34.0” STROKE) REPLACES AP31461</p> <p>SYNCHRONIZING CYLINDER_____ ITEM 3 - RAP90473 (12.155” STROKE) REPLACES AP13192</p> <p>TUBE KIT_____ ITEM 2 - RAP91703 - REPLACES AP31486</p> <p>HOSE ASSEMBLIES_____ ITEM 4 - RAP24632 (AP24632) ITEM 5 - RAP24638 (AP24638)</p>
MECHANISM <i>AP35233</i> <i>AP35234</i>	<p>UNIVERSAL LEVEL OUT ROOM EXTENSION – 30.0” STROKE (WITH SYNC. CYLINDER) AP37464 KIT SEE > MR412683.HTML FOR DRAWING AND PARTS INFORMATION.</p> <p>CYLINDER ASSEMBLY_____ ITEM 1 - RAP91702 (34.0” STROKE) REPLACES AP31461</p> <p>LIFT CYLINDER ASSEMBLY_____ ITEM 10 - RAP91992 (2.75” LIFT) REPLACES AP34390</p> <p>SYNCHRONIZING CYLINDER_____ ITEM 3 - RAP90473 (12.155” STROKE) REPLACES AP13192</p> <p>TUBE KIT_____ ITEM 2 - RAP91703 - REPLACES AP31486</p> <p>HOSE ASSEMBLIES_____ ITEM 4 - RAP24632 (AP24632) ITEM 5 - RAP24638 (AP24638)</p> <p>LIFT SYNCHRONIZING CYLINDER_ ITEM 11 - RAP92473 - REPLACES AP34576</p>