

ROOM EXTENSION ASSEMBLIES GUIDE PAGE "MDW INC" (PAGE 2 OF 2)

PROCEDURE: SEE "MDW INC" (PAGE 1 OF 2)

| | |
|---------------------------------|--|
| MECHANISM AP40753 AP40754 | UNIVERSAL LEVEL OUT - 30.0" STROKE (WITH SYNCHRONIZING CYLINDER) - AP44505 KIT SEE MR41.2690 FOR DRAWING AND PARTS INFORMATION. CYLINDER ASSEMBLY _____ ITEM 1 - RAP92076 (30.5" STROKE) - REPLACES AP38072 LIFT CYLINDER ASSEMBLY _____ ITEM 11 - RAP92261 (3.50" LIFT) - REPLACES AP40746 SYNCHRONIZING CYLINDER _____ ITEM 3 - RAP92077 (10.540" STROKE) - REPLACES AP37881 LIFT SYNCHRONIZING CYLINDER _____ ITEM 12 - RAP92503 - REPLACES AP40832 TUBE KIT _____ ITEM 2 - RAP92079 - REPLACES AP38267 HOSE ASSEMBLIES _____ ITEM 4 - RAP90872 (AP24632) ITEM 5 - RAP91421 (AP24818) CENTER LIFT CYLINDER _____ ITEM 13 - RAP92506 - REPLACES AP39601 |
| MECHANISM AP47135 AP47136 | GENERATOR EXTENSION - 31.0" STROKE - AP47131 KIT SEE MR41.2003 FOR DRAWING AND PARTS INFORMATION. CYLINDER ASSEMBLY _____ ITEM 1 - RAP90657 (32.0" STROKE) - REPLACES AP18257 SYNCHRONIZING CYLINDER _____ ITEM 3 - RAP90442 (12.570" STROKE) - REPLACES AP16484 TUBE KIT _____ ITEM 2 - RAP90658 - REPLACES AP18428 |