

# OEM Guide Page

## HWH SpaceMaker Equipment for **MICKEY TRUCK BODIES** Vehicles

(File: MR403990.DOC | Revised: 18APR17)

[> Printable PDF File](#)

- > [Slide-Out Mechanisms](#)
- > [Slide-Out "Platform Lift" Mechanisms](#)
- > [Step Systems](#)

**PROCEDURE:**

1. Locate the HWH identification tag on the SpaceMaker mechanism to get the correct mechanism part number.
2. Find the correct SpaceMaker mechanism part number in the left column below.
3. Refer to the listed HWH Parts Manual Page for general replacement parts information and item number arrangements.
4. Note that two-cylinder mechanisms with a synchronizing cylinder have two part numbers. One number is for the left assembly and one is for the right assembly. If the mechanism assembly originally had one number, that number is listed with the new numbers.

<b>SLIDE-OUT Mechanisms</b>	
<b>MECHANISM</b> <i>AP38251</i> <i>AP38252</i>	<p><b>UNIVERSAL STRAIGHT OUT – 30.0" STROKE (WITH SYNCHRONIZING CYLINDER)</b>  <b>AP47998 KIT</b>  <b>SEE &gt; <a href="#">MR412685.HTML</a> FOR DRAWING AND PARTS INFORMATION.</b></p> <p>CYLINDER ASSEMBLY_____ ITEM 1 - RAP92076 (30.5" STROKE)  REPLACES AP38072</p> <p>SYNCHRONIZING CYLINDER_____ ITEM 3 - RAP92077 (10.540" STROKE)  REPLACES AP37881</p> <p>TUBE KIT_____ ITEM 2 - RAP92079 - REPLACES AP38267</p> <p>HOSE ASSEMBLIES_____ ITEM 4 - RAP24632 (AP24632)  ITEM 5 - RAP24638 (AP24638)</p>
<b>MECHANISM</b> <i>AP38944</i> <i>AP38945</i>	<p><b>UNIVERSAL LEVEL OUT – 30.0" STROKE (WITH SYNCHRONIZING CYLINDER)</b>  <b>AP41480 KIT</b>  <b>SEE &gt; <a href="#">MR412690.HTML</a> FOR DRAWING AND PARTS INFORMATION.</b></p> <p>CYLINDER ASSEMBLY_____ ITEM 1 - RAP92076 (30.5" STROKE)  REPLACES AP38072</p> <p>LIFT CYLINDER ASSEMBLY_____ ITEM 11 - RAP92260 (2.75" LIFT)  REPLACES AP38604</p> <p>SYNCHRONIZING CYLINDER_____ ITEM 3 - RAP92077 (10.540" STROKE)  REPLACES AP37881</p> <p>LIFT SYNCHRONIZING CYLINDER_ ITEM 12 - RAP92316 - REPLACES AP38264</p> <p>TUBE KIT_____ ITEM 2 - RAP92079 - REPLACES AP38267</p> <p>HOSE ASSEMBLIES_____ ITEM 4 - RAP24632 (AP24632)  ITEM 5 - RAP24638 (AP24638)</p>
<b>MECHANISM</b> <i>AP43166</i> <i>AP43167</i>	<p><b>UNIVERSAL STRAIGHT OUT – 30.0" STROKE (WITH SYNCHRONIZING CYLINDER)</b>  <b>AP49851 KIT</b>  <b>SEE &gt; <a href="#">MR412685.HTML</a> FOR DRAWING AND PARTS INFORMATION.</b></p> <p>CYLINDER ASSEMBLY_____ ITEM 1 - RAP92076 (30.5" STROKE)  REPLACES AP38072</p> <p>SYNCHRONIZING CYLINDER_____ ITEM 3 - RAP93303 (10.540" STROKE)  REPLACES AP46064</p> <p>TUBE KIT_____ ITEM 2 - RAP92079 - REPLACES AP38267</p> <p>HOSE ASSEMBLIES_____ ITEM 4 - RAP24632 (AP24632)  ITEM 5 - RAP24638 (AP24638)</p>

<b>MECHANISM</b> AP43797 AP43798	<b>UNIVERSAL LEVEL OUT – 26.0” STROKE (WITH SYNCHRONIZING CYLINDER)</b> <b>AP49850 KIT</b> <b>SEE &gt; <a href="#">MR412690.HTML</a> FOR DRAWING AND PARTS INFORMATION.</b>  CYLINDER ASSEMBLY_____ ITEM 1 - RAP92076 (30.5” STROKE) REPLACES AP38072 LIFT CYLINDER ASSEMBLY_____ ITEM 11 - RAP92261 (3.50” LIFT) REPLACES AP40746 SYNCHRONIZING CYLINDER_____ ITEM 3 - RAP92469 (9.130” STROKE) REPLACES AP39275 LIFT SYNCHRONIZING CYLINDER_ ITEM 12 - RAP92503 - REPLACES AP40832 TUBE KIT_____ ITEM 2 - RAP92079 - REPLACES AP38267 HOSE ASSEMBLIES_____ ITEM 4 - RAP24632 (AP24632) ITEM 5 - RAP24638 (AP24638)
<b>MECHANISM</b> AP45900 AP45901	<b>UNIVERSAL STRAIGHT OUT – 30.0” STROKE (WITH SYNCHRONIZING CYLINDER)</b> <b>AP51077 KIT</b> <b>SEE &gt; <a href="#">MR412685.HTML</a> FOR DRAWING AND PARTS INFORMATION.</b>  CYLINDER ASSEMBLY_____ ITEM 1 - RAP92076 (30.5” STROKE) REPLACES AP38072 SYNCHRONIZING CYLINDER_____ ITEM 3 - RAP93303 (10.540” STROKE) REPLACES AP46064 TUBE KIT_____ ITEM 2 - RAP92079 - REPLACES AP38267 HOSE ASSEMBLIES_____ ITEM 4 - RAP24632 (AP24632) ITEM 5 - RAP24638 (AP24638)

<b>SLIDE-OUT “PLATFORM LIFT” Mechanisms</b>	
<b>MECHANISM</b> AP49866 (105 1/2")	<b>PLATFORM LIFT TWO-CYLINDER</b> <b>SEE &gt; <a href="#">MR414005.HTML</a> FOR DRAWING AND PARTS INFORMATION.</b>  CYLINDER W/SEQ. VALVE ASSY._ ITEM 1 - RAP93139 (4.8” STROKE) REPLACES AP44387 CYLINDER ASSEMBLY_____ ITEM 2 - RAP93140 (4.8” STROKE) REPLACES AP44395
<b>MECHANISM</b> AP50535 (105 1/2")	<b>PLATFORM LIFT TWO-CYLINDER</b> <b>SEE &gt; <a href="#">MR414005.HTML</a> FOR DRAWING AND PARTS INFORMATION.</b>  CYLINDER W/SEQ. VALVE ASSY._ ITEM 1 - RAP93139 (4.8” STROKE) REPLACES AP44387 CYLINDER ASSEMBLY_____ ITEM 2 - RAP93140 (4.8” STROKE) REPLACES AP44395
<b>MECHANISM</b> AP51238 (92 1/2")	<b>PLATFORM LIFT TWO-CYLINDER</b> <b>SEE &gt; <a href="#">MR414005.HTML</a> FOR DRAWING AND PARTS INFORMATION.</b>  CYLINDER W/SEQ. VALVE ASSY._ ITEM 1 - RAP93139 (4.8” STROKE) REPLACES AP44387 CYLINDER ASSEMBLY_____ ITEM 2 - RAP93140 (4.8” STROKE) REPLACES AP44395
<b>MECHANISM</b> AP51435 (126")	<b>PLATFORM LIFT THREE-CYLINDER</b> <b>SEE &gt; <a href="#">MR414010.HTML</a> FOR DRAWING AND PARTS INFORMATION.</b>  CYLINDER W/SEQ. VALVE ASSY._ ITEM 1 - RAP93139 (4.8” STROKE) REPLACES AP44387 CYLINDER ASSEMBLY_____ ITEM 2 - RAP93140 (4.8” STROKE) REPLACES AP44395

<b>STEP Systems</b>	
<b>MECHANISM</b> AP52354	<b>STEP ASSEMBLY – 28.75” STROKE</b>  CYLINDER ASSEMBLIES_____ RAP93541 (33.7” STROKE) -REPLACES AP52094 RAP93540 (4.8” STROKE) -REPLACES AP52080 HOSE ASSEMBLIES_____ RAP50556 (AP50556) RAP51975 (AP51975) RAP49244 (AP49244) RAP52043 (AP52043)