
**ROOM EXTENSION ASSEMBLIES
GUIDE PAGE
"MONACO COACH CORPORATION" (PAGE 4 OF 4)**

PROCEDURE: SEE "MONACO COACH CORPORATION" (PAGE 1 OF 4)

MECHANISM AP40226 AP40227	UNIVERSAL STRAIGHT OUT - 18.0" STROKE - AP40172 KIT SEE MR41.2685 FOR DRAWING AND PARTS INFORMATION. CYLINDER ASSEMBLY _____ ITEM 1 - RAP92075 (20.5" STROKE) - REPLACES AP39251 TUBE KIT _____ ITEM 2 - RAP92092 - REPLACES AP39321 HOSE ASSEMBLIES _____ ITEM 4 - RAP91535 (AP24661) ITEM 5 - RAP92510 (AP24664)
MECHANISM AP41642 AP41643	UNIVERSAL STRAIGHT OUT - 18.0" STROKE - AP41534 KIT SEE MR41.2685 FOR DRAWING AND PARTS INFORMATION. CYLINDER ASSEMBLY _____ ITEM 1 - RAP92076 (30.5" STROKE) - REPLACES AP38072 TUBE KIT _____ ITEM 2 - RAP92079 - REPLACES AP38267 HOSE ASSEMBLIES _____ ITEM 4 - RAP91531 (AP24657) ITEM 5 - RAP91420 (AP24659)