

**ROOM EXTENSION ASSEMBLIES
GUIDE PAGE
"MORRISON VIP COACH" (PAGE 4 OF 5)**

PROCEDURE: SEE "MORRISON VIP COACH" (PAGE 1 OF 5)

MECHANISM AP36205 AP36206	UNIVERSAL LEVEL OUT ROOM EXTENSION - 25.0" STROKE (WITH SYNC. CYLINDER) - AP35154 KIT SEE MR41.2683 FOR DRAWING AND PARTS INFORMATION. CYLINDER ASSEMBLY _____ ITEM 1 - RAP91702 (34.0" STROKE) - REPLACES AP31461 LIFT CYLINDER ASSEMBLY _____ ITEM 10 - RAP91992 (2.75" LIFT) - REPLACES AP34390 SYNCHRONIZING CYLINDER _____ ITEM 3 - RAP90440 (10.095" STROKE) - REPLACES AP16509 LIFT SYNCHRONIZING CYLINDER _____ ITEM 11 - RAP92473 - REPLACES AP34576 TUBE KIT _____ ITEM 2 - RAP91703 - REPLACES AP31486 HOSE ASSEMBLIES _____ ITEM 4 - RAP90872 (AP24632) ITEM 5 - RAP91421 (AP24818)
MECHANISM AP36590 AP36591	LATERAL ARM ROOM EXTENSION - 20.0" STROKE (WITH SYNCHRONIZING CYLINDER) - AP36589 KIT SEE MR41.2825 FOR DRAWING AND PARTS INFORMATION. CYLINDER ASSEMBLY _____ ITEM 1 - RAP91351 (6.775" STROKE) - REPLACES AP27997 SYNCHRONIZING CYLINDER _____ ITEM 3 - RAP90524 (2.385" STROKE) - REPLACES AP14881 TUBE KIT _____ ITEM 2 - RAP91774 - REPLACES AP28035 HOSE ASSEMBLIES _____ ITEM 4 - RAP91574 (AP24627) ITEM 5 - RAP91573 (AP32672)
MECHANISM AP36593 AP36594	LATERAL ARM ROOM EXTENSION - 16.0" STROKE (WITH SYNCHRONIZING CYLINDER) - AP36592 KIT SEE MR41.2825 FOR DRAWING AND PARTS INFORMATION. CYLINDER ASSEMBLY _____ ITEM 1 - RAP91203 (6.150" STROKE) - REPLACES AP26255 SYNCHRONIZING CYLINDER _____ ITEM 3 - RAP91013 (1.810" STROKE) - REPLACES AP28566 TUBE KIT _____ ITEM 2 - RAP91226 - REPLACES AP27031 HOSE ASSEMBLIES _____ ITEM 4 - RAP91574 (AP24627) ITEM 5 - RAP91573 (AP32672)
MECHANISM AP36598 AP36599	LATERAL ARM ROOM EXTENSION - 16.0" STROKE (WITH SYNCHRONIZING CYLINDER) - AP36597 KIT SEE MR41.2825 FOR DRAWING AND PARTS INFORMATION. CYLINDER ASSEMBLY _____ ITEM 1 - RAP91203 (6.150" STROKE) - REPLACES AP26255 SYNCHRONIZING CYLINDER _____ ITEM 3 - RAP91013 (1.810" STROKE) - REPLACES AP28566 TUBE KIT _____ ITEM 2 - RAP91226 - REPLACES AP27031 HOSE ASSEMBLIES _____ ITEM 4 - RAP91574 (AP24627) ITEM 5 - RAP91573 (AP32672)
MECHANISM AP36608 AP36609	LATERAL ARM ROOM EXTENSION - 20.0" STROKE (WITH SYNCHRONIZING CYLINDER) - AP36607 KIT SEE MR41.2825 FOR DRAWING AND PARTS INFORMATION. CYLINDER ASSEMBLY _____ ITEM 1 - RAP91351 (6.775" STROKE) - REPLACES AP27997 SYNCHRONIZING CYLINDER _____ ITEM 3 - RAP90524 (2.385" STROKE) - REPLACES AP14881 TUBE KIT _____ ITEM 2 - RAP91774 - REPLACES AP28035 HOSE ASSEMBLIES _____ ITEM 4 - RAP91574 (AP24627) ITEM 5 - RAP91573 (AP32672)
MECHANISM AP38251 AP38252	UNIVERSAL STRAIGHT OUT - 30.0" STROKE (WITH SYNCHRONIZING CYLINDER) - AP42236 KIT SEE MR41.2685 FOR DRAWING AND PARTS INFORMATION. CYLINDER ASSEMBLY _____ ITEM 1 - RAP92076 (30.5" STROKE) - REPLACES AP38072 SYNCHRONIZING CYLINDER _____ ITEM 3 - RAP92077 (10.540" STROKE) - REPLACES AP37881 TUBE KIT _____ ITEM 2 - RAP92079 - REPLACES AP38267 HOSE ASSEMBLIES _____ ITEM 4 - RAP90872 (AP24632) ITEM 5 - RAP91421 (AP24818)
MECHANISM AP38383 AP38384	UNIVERSAL LEVEL OUT - 26.0" STROKE (WITH SYNCHRONIZING CYLINDER) - AP40756 KIT SEE MR41.2690 FOR DRAWING AND PARTS INFORMATION. CYLINDER ASSEMBLY _____ ITEM 1 - RAP92076 (30.5" STROKE) - REPLACES AP38072 LIFT CYLINDER ASSEMBLY _____ ITEM 11 - RAP92260 (2.75" LIFT) - REPLACES AP38604 SYNCHRONIZING CYLINDER _____ ITEM 3 - RAP92469 (9.130" STROKE) - REPLACES AP39275 LIFT SYNCHRONIZING CYLINDER _____ ITEM 12 - RAP92316 - REPLACES AP38264 TUBE KIT _____ ITEM 2 - RAP92079 - REPLACES AP38267 HOSE ASSEMBLIES _____ ITEM 4 - RAP90872 (AP24632) ITEM 5 - RAP91421 (AP24818)