

**ROOM EXTENSION ASSEMBLIES
GUIDE PAGE
"MORRISON VIP COACH" (PAGE 5 OF 5)**

PROCEDURE: SEE "MORRISON VIP COACH" (PAGE 1 OF 5)

MECHANISM AP38944 AP38945	<p>UNIVERSAL LEVEL OUT - 30.0" STROKE (WITH SYNCHRONIZING CYLINDER) - AP40757 KIT</p> <p>SEE MR41.2690 FOR DRAWING AND PARTS INFORMATION.</p> <p>CYLINDER ASSEMBLY _____ ITEM 1 - RAP92076 (30.5" STROKE) - REPLACES AP38072 LIFT CYLINDER ASSEMBLY _____ ITEM 11 - RAP92260 (2.75" LIFT) - REPLACES AP38604 SYNCHRONIZING CYLINDER _____ ITEM 3 - RAP92077 (10.540" STROKE) - REPLACES AP37881 LIFT SYNCHRONIZING CYLINDER _____ ITEM 12 - RAP92316 - REPLACES AP38264 TUBE KIT _____ ITEM 2 - RAP92079 - REPLACES AP38267 HOSE ASSEMBLIES _____ ITEM 4 - RAP90872 (AP24632) ITEM 5 - RAP91421 (AP24818)</p>
MECHANISM AP39645 AP39646	<p>UNIVERSAL STRAIGHT OUT - 26.0" STROKE (WITH SYNC. CYLINDER) - AP40755 AND AP49898 KITS</p> <p>SEE MR41.2685 FOR DRAWING AND PARTS INFORMATION.</p> <p>CYLINDER ASSEMBLY _____ ITEM 1 - RAP92076 (30.5" STROKE) - REPLACES AP38072 SYNCHRONIZING CYLINDER _____ ITEM 3 - RAP92469 (9.130" STROKE) - REPLACES AP39275 TUBE KIT _____ ITEM 2 - RAP92079 - REPLACES AP38267 HOSE ASSEMBLIES _____ ITEM 4 - RAP90872 (AP24632) ITEM 5 - RAP91421 (AP24818)</p>
MECHANISM AP40822 AP40823	<p>UNIVERSAL STRAIGHT OUT - 20.0" STROKE (WITH SYNCHRONIZING CYLINDER) - AP48831 KIT</p> <p>SEE MR41.2685 FOR DRAWING AND PARTS INFORMATION.</p> <p>CYLINDER ASSEMBLY _____ ITEM 1 - RAP92075 (20.5" STROKE) - REPLACES AP39251 SYNCHRONIZING CYLINDER _____ ITEM 3 - RAP92099 (7.010" STROKE) - REPLACES AP39221 TUBE KIT _____ ITEM 2 - RAP92092 - REPLACES AP39321 HOSE ASSEMBLIES _____ ITEM 4 - RAP91566 (AP24631) ITEM 5 - RAP91568 (AP24637)</p>