

MECHANISM AP16627	SINGLE CYLINDER ROOM EXTENSION – 24.0” STROKE – AP16626 KIT SEE > MR41.1101.HTML FOR DRAWING AND PARTS INFORMATION. CYLINDER ASSEMBLY_____ ITEM 1 - RAP90688 (27.0” STROKE) REPLACES AP15818 HOSE ASSEMBLIES_____ ITEM 3 - RAP50907 (AP50907) ITEM 4 - RAP16434 (AP16434)
MECHANISM AP16904	SINGLE CYLINDER ROOM EXTENSION – 24.0” STROKE – AP16903 KIT SEE > MR41.1101.HTML FOR DRAWING AND PARTS INFORMATION. CYLINDER ASSEMBLY_____ ITEM 1 - RAP90688 (27.0” STROKE) REPLACES AP15818 HOSE ASSEMBLIES_____ ITEM 3 - RAP50907 (AP50907) ITEM 4 - RAP16434 (AP16434)
MECHANISM AP17144	SINGLE CYLINDER ROOM EXTENSION – 24.0” STROKE – AP17143 KIT SEE > MR41.1101.HTML FOR DRAWING AND PARTS INFORMATION. CYLINDER ASSEMBLY_____ ITEM 1 - RAP90688 (27.0” STROKE) REPLACES AP15818 HOSE ASSEMBLIES_____ ITEM 3 - RAP50907 (AP50907) ITEM 4 - RAP16434 (AP16434)
MECHANISM AP17448	SINGLE CYLINDER ROOM EXTENSION – 24.0” STROKE – AP17447 KIT SEE > MR41.1101.HTML FOR DRAWING AND PARTS INFORMATION. CYLINDER ASSEMBLY_____ ITEM 1 - RAP90688 (27.0” STROKE) REPLACES AP15818 HOSE ASSEMBLIES_____ ITEM 3 - RAP50907 (AP50907) ITEM 4 - RAP16434 (AP16434)
MECHANISM AP17657	SINGLE CYLINDER ROOM EXTENSION – 24.0” STROKE – AP17656 KIT SEE > MR41.1101.HTML FOR DRAWING AND PARTS INFORMATION. CYLINDER ASSEMBLY_____ ITEM 1 - RAP90688 (27.0” STROKE) REPLACES AP15818 HOSE ASSEMBLIES_____ ITEM 3 - RAP50907 (AP50907) ITEM 4 - RAP16434 (AP16434)
MECHANISM AP17698	SINGLE CYLINDER ROOM EXTENSION – 24.0” STROKE – AP17697 KIT SEE > MR41.1101.HTML FOR DRAWING AND PARTS INFORMATION. CYLINDER ASSEMBLY_____ ITEM 1 - RAP90688 (27.0” STROKE) REPLACES AP15818 HOSE ASSEMBLIES_____ ITEM 3 - RAP50907 (AP50907) ITEM 4 - RAP16434 (AP16434)
MECHANISM AP18331 AP18332	VERTICAL ARM ROOM EXTENSION – 24.0” STROKE (WITH SYNCHRONIZING CYLINDER) AP18708 KIT SEE > MR41.2505.HTML FOR DRAWING AND PARTS INFORMATION. CYLINDER ASSEMBLY_____ ITEM 1 - RAP90426 (9.689” STROKE) REPLACES AP14028 SYNCHRONIZING CYLINDER_____ ITEM 6 - RAP90427 (3.815” STROKE) REPLACES AP14027 HOSE ASSEMBLIES_____ ITEM 4 - RAP24662 (AP24662) ITEM 5 - RAP24653 (AP24653)
MECHANISM AP18365	SINGLE CYLINDER ROOM EXTENSION – 24.0” STROKE – AP18364 KIT SEE > MR41.1101.HTML FOR DRAWING AND PARTS INFORMATION. CYLINDER ASSEMBLY_____ ITEM 1 - RAP90688 (27.0” STROKE) REPLACES AP15818 HOSE ASSEMBLIES_____ ITEM 3 - RAP50907 (AP50907) ITEM 4 - RAP16434 (AP16434)
MECHANISM AP18423	SINGLE CYLINDER GENERATOR EXTENSION – 28.0” STROKE – AP18460 KIT CYLINDER ASSEMBLY_____ RAP91597 (28.0” STROKE) - REPLACES AP18365
MECHANISM AP18704	SINGLE CYLINDER ROOM EXTENSION – 24.0” STROKE – AP18703 KIT SEE > MR41.1101.HTML FOR DRAWING AND PARTS INFORMATION. CYLINDER ASSEMBLY_____ ITEM 1 - RAP90688 (27.0” STROKE) REPLACES AP15818 HOSE ASSEMBLIES_____ ITEM 3 - RAP50907 (AP50907) ITEM 4 - RAP16434 (AP16434)

MECHANISM AP19103	SINGLE CYLINDER ROOM EXTENSION – 24.0” STROKE – AP19102 KIT SEE > MR41.1101.HTML FOR DRAWING AND PARTS INFORMATION. CYLINDER ASSEMBLY_____ ITEM 1 - RAP90688 (27.0” STROKE) REPLACES AP15818 HOSE ASSEMBLIES_____ ITEM 3 - RAP50907 (AP50907) ITEM 4 - RAP16434 (AP16434)
MECHANISM AP19351 AP19352	VERTICAL ARM ROOM EXTENSION – 22.0” STROKE (WITH SYNC. CYLINDER) AP19350 AND AP20391 KITS SEE > MR41.2505.HTML FOR DRAWING AND PARTS INFORMATION. CYLINDER ASSEMBLY_____ ITEM 1 - RAP90586 (8.825” STROKE) REPLACES AP17191 SYNCHRONIZING CYLINDER_____ ITEM 6 - RAP90587 (3.455” STROKE) REPLACES AP17199 HOSE ASSEMBLIES_____ ITEM 4 - RAP49247 (AP49247) ITEM 5 - RAP24653 (AP24653)
MECHANISM AP19598	SINGLE CYLINDER ROOM EXTENSION – 24.0” STROKE – AP19597 KIT SEE > MR41.1101.HTML FOR DRAWING AND PARTS INFORMATION. CYLINDER ASSEMBLY_____ ITEM 1 - RAP90688 (27.0” STROKE) REPLACES AP15818 HOSE ASSEMBLIES_____ ITEM 3 - RAP50907 (AP50907) ITEM 4 - RAP16434 (AP16434)
MECHANISM AP19899	SINGLE CYLINDER ROOM EXTENSION – 24.0” STROKE – AP19897 KIT NO INFORMATION AVAILABLE
MECHANISM AP20248	SINGLE CYLINDER ROOM EXTENSION – 24.0” STROKE – AP20247 KIT SEE > MR41.1101.HTML FOR DRAWING AND PARTS INFORMATION. CYLINDER ASSEMBLY_____ ITEM 1 - RAP90688 (27.0” STROKE) REPLACES AP15818 HOSE ASSEMBLIES_____ ITEM 3 - RAP50907 (AP50907) ITEM 4 - RAP16434 (AP16434)
MECHANISM AP20385	SINGLE CYLINDER ROOM EXTENSION – 24.0” STROKE – AP20384 KIT SEE > MR41.1101.HTML FOR DRAWING AND PARTS INFORMATION. CYLINDER ASSEMBLY_____ ITEM 1 - RAP90688 (27.0” STROKE) REPLACES AP15818 HOSE ASSEMBLIES_____ ITEM 3 - RAP24632 (AP24632) ITEM 4 - RAP53984 (AP53984)
MECHANISM AP20389	SINGLE CYLINDER ROOM EXTENSION – 24.0” STROKE – AP20388 KIT NO INFORMATION AVAILABLE
MECHANISM AP20531	SINGLE CYLINDER ROOM EXTENSION – 24.0” STROKE – AP20530 KIT SEE > MR41.1101.HTML FOR DRAWING AND PARTS INFORMATION. CYLINDER ASSEMBLY_____ ITEM 1 - RAP90688 (27.0” STROKE) REPLACES AP15818 HOSE ASSEMBLIES_____ ITEM 3 - RAP50907 (AP50907) ITEM 4 - RAP16434 (AP16434)
MECHANISM AP20702	SINGLE CYLINDER ROOM EXTENSION – 24.0” STROKE – AP17885 KIT SEE > MR41.1101.HTML FOR DRAWING AND PARTS INFORMATION. CYLINDER ASSEMBLY_____ ITEM 1 - RAP90688 (27.0” STROKE) REPLACES AP15818 HOSE ASSEMBLIES_____ ITEM 3 - RAP24632 (AP24632) ITEM 4 - RAP53984 (AP53984)
MECHANISM AP20704	SINGLE CYLINDER ROOM EXTENSION – 24.0” STROKE – AP18169 KIT SEE > MR41.1101.HTML FOR DRAWING AND PARTS INFORMATION. CYLINDER ASSEMBLY_____ ITEM 1 - RAP90688 (27.0” STROKE) REPLACES AP15818 HOSE ASSEMBLIES_____ ITEM 3 - RAP24632 (AP24632) ITEM 4 - RAP53984 (AP53984)

MECHANISM AP21177	SINGLE CYLINDER ROOM EXTENSION – 24.0” STROKE – AP21176 KIT SEE > MR41.1101.HTML FOR DRAWING AND PARTS INFORMATION. CYLINDER ASSEMBLY_____ ITEM 1 - RAP90688 (27.0” STROKE) REPLACES AP15818 HOSE ASSEMBLIES_____ ITEM 3 - RAP24632 (AP24632) ITEM 4 - RAP53984 (AP53984)
MECHANISM AP21180	SINGLE CYLINDER ROOM EXTENSION – 24.0” STROKE – AP21179 KIT SEE > MR41.1101.HTML FOR DRAWING AND PARTS INFORMATION. CYLINDER ASSEMBLY_____ ITEM 1 - RAP90688 (27.0” STROKE) REPLACES AP15818 HOSE ASSEMBLIES_____ ITEM 3 - RAP24632 (AP24632) ITEM 4 - RAP53984 (AP53984)
MECHANISM AP21245 AP21246	VERTICAL ARM ROOM EXTENSION – 22.0” STROKE (WITH SYNC. CYL.) – AP21236, AP22671, AND AP22936 KITS SEE > MR41.2505.HTML FOR DRAWING AND PARTS INFORMATION. CYLINDER ASSEMBLY_____ ITEM 1 - RAP90586 (8.825” STROKE) REPLACES AP17191 SYNCHRONIZING CYLINDER_____ ITEM 6 - RAP90587 (3.455” STROKE) REPLACES AP17199 HOSE ASSEMBLIES_____ ITEM 4 - RAP49247 (AP49247) ITEM 5 - RAP24653 (AP24653)
MECHANISM AP21556	SINGLE CYLINDER ROOM EXTENSION – 24.0” STROKE – AP21550 KIT SEE > MR41.1101.HTML FOR DRAWING AND PARTS INFORMATION. CYLINDER ASSEMBLY_____ ITEM 1 - RAP90688 (27.0” STROKE) REPLACES AP15818 HOSE ASSEMBLIES_____ ITEM 3 - RAP24632 (AP24632) ITEM 4 - RAP53984 (AP53984)
MECHANISM AP21570	SINGLE CYLINDER ROOM EXTENSION – 24.0” STROKE – AP21569 KIT SEE > MR41.1101.HTML FOR DRAWING AND PARTS INFORMATION. CYLINDER ASSEMBLY_____ ITEM 1 - RAP90688 (27.0” STROKE) REPLACES AP15818 HOSE ASSEMBLIES_____ ITEM 3 - RAP50907 (AP50907) ITEM 4 - RAP16434 (AP16434)
MECHANISM AP21642	SINGLE CYLINDER ROOM EXTENSION – 24.0” STROKE – AP21641 KIT SEE > MR41.1101.HTML FOR DRAWING AND PARTS INFORMATION. CYLINDER ASSEMBLY_____ ITEM 1 - RAP90688 (27.0” STROKE) REPLACES AP15818 HOSE ASSEMBLIES_____ ITEM 3 - RAP50907 (AP50907) ITEM 4 - RAP16434 (AP16434)
MECHANISM AP21674 AP21675	VERTICAL ARM ROOM EXTENSION – 24.0” STROKE (WITH SYNCHRONIZING CYLINDER) AP21643 KIT SEE > MR41.2505.HTML FOR DRAWING AND PARTS INFORMATION. CYLINDER ASSEMBLY_____ ITEM 1 - RAP90426 (9.689” STROKE) REPLACES AP14028 SYNCHRONIZING CYLINDER_____ ITEM 6 - RAP90427 (3.815” STROKE) REPLACES AP14027 HOSE ASSEMBLIES_____ ITEM 4 - RAP49247 (AP49247) ITEM 5 - RAP24653 (AP24653)
MECHANISM AP22030	SINGLE CYLINDER ROOM EXTENSION – 24.0” STROKE – AP22029 KIT SEE > MR41.1101.HTML FOR DRAWING AND PARTS INFORMATION. CYLINDER ASSEMBLY_____ ITEM 1 - RAP90688 (27.0” STROKE) REPLACES AP15818 HOSE ASSEMBLIES_____ ITEM 3 - RAP24632 (AP24632) ITEM 4 - RAP53984 (AP53984)
MECHANISM AP22034	SINGLE CYLINDER ROOM EXTENSION – 24.0” STROKE – AP22033 KIT SEE > MR41.1101.HTML FOR DRAWING AND PARTS INFORMATION. CYLINDER ASSEMBLY_____ ITEM 1 - RAP90688 (27.0” STROKE) REPLACES AP15818 HOSE ASSEMBLIES_____ ITEM 3 - RAP24632 (AP24632) ITEM 4 - RAP53984 (AP53984)

MECHANISM AP22124	SINGLE CYLINDER ROOM EXTENSION – 24.0” STROKE – AP22123 KIT SEE > MR41.1101.HTML FOR DRAWING AND PARTS INFORMATION. CYLINDER ASSEMBLY_____ ITEM 1 - RAP90688 (27.0” STROKE) REPLACES AP15818 HOSE ASSEMBLIES_____ ITEM 3 - RAP24632 (AP24632) ITEM 4 - RAP53984 (AP53984)
MECHANISM AP23086	SINGLE CYLINDER ROOM EXTENSION – 24.0” STROKE – AP23085 KIT SEE > MR41.1101.HTML FOR DRAWING AND PARTS INFORMATION. CYLINDER ASSEMBLY_____ ITEM 1 - RAP90688 (27.0” STROKE) REPLACES AP15818 HOSE ASSEMBLIES_____ ITEM 3 - RAP24632 (AP24632) ITEM 4 - RAP53984 (AP53984)
MECHANISM AP23750 AP24579	TRAIN DRIVE ROOM EXTENSION – (4) CYLINDERS – 20.0” STROKE (WITH SYNCHRONIZING CYLINDER) AP23012, AP25585, AP24892, AND AP25709 KITS SEE > MR41.2650.HTML FOR DRAWING AND PARTS INFORMATION. CYLINDER ASSEMBLY_____ ITEM 1 - AP25500 - CONTACT HWH FOR REPLACEMENT SYNCHRONIZING CYLINDER_____ RAP90857 (2.78” STROKE)–REPLACES AP23247 SEE > MR41.8000.HTML FOR ADDITIONAL SYNC CYL REPLACEMENT PARTS. HOSE ASSEMBLIES_____ ITEM 1A - SPECIAL HOSE - CONTACT HWH HOSE ASSEMBLIES_____ ITEM 2 - RAP24658 - REPLACES AP24568 (TOP ROD END) HOSE ASSEMBLIES_____ ITEM 2 - RAP24656 - REPLACES AP24656 (TOP CAP END) HOSE ASSEMBLIES_____ ITEM 2 - RAP24667 - REPLACES AP24667 (BOTTOM ROD END) HOSE ASSEMBLIES_____ ITEM 2 - RAP24666 - REPLACES AP24666 (BOTTOM CAP END)
MECHANISM AP24054	SINGLE CYLINDER ROOM EXTENSION – 24.0” STROKE – AP24053 KIT SEE > MR41.1101.HTML FOR DRAWING AND PARTS INFORMATION. CYLINDER ASSEMBLY_____ ITEM 1 - RAP90688 (27.0” STROKE) REPLACES AP15818 HOSE ASSEMBLIES_____ ITEM 3 - RAP24632 (AP24632) ITEM 4 - RAP53984 (AP53984)
MECHANISM AP24342	SINGLE CYLINDER ROOM EXTENSION – 24.0” STROKE – AP23325 KIT SEE > MR41.1101.HTML FOR DRAWING AND PARTS INFORMATION. CYLINDER ASSEMBLY_____ ITEM 1 - RAP90688 (27.0” STROKE) REPLACES AP15818 HOSE ASSEMBLIES_____ ITEM 3 - RAP24632 (AP24632) ITEM 4 - RAP53984 (AP53984)
MECHANISM AP21674 AP21675	VERTICAL ARM ROOM EXTENSION – 22.0” STROKE (WITH SYNCHRONIZING CYLINDER) AP24602, AP24841, AND AP26533 KITS SEE > MR41.2505.HTML FOR DRAWING AND PARTS INFORMATION. CYLINDER ASSEMBLY_____ ITEM 1 - AP24522 (9.689” STROKE) CONTACT HWH CORPORATION SYNCHRONIZING ASSEMBLY_____ ITEM 6 - RAP91016 (3.600” STROKE) REPLACES AP24532 HOSE ASSEMBLIES_____ ITEM 4 - RAP24658 (AP24658) ITEM 5 - RAP24653 (AP24653)
MECHANISM AP24583	SINGLE CYLINDER ROOM EXTENSION – 24.0” STROKE – AP24582 KIT SEE > MR41.1101.HTML FOR DRAWING AND PARTS INFORMATION. CYLINDER ASSEMBLY_____ ITEM 1 - RAP90688 (27.0” STROKE) REPLACES AP15818 HOSE ASSEMBLIES_____ ITEM 3 - RAP50907 (AP50907) ITEM 4 - RAP16434 (AP16434)

