

ROOM EXTENSION ASSEMBLIES

GUIDE PAGE

"NEWELL" (PAGE 2 OF 5)

PROCEDURE: SEE: "NEWELL" (PAGE 1 OF 5)

MECHANISM AP17448	<p>SINGLE CYLINDER ROOM EXTENSION - 24.0" STROKE - AP17447 KIT</p> <p>SEE MR41.1101 FOR DRAWING AND PARTS INFORMATION. CYLINDER ASSEMBLY _____ ITEM 1 - RAP90688 (27.0" STROKE) - REPLACES AP15818 HOSE ASSEMBLIES _____ ITEM 3 - RAP91750 (AP13842) ITEM 4 - RAP91751 (AP16434)</p>
MECHANISM AP17657	<p>SINGLE CYLINDER ROOM EXTENSION - 24.0" STROKE - AP17656 KIT</p> <p>SEE MR41.1101 FOR DRAWING AND PARTS INFORMATION. CYLINDER ASSEMBLY _____ ITEM 1 - RAP90688 (27.0" STROKE) - REPLACES AP15818 HOSE ASSEMBLIES _____ ITEM 3 - RAP91750 (AP13842) ITEM 4 - RAP91751 (AP16434)</p>
MECHANISM AP17698	<p>SINGLE CYLINDER ROOM EXTENSION - 24.0" STROKE - AP17697 KIT</p> <p>SEE MR41.1101 FOR DRAWING AND PARTS INFORMATION. CYLINDER ASSEMBLY _____ ITEM 1 - RAP90688 (27.0" STROKE) - REPLACES AP15818 HOSE ASSEMBLIES _____ ITEM 3 - RAP91750 (AP13842) ITEM 4 - RAP91751 (AP16434)</p>
MECHANISM AP18331 AP18332	<p>VERTICAL ARM ROOM EXTENSION - 24.0" STROKE (WITH SYNCHRONIZING CYLINDER) - AP18708 KIT</p> <p>SEE MR41.2505 FOR DRAWING AND PARTS INFORMATION. CYLINDER ASSEMBLY _____ ITEM 1 - RAP90426 (9.689" STROKE) - REPLACES AP14028 SYNCHRONIZING CYLINDER _____ ITEM 6 - RAP90427 (3.815" STROKE) - REPLACES AP14027 HOSE ASSEMBLIES _____ ITEM 4 - RAP91536 (AP24662) ITEM 5 - RAP90321 (AP24653)</p>
MECHANISM AP18365	<p>SINGLE CYLINDER ROOM EXTENSION - 24.0" STROKE - AP18364 KIT</p> <p>SEE MR41.1101 FOR DRAWING AND PARTS INFORMATION. CYLINDER ASSEMBLY _____ ITEM 1 - RAP90688 (27.0" STROKE) - REPLACES AP15818 HOSE ASSEMBLIES _____ ITEM 3 - RAP91750 (AP13842) ITEM 4 - RAP91751 (AP16434)</p>
MECHANISM AP18423	<p>SINGLE CYLINDER GENERATOR EXTENSION - 28.0" STROKE - AP18460 KIT</p> <p>CYLINDER ASSEMBLY _____ RAP91597 (28.0" STROKE) - REPLACES AP18365</p>
MECHANISM AP18704	<p>SINGLE CYLINDER ROOM EXTENSION - 24.0" STROKE - AP18703 KIT</p> <p>SEE MR41.1101 FOR DRAWING AND PARTS INFORMATION. CYLINDER ASSEMBLY _____ ITEM 1 - RAP90688 (27.0" STROKE) - REPLACES AP15818 HOSE ASSEMBLIES _____ ITEM 3 - RAP91750 (AP13842) ITEM 4 - RAP91751 (AP16434)</p>
MECHANISM AP19103	<p>SINGLE CYLINDER ROOM EXTENSION - 24.0" STROKE - AP19102 KIT</p> <p>SEE MR41.1101 FOR DRAWING AND PARTS INFORMATION. CYLINDER ASSEMBLY _____ ITEM 1 - RAP90688 (27.0" STROKE) - REPLACES AP15818 HOSE ASSEMBLIES _____ ITEM 3 - RAP91750 (AP13842) ITEM 4 - RAP91751 (AP16434)</p>
MECHANISM AP19351 AP19352	<p>VERTICAL ARM ROOM EXTENSION - 22.0" STROKE (WITH SYNC. CYLINDER) - AP19350 AND AP20391 KITS</p> <p>SEE MR41.2505 FOR DRAWING AND PARTS INFORMATION. CYLINDER ASSEMBLY _____ ITEM 1 - RAP90586 (8.825" STROKE) - REPLACES AP17191 SYNCHRONIZING CYLINDER _____ ITEM 6 - RAP90587 (3.455" STROKE) - REPLACES AP17199 HOSE ASSEMBLIES _____ ITEM 4 - RAP90790 (AP20751) ITEM 5 - RAP90321 (AP24653)</p>
MECHANISM AP19598	<p>SINGLE CYLINDER ROOM EXTENSION - 24.0" STROKE - AP19597 KIT</p> <p>SEE MR41.1101 FOR DRAWING AND PARTS INFORMATION. CYLINDER ASSEMBLY _____ ITEM 1 - RAP90688 (27.0" STROKE) - REPLACES AP15818 HOSE ASSEMBLIES _____ ITEM 3 - RAP91750 (AP13842) ITEM 4 - RAP91751 (AP16434)</p>
MECHANISM AP19899	<p>SINGLE CYLINDER ROOM EXTENSION - 24.0" STROKE - AP19897 KIT</p> <p>NO INFORMATION AVAILABLE</p>