

ROOM EXTENSION ASSEMBLIES

GUIDE PAGE

"NEWELL" (PAGE 3 OF 5)

PROCEDURE: SEE: "NEWELL" (PAGE 1 OF 5)

MECHANISM AP20248	<p>SINGLE CYLINDER ROOM EXTENSION - 24.0" STROKE - AP20247 KIT</p> <p>SEE MR41.1101 FOR DRAWING AND PARTS INFORMATION. CYLINDER ASSEMBLY _____ ITEM 1 - RAP90688 (27.0" STROKE) - REPLACES AP15818 HOSE ASSEMBLIES _____ ITEM 3 - RAP91750 (AP13842) ITEM 4 - RAP91751 (AP16434)</p>
MECHANISM AP20385	<p>SINGLE CYLINDER ROOM EXTENSION - 24.0" STROKE - AP20384 KIT</p> <p>SEE MR41.1101 FOR DRAWING AND PARTS INFORMATION. CYLINDER ASSEMBLY _____ ITEM 1 - RAP90688 (27.0" STROKE) - REPLACES AP15818 HOSE ASSEMBLIES _____ ITEM 3 - RAP90872 (AP24632) ITEM 4 - RAP90871 (AP24628)</p>
MECHANISM AP20389	<p>SINGLE CYLINDER ROOM EXTENSION - 24.0" STROKE - AP20388 KIT</p> <p>NO INFORMATION AVAILABLE</p>
MECHANISM AP20531	<p>SINGLE CYLINDER ROOM EXTENSION - 24.0" STROKE - AP20530 KIT</p> <p>SEE MR41.1101 FOR DRAWING AND PARTS INFORMATION. CYLINDER ASSEMBLY _____ ITEM 1 - RAP90688 (27.0" STROKE) - REPLACES AP15818 HOSE ASSEMBLIES _____ ITEM 3 - RAP91750 (AP13842) ITEM 4 - RAP91751 (AP16434)</p>
MECHANISM AP20702	<p>SINGLE CYLINDER ROOM EXTENSION - 24.0" STROKE - AP17885 KIT</p> <p>SEE MR41.1101 FOR DRAWING AND PARTS INFORMATION. CYLINDER ASSEMBLY _____ ITEM 1 - RAP90688 (27.0" STROKE) - REPLACES AP15818 HOSE ASSEMBLIES _____ ITEM 3 - RAP90872 (AP24632) ITEM 4 - RAP90871 (AP24628)</p>
MECHANISM AP20704	<p>SINGLE CYLINDER ROOM EXTENSION - 24.0" STROKE - AP18169 KIT</p> <p>SEE MR41.1101 FOR DRAWING AND PARTS INFORMATION. CYLINDER ASSEMBLY _____ ITEM 1 - RAP90688 (27.0" STROKE) - REPLACES AP15818 HOSE ASSEMBLIES _____ ITEM 3 - RAP90872 (AP24632) ITEM 4 - RAP90871 (AP24628)</p>
MECHANISM AP21177	<p>SINGLE CYLINDER ROOM EXTENSION - 24.0" STROKE - AP21176 KIT</p> <p>SEE MR41.1101 FOR DRAWING AND PARTS INFORMATION. CYLINDER ASSEMBLY _____ ITEM 1 - RAP90688 (27.0" STROKE) - REPLACES AP15818 HOSE ASSEMBLIES _____ ITEM 3 - RAP90872 (AP24632) ITEM 4 - RAP90871 (AP24628)</p>
MECHANISM AP21180	<p>SINGLE CYLINDER ROOM EXTENSION - 24.0" STROKE - AP21179 KIT</p> <p>SEE MR41.1101 FOR DRAWING AND PARTS INFORMATION. CYLINDER ASSEMBLY _____ ITEM 1 - RAP90688 (27.0" STROKE) - REPLACES AP15818 HOSE ASSEMBLIES _____ ITEM 3 - RAP90872 (AP24632) ITEM 4 - RAP90871 (AP24628)</p>
MECHANISM AP21245 AP21246	<p>VERTICAL ARM ROOM EXTENSION - 22.0" STROKE (WITH SYNC. CYL.) - AP21236, AP22671 AND AP22936 KITS</p> <p>SEE MR41.2505 FOR DRAWING AND PARTS INFORMATION. CYLINDER ASSEMBLY _____ ITEM 1 - RAP90586 (8.825" STROKE) - REPLACES AP17191 SYNCHRONIZING CYLINDER _____ ITEM 6 - RAP90587 (3.455" STROKE) - REPLACES AP17199 HOSE ASSEMBLIES _____ ITEM 4 - RAP90790 (AP20751) ITEM 5 - RAP90321 (AP24653)</p>
MECHANISM AP21556	<p>SINGLE CYLINDER ROOM EXTENSION - 24.0" STROKE - AP21550 KIT</p> <p>SEE MR41.1101 FOR DRAWING AND PARTS INFORMATION. CYLINDER ASSEMBLY _____ ITEM 1 - RAP90688 (27.0" STROKE) - REPLACES AP15818 HOSE ASSEMBLIES _____ ITEM 3 - RAP90872 (AP24632) ITEM 4 - RAP90871 (AP24628)</p>
MECHANISM AP21570	<p>SINGLE CYLINDER ROOM EXTENSION - 24.0" STROKE - AP21569 KIT</p> <p>SEE MR41.1101 FOR DRAWING AND PARTS INFORMATION. CYLINDER ASSEMBLY _____ ITEM 1 - RAP90688 (27.0" STROKE) - REPLACES AP15818 HOSE ASSEMBLIES _____ ITEM 3 - RAP91750 (AP13842) ITEM 4 - RAP91751 (AP16434)</p>