

# ROOM EXTENSION ASSEMBLIES

## GUIDE PAGE

### "NEWELL" (PAGE 4 OF 5)

PROCEDURE: SEE: "NEWELL" (PAGE 1 OF 5)

MECHANISM AP21642	<p><b>SINGLE CYLINDER ROOM EXTENSION - 24.0" STROKE - AP21641 KIT</b></p> <p><a href="#">SEE MR41.1101 FOR DRAWING AND PARTS INFORMATION.</a>            CYLINDER ASSEMBLY _____ ITEM 1 - RAP90688 (27.0" STROKE) - REPLACES AP15818            HOSE ASSEMBLIES _____ ITEM 3 - RAP91750 (AP13842) ITEM 4 - RAP91751 (AP16434)</p>
MECHANISM AP21674 AP21675	<p><b>VERTICAL ARM ROOM EXTENSION - 24.0" STROKE (WITH SYNCHRONIZING CYLINDER) - AP21643 KIT</b></p> <p><a href="#">SEE MR41.2505 FOR DRAWING AND PARTS INFORMATION.</a>            CYLINDER ASSEMBLY _____ ITEM 1 - RAP90426 (9.689" STROKE) - REPLACES AP14028            SYNCHRONIZING CYLINDER _____ ITEM 6 - RAP90427 (3.815" STROKE) - REPLACES AP14027            HOSE ASSEMBLIES _____ ITEM 4 - RAP90790 (AP20751) ITEM 5 - RAP90321 (AP24653)</p>
MECHANISM AP22030	<p><b>SINGLE CYLINDER ROOM EXTENSION - 24.0" STROKE - AP22029 KIT</b></p> <p><a href="#">SEE MR41.1101 FOR DRAWING AND PARTS INFORMATION.</a>            CYLINDER ASSEMBLY _____ ITEM 1 - RAP90688 (27.0" STROKE) - REPLACES AP15818            HOSE ASSEMBLIES _____ ITEM 3 - RAP90872 (AP24632) ITEM 4 - RAP90871 (AP24628)</p>
MECHANISM AP22034	<p><b>SINGLE CYLINDER ROOM EXTENSION - 24.0" STROKE - AP22033 KIT</b></p> <p><a href="#">SEE MR41.1101 FOR DRAWING AND PARTS INFORMATION.</a>            CYLINDER ASSEMBLY _____ ITEM 1 - RAP90688 (27.0" STROKE) - REPLACES AP15818            HOSE ASSEMBLIES _____ ITEM 3 - RAP90872 (AP24632) ITEM 4 - RAP90871 (AP24628)</p>
MECHANISM AP22124	<p><b>SINGLE CYLINDER ROOM EXTENSION - 24.0" STROKE - AP22123 KIT</b></p> <p><a href="#">SEE MR41.1101 FOR DRAWING AND PARTS INFORMATION.</a>            CYLINDER ASSEMBLY _____ ITEM 1 - RAP90688 (27.0" STROKE) - REPLACES AP15818            HOSE ASSEMBLIES _____ ITEM 3 - RAP90872 (AP24632) ITEM 4 - RAP90871 (AP24628)</p>
MECHANISM AP23086	<p><b>SINGLE CYLINDER ROOM EXTENSION - 24.0" STROKE - AP23085 KIT</b></p> <p><a href="#">SEE MR41.1101 FOR DRAWING AND PARTS INFORMATION.</a>            CYLINDER ASSEMBLY _____ ITEM 1 - RAP90688 (27.0" STROKE) - REPLACES AP15818            HOSE ASSEMBLIES _____ ITEM 3 - RAP90872 (AP24632) ITEM 4 - RAP90871 (AP24628)</p>
MECHANISM AP23750 AP24579	<p><b>TRAIN DRIVE ROOM EXTENSION - (4) CYLINDERS - 20.0" STROKE (WITH SYNCHRONIZING CYLINDER)            AP23012, AP25585, AP24892, AND AP25709 KITS</b></p> <p><a href="#">SEE MR41.2650 FOR DRAWING AND PARTS INFORMATION.</a>            CYLINDER ASSEMBLY _____ ITEM 1 - AP25500 - CONTACT HWH CORPORATION FOR REPLACEMENT            SYNCHRONIZING CYLINDER _____ RAP90857 (2.78" STROKE) - REPLACES AP23247  <a href="#">SEE MR41.8000 FOR ADDITIONAL SYNC CYL REPLACEMENT PARTS</a>            HOSE ASSEMBLIES _____ ITEM 1A - RAP91237 - REPLACES AP25732            HOSE ASSEMBLIES _____ ITEM 2 - RAP91531 - REPLACES AP24568 (TOP ROD END)            HOSE ASSEMBLIES _____ ITEM 2 - RAP91530 - REPLACES AP24569 (TOP CAP END)            HOSE ASSEMBLIES _____ ITEM 2 - RAP91540 - REPLACES AP24570 (BOTTOM ROD END)            HOSE ASSEMBLIES _____ ITEM 2 - RAP91538 - REPLACES AP24571 (BOTTOM CAP END)</p>
MECHANISM AP24054	<p><b>SINGLE CYLINDER ROOM EXTENSION - 24.0" STROKE - AP24053 KIT</b></p> <p><a href="#">SEE MR41.1101 FOR DRAWING AND PARTS INFORMATION.</a>            CYLINDER ASSEMBLY _____ ITEM 1 - RAP90688 (27.0" STROKE) - REPLACES AP15818            HOSE ASSEMBLIES _____ ITEM 3 - RAP90872 (AP24632) ITEM 4 - RAP90871 (AP24628)</p>
MECHANISM AP24342	<p><b>SINGLE CYLINDER ROOM EXTENSION - 24.0" STROKE - AP23325 KIT</b></p> <p><a href="#">SEE MR41.1101 FOR DRAWING AND PARTS INFORMATION.</a>            CYLINDER ASSEMBLY _____ ITEM 1 - RAP90688 (27.0" STROKE) - REPLACES AP15818            HOSE ASSEMBLIES _____ ITEM 3 - RAP90872 (AP24632) ITEM 4 - RAP90871 (AP24628)</p>