## OEM Guide Page HWH SpaceMaker Equipment for OTTERBACHER MFG. Vehicles

(File: MR405250.DOC | Revised: 20APR17)

## > Printable PDF File

## PROCEDURE:

- 1. Locate the HWH identification tag on the SpaceMaker mechanism to get the correct mechanism part number.
- 2. Find the correct SpaceMaker mechanism part number in the left column below.
- 3. Refer to the listed HWH Parts Manual Page for general replacement parts information and item number arrangements.
- 4. Note that two-cylinder mechanisms with a synchronizing cylinder have two part numbers. One number is for the left assembly and one is for the right assembly. If the mechanism assembly originally had one number, that number is listed with the new numbers.

SLIDE-OUT Mechanisms			
MECHANISM AP15749	DUAL CYLINDER ROOM EXTENSION – 41.5" STROKE (WITH SYNCHRONIZING CYLINDER) AP15748 KIT SEE > MR412000.HTML FOR DRAWING AND PARTS INFORMATION.		
OR AP19331			
AP 19331 AP 19332	CYLINDER ASSEMBLY	ITEM 1 - RAP90475 (42.5" STROKE)	
	SYNCHRONIZING CYLINDER	REPLACES AP15821 ITEM 3 - RAP90445 (16.895" STROKE) REPLACES AP15764	
	TUBE KIT	ITEM 2 - RAP90481 - REPLACES AP15379	
MECHANISM AP15755	DUAL CYLINDER ROOM EXTENSION – 35.5" STROKE (WITH SYNCHRONIZING CYLINDER) AP15754 KIT		
OR AP19324		WING AND PARTS INFORMATION.	
AP19325	CYLINDER ASSEMBLY	ITEM 1 - RAP90476 (36.0" STROKE)  REPLACES AP15824	
	SYNCHRONIZING CYLINDER	ITEM 3 - RAP90446 (14.425" STROKE)  REPLACES AP15763	
1	TUBE KIT	ITEM 2 - RAP90480 - REPLACES AP13252	
MECHANISM AP15757 OR AP19300	AP15756 KIT	ION – 41.5" STROKE (WITH SYNCHRONIZING CYLINDER) WING AND PARTS INFORMATION.	
AP19301	CYLINDER ASSEMBLY	ITEM 1 - RAP90475 (42.5" STROKE) REPLACES AP15821	
	SYNCHRONIZING CYLINDER	ITEM 3 - RAP90445 (16.895" STROKE)  REPLACES AP15764	
	TUBE KIT	ITEM 2 - RAP90481 - REPLACES AP15379	
MECHANISM AP15758 OR	DUAL CYLINDER ROOM EXTENSION – 29.5" STROKE (WITH SYNCHRONIZING CYLINDER) AP15752 KIT SEE > MR412000.HTML FOR DRAWING AND PARTS INFORMATION.		
AP19333 AP19334	CYLINDER ASSEMBLY	ITEM 1 - RAP90467 (30.0" STROKE)	
	SYNCHRONIZING CYLINDER	REPLACES AP15822 ITEM 3 - RAP90444 (11.950" STROKE) REPLACES AP15762	
	TUBE KIT	ITEM 2 - RAP90480 - REPLACES AP13252	
MECHANISM AP17080	DUAL CYLINDER BED LIFT – 24.0	" STROKE – AP15753 KIT	
	CYLINDER ASSEMBLY	_ AP17080 (24.0" STROKE)-CONTACT HWH CORP.	

MECHANISM AP18611 AP18612	DUAL CYLINDER ROOM EXTENSION – 48.0" STROKE (WITH SYNCHRONIZING CYLINDER) AP18610 KIT SEE > MR412005.HTML FOR DRAWING AND PARTS INFORMATION.	
	CYLINDER ASSEMBLY ITEM 1 - RAP90479 (49.0" STROKE)  REPLACES AP15317	
	SYNCHRONIZING CYLINDER ITEM 3 - RAP90462 (19.575" STROKE) REPLACES AP14500	
	TUBE KIT ITEM 2 - RAP90481 - REPLACES AP15379	
MECHANISM AP18614 AP18615	DUAL CYLINDER ROOM EXTENSION – 48.0" STROKE (WITH SYNCHRONIZING CYLINDER) AP18613 KIT SEE > MR412000.HTML FOR DRAWING AND PARTS INFORMATION.	
	CYLINDER ASSEMBLY ITEM 1 - RAP90479 (49.0" STROKE) REPLACES AP15317	
	SYNCHRONIZING CYLINDER ITEM 3 - RAP90462 (19.575" STROKE) REPLACES AP14500	
	TUBE KIT ITEM 2 - RAP90481 - REPLACES AP15379	