

MECHANISM AP38251 AP38252	UNIVERSAL STRAIGHT OUT – 30.0” STROKE (WITH SYNCHRONIZING CYLINDER) AP41217 KIT SEE > MR41.2685.HTML FOR DRAWING AND PARTS INFORMATION. CYLINDER ASSEMBLY_____ ITEM 1 - RAP92076 (30.5” STROKE) REPLACES AP38072 SYNCHRONIZING CYLINDER_____ ITEM 3 - RAP92077 (10.540” STROKE) REPLACES AP37881 TUBE KIT_____ ITEM 2 - RAP92079 - REPLACES AP38267 HOSE ASSEMBLIES_____ ITEM 4 - RAP24632 (AP24632) ITEM 5 - RAP24638 (AP24638)
MECHANISM AP38944 AP38945	UNIVERSAL LEVEL OUT – 30.0” STROKE (WITH SYNCHRONIZING CYLINDER) AP38545 AND AP40674 KITS SEE > MR41.2690.HTML FOR DRAWING AND PARTS INFORMATION. CYLINDER ASSEMBLY_____ ITEM 1 - RAP92076 (30.5” STROKE) REPLACES AP38072 LIFT CYLINDER ASSEMBLY_____ ITEM 11 - RAP92260 (2.75” LIFT) REPLACES AP38604 SYNCHRONIZING CYLINDER_____ ITEM 3 - RAP92077 (10.540” STROKE) REPLACES AP37881 LIFT SYNCHRONIZING CYLINDER_ ITEM 12 - RAP92316 - REPLACES AP38264 TUBE KIT_____ ITEM 2 - RAP92079 - REPLACES AP38267 HOSE ASSEMBLIES_____ ITEM 4 - RAP24632 (AP24632) ITEM 5 - RAP24638 (AP24638) CENTER LIFT CYLINDER_____ ITEM 13 - RAP92279 - REPLACES AP35823
MECHANISM AP39182 AP39183	UNIVERSAL STRAIGHT OUT – 18.0” STROKE (WITH SYNCHRONIZING CYLINDER) AP38938 KIT SEE > MR41.2685.HTML FOR DRAWING AND PARTS INFORMATION. CYLINDER ASSEMBLY_____ ITEM 1 - RAP92076 (30.5” STROKE) REPLACES AP38072 SYNCHRONIZING CYLINDER_____ ITEM 3 - RAP92369 (6.300” STROKE) REPLACES AP39267 TUBE KIT_____ ITEM 2 - RAP92079 - REPLACES AP38267 HOSE ASSEMBLIES_____ ITEM 4 - RAP24632 (AP24632) ITEM 5 - RAP24638 (AP24638)
MECHANISM AP39159	SINGLE CYLINDER ROOM EXTENSION – 18.0” STROKE – AP38546 KIT SEE > MR41.1100.HTML FOR DRAWING AND PARTS INFORMATION. CYLINDER ASSEMBLY_____ ITEM 1 - RAP91021 (27.0” STROKE) REPLACES AP28682 HOSE ASSEMBLIES_____ ITEM 3 - RAP24632 (AP24632) ITEM 4 - RAP53984 (AP53984)
MECHANISM AP40753 AP40754	UNIVERSAL LEVEL OUT – 30.0” STROKE (WITH SYNCHRONIZING CYLINDER) AP40682 AND AP42344 KITS SEE > MR41.2690.HTML FOR DRAWING AND PARTS INFORMATION. CYLINDER ASSEMBLY_____ ITEM 1 - RAP92076 (30.5” STROKE) REPLACES AP38072 LIFT CYLINDER ASSEMBLY_____ ITEM 11 - RAP92261 (3.50” LIFT) REPLACES AP40746 SYNCHRONIZING CYLINDER_____ ITEM 3 - RAP92077 (10.540” STROKE) REPLACES AP37881 LIFT SYNCHRONIZING CYLINDER_ ITEM 12 - RAP92503 - REPLACES AP40832 TUBE KIT_____ ITEM 2 - RAP92079 - REPLACES AP38267 HOSE ASSEMBLIES_____ ITEM 4 - RAP24632 (AP24632) ITEM 5 - RAP24638 (AP24638) CENTER LIFT CYLINDER_____ ITEM 13 - RAP92506 - REPLACES AP39601

MECHANISM AP43166 AP43167	UNIVERSAL STRAIGHT OUT / LEVEL OUT – 30.0” STROKE (WITH SYNC. CYLINDER) AP43092 KIT SEE > MR41.2685.HTML FOR DRAWING AND PARTS INFORMATION. CYLINDER ASSEMBLY_____ ITEM 1 - RAP92076 (30.5” STROKE) REPLACES AP38072 SYNCHRONIZING CYLINDER_____ ITEM 3 - RAP92513 (10.540” STROKE) REPLACES AP39500 TUBE KIT_____ ITEM 2 - RAP92079 - REPLACES AP38267 HOSE ASSEMBLIES_____ ITEM 4 - RAP24632 (AP24632) ITEM 5 - RAP24638 (AP24638) ROOM LIFT CYLINDERS_____ RAP92514 (4.00” STROKE)–REPLACES AP43168
MECHANISM AP43733 AP43734	UNIVERSAL STRAIGHT OUT – 22.0” STROKE (WITH SYNCHRONIZING CYLINDER) AP44731 KIT SEE > MR41.2685.HTML FOR DRAWING AND PARTS INFORMATION. CYLINDER ASSEMBLY_____ ITEM 1 - RAP92076 (30.5” STROKE) REPLACES AP38072 SYNCHRONIZING CYLINDER_____ ITEM 3 - RAP92522 (7.710” STROKE) REPLACES AP43403 TUBE KIT_____ ITEM 2 - RAP92079 - REPLACES AP38267 HOSE ASSEMBLIES_____ ITEM 4 - RAP24632 (AP24632) ITEM 5 - RAP24638 (AP24638)