

MECHANISM AP40753 AP40754	UNIVERSAL LEVEL OUT – 30.0” STROKE (WITH SYNCHRONIZING CYLINDER) AP52451 KIT SEE > MR412690.HTML FOR DRAWING AND PARTS INFORMATION. CYLINDER ASSEMBLY_____ ITEM 1 - RAP92076 (30.5” STROKE) REPLACES AP38072 LIFT CYLINDER ASSEMBLY_____ ITEM 11 - RAP92261 (3.50” LIFT) REPLACES AP40746 SYNCHRONIZING CYLINDER_____ ITEM 3 - RAP92077 (10.540” STROKE) REPLACES AP37881 LIFT SYNCHRONIZING CYLINDER_ ITEM 12 - RAP92503 - REPLACES AP40832 TUBE KIT_____ ITEM 2 - RAP92079 - REPLACES AP38267 HOSE ASSEMBLIES_____ ITEM 4 - RAP24632 (AP24632) ITEM 5 - RAP24638 (AP24638)
MECHANISM AP42937 AP43938	UNIVERSAL LEVEL OUT – 24.0” STROKE (WITH SYNCHRONIZING CYLINDER) AP52450 KIT SEE > MR412690.HTML FOR DRAWING AND PARTS INFORMATION. CYLINDER ASSEMBLY_____ ITEM 1 - RAP92076 (30.5” STROKE) REPLACES AP38072 LIFT CYLINDER ASSEMBLY_____ ITEM 11 - RAP92261 (3.50” LIFT) REPLACES AP40746 SYNCHRONIZING CYLINDER_____ ITEM 3 - RAP92275 (8.420” STROKE) REPLACES AP39271 LIFT SYNCHRONIZING CYLINDER_ ITEM 12 - RAP92503 - REPLACES AP40832 TUBE KIT_____ ITEM 2 - RAP92079 - REPLACES AP38267 HOSE ASSEMBLIES_____ ITEM 4 - RAP24632 (AP24632) ITEM 5 - RAP24638 (AP24638)
MECHANISM AP43166 AP43167	UNIVERSAL STRAIGHT OUT – 30.0” STROKE (WITH SYNCHRONIZING CYLINDER) AP50351 KIT SEE > MR412685.HTML FOR DRAWING AND PARTS INFORMATION. CYLINDER ASSEMBLY_____ ITEM 1 - RAP92076 (30.5” STROKE) REPLACES AP38072 SYNCHRONIZING CYLINDER_____ ITEM 3 - RAP93303 (10.540” STROKE) REPLACES AP46064 TUBE KIT_____ ITEM 2 - RAP92079 - REPLACES AP38267 HOSE ASSEMBLIES_____ ITEM 4 - RAP24632 (AP24632) ITEM 5 - RAP24638 (AP24638)

SLIDE-OUT “PLATFORM LIFT” Mechanisms	
MECHANISM AP50352 (204”)	PLATFORM LIFT FOUR-CYLINDER SEE > MR414015.HTML FOR DRAWING AND PARTS INFORMATION. CYL WITH SEQUENCE VALVE ASSEMBLY_____ ITEM 1 - RAP93139 (4.8” STROKE) REPLACES AP44387 CYL ASSEMBLY_____ ITEM 2 - RAP93140 (4.8” STROKE) REPLACES AP44395
MECHANISM AP50689 (204”)	PLATFORM LIFT FOUR-CYLINDER SEE > MR414015.HTML FOR DRAWING AND PARTS INFORMATION. CYL WITH SEQUENCE VALVE ASSEMBLY_____ ITEM 1 - RAP93139 (4.8” STROKE) REPLACES AP44387 CYL ASSEMBLY_____ ITEM 2 - RAP93140 (4.8” STROKE) REPLACES AP44395