

# ROOM EXTENSION ASSEMBLIES GUIDE PAGE "REXHALL WEST" (PAGE 2 OF 4)

PROCEDURE: SEE "REXHALL WEST" (PAGE 1 OF 4)

MECHANISM AP19251 AP19252	<p><b>DUAL CYLINDER ROOM EXTENSION - 34.5" STROKE (WITH SYNCHRONIZING CYLINDER) - AP15211 KIT</b></p> <p><a href="#">SEE MR41.2015 FOR DRAWING AND PARTS INFORMATION.</a></p> <p>CYLINDER ASSEMBLY _____ ITEM 1 - RAP90488 (35.0" STROKE) - REPLACES AP15224            SYNCHRONIZING CYLINDER _____ ITEM 3 - RAP90464 (14.01" STROKE) - REPLACES AP14368            TUBE KIT _____ ITEM 2 - RAP90480 - REPLACES AP13252</p>
MECHANISM AP19257 AP19258	<p><b>DUAL CYLINDER ROOM EXTENSION - 25.0" STROKE (WITH SYNCHRONIZING CYLINDER) - AP16496 KIT</b></p> <p><a href="#">SEE MR41.2015 FOR DRAWING AND PARTS INFORMATION.</a></p> <p>CYLINDER ASSEMBLY _____ ITEM 1 - RAP90488 (35.0" STROKE) - REPLACES AP15224            SYNCHRONIZING CYLINDER _____ ITEM 3 - RAP90440 (10.095" STROKE) - REPLACES AP16509            TUBE KIT _____ ITEM 2 - RAP90480 - REPLACES AP13252</p>
MECHANISM AP19392	<p><b>SINGLE CYLINDER ROOM EXTENSION - 24.0" STROKE - AP19391 KIT</b></p> <p><a href="#">SEE MR41.1100 FOR DRAWING AND PARTS INFORMATION.</a></p> <p>CYLINDER ASSEMBLY _____ ITEM 1 - RAP91021 (27.0" STROKE) - REPLACES AP28682            HOSE ASSEMBLY _____ ITEM 3 - RAP90872 (AP24632) ITEM 4 - RAP90871 (AP24628)</p>
MECHANISM AP19409 AP19410	<p><b>DUAL CYLINDER ROOM EXTENSION - 34.5" STROKE (WITH SYNCHRONIZING CYLINDER) - AP14371 KIT</b></p> <p><a href="#">SEE MR41.2010 FOR DRAWING AND PARTS INFORMATION.</a></p> <p>CYLINDER ASSEMBLY _____ ITEM 1 - RAP90488 (35.0" STROKE) - REPLACES AP15224            SYNCHRONIZING CYLINDER _____ ITEM 3 - RAP90464 (14.01" STROKE) - REPLACES AP14368            TUBE KIT _____ ITEM 2 - RAP90480 - REPLACES AP13252</p>
MECHANISM AP19926 AP19927	<p><b>DUAL CYLINDER ROOM EXTENSION - 25.0" STROKE (WITH SYNCHRONIZING CYLINDER) - AP19925 KIT</b></p> <p><a href="#">SEE MR41.2005 FOR DRAWING AND PARTS INFORMATION.</a></p> <p>CYLINDER ASSEMBLY _____ ITEM 1 - RAP90488 (35.0" STROKE) - REPLACES AP15224            SYNCHRONIZING CYLINDER _____ ITEM 3 - RAP90440 (10.095" STROKE) - REPLACES AP16509            TUBE KIT _____ ITEM 2 - RAP90480 - REPLACES AP13252</p>
MECHANISM AP19929 AP19930	<p><b>DUAL CYLINDER ROOM EXTENSION - 34.5" STROKE (WITH SYNCHRONIZING CYLINDER) - AP19928 KIT</b></p> <p><a href="#">SEE MR41.2005 FOR DRAWING AND PARTS INFORMATION.</a></p> <p>CYLINDER ASSEMBLY _____ ITEM 1 - RAP90488 (35.0" STROKE) - REPLACES AP15224            SYNCHRONIZING CYLINDER _____ ITEM 3 - RAP90464 (14.01" STROKE) - REPLACES AP14368            TUBE KIT _____ ITEM 2 - RAP90480 - REPLACES AP13252</p>
MECHANISM AP20618 AP20619	<p><b>DUAL CYLINDER ROOM EXTENSION - 34.5" STROKE (WITH SYNCHRONIZING CYLINDER) - AP20581 KIT</b></p> <p><a href="#">SEE MR41.2011 FOR DRAWING AND PARTS INFORMATION.</a></p> <p>CYLINDER ASSEMBLY _____ ITEM 1 - RAP90488 (35.0" STROKE) - REPLACES AP15224            SYNCHRONIZING CYLINDER _____ ITEM 3 - RAP90464 (14.01" STROKE) - REPLACES AP14368            TUBE KIT _____ ITEM 2 - RAP90480 - REPLACES AP13252</p>
MECHANISM AP20620 AP20621	<p><b>DUAL CYLINDER ROOM EXTENSION - 25.0" STROKE (WITH SYNCHRONIZING CYLINDER) - AP20580 KIT</b></p> <p><a href="#">SEE MR41.2011 FOR DRAWING AND PARTS INFORMATION.</a></p> <p>CYLINDER ASSEMBLY _____ ITEM 1 - RAP90488 (35.0" STROKE) - REPLACES AP15224            SYNCHRONIZING CYLINDER _____ ITEM 3 - RAP90440 (10.095" STROKE) - REPLACES AP16509            TUBE KIT _____ ITEM 2 - RAP90480 - REPLACES AP13252</p>
MECHANISM AP20867 AP20868	<p><b>DUAL CYLINDER LEVEL OUT ROOM EXTENSION - 32.0" STROKE (WITH SYNC. CYLINDER) - AP20866 KIT</b></p> <p><a href="#">SEE MR41.2200 FOR DRAWING AND PART INFORMATION.</a></p> <p>CYLINDER ASSEMBLY _____ ITEM 1 - RAP90696 (36.0" STROKE) - REPLACES AP19256            SYNCHRONIZING CYLINDER _____ ITEM 3 - RAP90466 (12.98" STROKE) - REPLACES AP14301            HOSE ASSEMBLY _____ ITEM 2 - RAP91561 - REPLACES AP24648</p>