

ROOM EXTENSION ASSEMBLIES GUIDE PAGE "REXHALL WEST" (PAGE 3 OF 4)

PROCEDURE: SEE "REXHALL WEST" (PAGE 1 OF 4)

MECHANISM AP20870 AP20871	<p>DUAL CYLINDER LEVEL OUT ROOM EXTENSION - 34.5" STROKE (WITH SYNC. CYLINDER) - AP20869 KIT</p> <p>SEE MR41.2200 FOR DRAWING AND PART INFORMATION.</p> <p>CYLINDER ASSEMBLY _____ ITEM 1 - RAP90696 (36.0" STROKE) - REPLACES AP19256 SYNCHRONIZING CYLINDER _____ ITEM 3 - RAP90464 (14.01" STROKE) - REPLACES AP14368 HOSE ASSEMBLY _____ ITEM 2 - RAP91561 - REPLACES AP24648</p>
MECHANISM AP20978 AP20979	<p>DUAL CYLINDER ROOM EXTENSION - 18.0" STROKE (WITH SYNCHRONIZING CYLINDER) - AP20977 KIT</p> <p>SEE MR41.2011 FOR DRAWING AND PART INFORMATION.</p> <p>CYLINDER ASSEMBLY _____ ITEM 1 - RAP90488 (35.0" STROKE) - REPLACES AP15224 SYNCHRONIZING CYLINDER _____ ITEM 3 - RAP90439 (7.21" STROKE) - REPLACES AP16618 TUBE KIT _____ ITEM 2 - RAP90480 - REPLACES AP13252</p>
MECHANISM AP21156	<p>CYLINDER ASSEMBLY - 24.5" STROKE</p> <p>CYLINDER ASSEMBLY _____ AP21156 (24.5" STROKE) - CONTACT HWH CORPORATION</p>
MECHANISM AP21944	<p>SINGLE CYLINDER ROOM EXTENSION - 34.5" STROKE - AP21943 KIT</p> <p>SEE MR41.1008 FOR DRAWING AND PART INFORMATION.</p> <p>CYLINDER ASSEMBLY _____ ITEM 1 - RAP90488 (35.0" STROKE) - REPLACES AP15224 TUBE KIT _____ ITEM 2 - RAP90480 - REPLACES AP13252</p>
MECHANISM AP22788	<p>SINGLE CYLINDER ROOM EXTENSION - 25.0" STROKE - AP22787 KIT</p> <p>SEE MR41.1008 FOR DRAWING AND PART INFORMATION.</p> <p>CYLINDER ASSEMBLY _____ ITEM 1 - RAP90488 (35.0" STROKE) - REPLACES AP15224 TUBE KIT _____ ITEM 2 - RAP90480 - REPLACES AP13252</p>
MECHANISM AP22919 AP22920	<p>DUAL CYLINDER LEVEL OUT ROOM EXTENSION - 34.5" STROKE (WITH SYNC. CYLINDER) - AP22918 KIT</p> <p>SEE MR41.2200 FOR DRAWING AND PART INFORMATION.</p> <p>CYLINDER ASSEMBLY _____ ITEM 1 - RAP90696 (36.0" STROKE) - REPLACES AP19256 SYNCHRONIZING CYLINDER _____ ITEM 3 - RAP90464 (14.01" STROKE) - REPLACES AP14368</p>
MECHANISM AP24307	<p>SINGLE CYLINDER ROOM EXTENSION - 25.0" STROKE - AP24336 KIT</p> <p>SEE MR41.1100 FOR DRAWING AND PART INFORMATION.</p> <p>CYLINDER ASSEMBLY _____ ITEM 1 - RAP91021 (27.0" STROKE) - REPLACES AP28682 HOSE ASSEMBLY _____ ITEM 3 - RAP91424 (AP24635) ITEM 4 - RAP90872 (AP24632)</p>
MECHANISM AP27070 AP27071	<p>LATERAL ARM ROOM EXTENSION - 21.0" STROKE (WITH TORSION BAR) - AP27069 KIT</p> <p>NO INFORMATION AVAILABLE.</p>
MECHANISM AP29218 AP29219	<p>X-SLIDE ROOM EXTENSION - 25.0" STROKE (WITH SYNCHRONIZING CYLINDER) - AP30099 KIT</p> <p>SEE MR41.2670 FOR DRAWING AND PART INFORMATION.</p> <p>CYLINDER ASSEMBLY _____ ITEM 1 - RAP91350 (11.40" STROKE) - REPLACES AP27865 SYNCHRONIZING CYLINDER _____ ITEM 3 - RAP91701 (4.300" STROKE) - REPLACES AP30260 TUBE KIT _____ ITEM 2 - RAP91229 - REPLACES AP27587 HOSE ASSEMBLIES _____ ITEM 5 - RAP90800 (AP24640) ITEM 6 - RAP91553 (AP27857)</p>
MECHANISM AP29415	<p>SINGLE CYLINDER ROOM EXTENSION - 18.0" STROKE - AP29414 KIT</p> <p>SEE MR41.1008 FOR DRAWING AND PART INFORMATION.</p> <p>CYLINDER ASSEMBLY _____ ITEM 1 - RAP90488 (35.0" STROKE) - REPLACES AP15224 TUBE KIT _____ ITEM 2 - RAP90480 - REPLACES AP13252</p>
MECHANISM AP29841	<p>SINGLE CYLINDER ROOM EXTENSION - 18.0" STROKE - AP29840 KIT</p> <p>SEE MR41.1100 FOR DRAWING AND PART INFORMATION.</p> <p>CYLINDER ASSEMBLY _____ ITEM 1 - RAP91021 (27.0" STROKE) - REPLACES AP28682 HOSE ASSEMBLY _____ ITEM 3 - RAP90872 (AP24632) ITEM 4 - RAP91424 (AP24635)</p>