

ROOM EXTENSION ASSEMBLIES GUIDE PAGE "ROELOFSEN HEESWEG 41"

PROCEDURE:

1. Locate the HWH identification tag on the room extension mechanism to get the correct room extension part number.
2. Find the correct room extension part number in the left column below.
3. Refer to the proper parts page for general replacement parts information and item number arrangements.
4. Two cylinder room extensions with a synchronizing cylinder have two room extension part numbers. One number is for the left assembly, one is for the right assembly. If the room extension assembly originally had one number, that number is listed with the new numbers.

MECHANISM AP18960 AP18961	DUAL CYLINDER ROOM EXTENSION - 35.5" STROKE (WITH SYNCHRONIZING CYLINDER) - AP41444 KIT SEE MR41.2000 FOR DRAWING AND PARTS INFORMATION. CYLINDER ASSEMBLY _____ ITEM 1 - RAP90476 (36.0" STROKE) - REPLACES AP15824 SYNCHRONIZING CYLINDER _____ ITEM 3 - RAP90446 (14.425" STROKE) - REPLACES AP15763 TUBE ASSEMBLIES _____ ITEM 2 - RAP90480 - REPLACES AP13252
MECHANISM AP40238 AP40239	DUAL CYLINDER ROOM EXTENSION - 35.5" STROKE (WITH SYNCHRONIZING CYLINDER) - AP39362 KIT SEE MR41.2011 FOR DRAWING AND PARTS INFORMATION. CYLINDER ASSEMBLY _____ ITEM 1 - RAP92542 (36.5" STROKE) - REPLACES AP40622 SYNCHRONIZING CYLINDER _____ ITEM 3 - RAP90446 (14.425" STROKE) - REPLACES AP15763 TUBE ASSEMBLIES _____ ITEM 2 - RAP90481 - REPLACES AP15379
MECHANISM AP40241 AP40242	DUAL CYLINDER ROOM EXTENSION - 43.5" STROKE (WITH SYNCHRONIZING CYLINDER) - AP40240 KIT SEE MR41.2011 FOR DRAWING AND PARTS INFORMATION. CYLINDER ASSEMBLY _____ ITEM 1 - RAP92499 (44.5" STROKE) - REPLACES AP40624 SYNCHRONIZING CYLINDER _____ ITEM 3 - RAP92500 (17.795" STROKE) - REPLACES AP40571 TUBE ASSEMBLIES _____ ITEM 2 - RAP90481 - REPLACES AP15379
MECHANISM AP41437 AP41438	DUAL CYLINDER ROOM EXTENSION - 43.5" STROKE (WITH SYNCHRONIZING CYLINDER) - AP41436 KIT SEE MR41.2000 FOR DRAWING AND PARTS INFORMATION. CYLINDER ASSEMBLY _____ ITEM 1 - RAP92499 (44.5" STROKE) - REPLACES AP40624 SYNCHRONIZING CYLINDER _____ ITEM 3 - RAP92500 (17.795" STROKE) - REPLACES AP40571 TUBE ASSEMBLIES _____ ITEM 2 - RAP90481 - REPLACES AP15379