

ROOM EXTENSION ASSEMBLIES GUIDE PAGE "ROLLING STAR MFG."

PROCEDURE:

1. Locate the HWH identification tag on the room extension mechanism to get the correct room extension part number.
2. Find the correct room extension part number in the left column below.
3. Refer to the proper parts page for general replacement parts information and item number arrangements.
4. Two cylinder room extensions with a synchronizing cylinder have two room extension part numbers. One number is for the left assembly, one is for the right assembly. If the room extension assembly originally had one number, that number is listed with the new numbers.

MECHANISM AP19281 AP19282	DUAL CYLINDER ROOM EXTENSION - 70.0" STROKE (WITH SYNCHRONIZING CYLINDER) - AP39582 KIT SEE MR41.2006 FOR DRAWING AND PARTS INFORMATION. CYLINDER ASSEMBLY _____ ITEM 1 - RAP91189 (71.0" STROKE) - REPLACES AP17270 SYNCHRONIZING CYLINDER _____ ITEM 3 - RAP91809 (26.860" STROKE) - REPLACES AP17246 TUBE KIT _____ ITEM 2 - RAP91221 - REPLACES AP17321
MECHANISM AP35721 AP35722	UNIVERSAL LEVEL OUT ROOM EXTENSION - 30.0" STROKE (WITH SYNC. CYLINDER) - AP35638 KIT SEE MR41.2683 FOR DRAWING AND PARTS INFORMATION. CYLINDER ASSEMBLY _____ ITEM 1 - RAP91702 (34.0" STROKE) - REPLACES AP31461 LIFT CYLINDER ASSEMBLY _____ ITEM 10 - RAP91992 - REPLACES AP34390 (2.75" LIFT) SYNCHRONIZING CYLINDER _____ ITEM 3 - RAP90473 (12.155" STROKE) - REPLACES AP13192 TUBE KIT _____ ITEM 2 - RAP91703 - REPLACES AP31486 HOSE ASSEMBLIES _____ ITEM 4 - RAP90872 (AP24632) ITEM 5 - RAP91421 (AP24818) LIFT SYNCHRONIZING CYLINDER _____ ITEM 11 - RAP92473 - REPLACES AP34576 CENTER LIFT CYLINDER _____ ITEM 12 - RAP92279 - REPLACES AP35823
MECHANISM AP38944 AP38945	UNIVERSAL LEVEL OUT - 30.0" STROKE (WITH SYNCHRONIZING CYLINDER) - AP39948 KIT SEE MR41.2690 FOR DRAWING AND PARTS INFORMATION. CYLINDER ASSEMBLY _____ ITEM 1 - RAP92076 (30.5" STROKE) - REPLACES AP38072 LIFT CYLINDER ASSEMBLY _____ ITEM 11 - RAP92260 (2.75" LIFT) - REPLACES AP38604 SYNCHRONIZING CYLINDER _____ ITEM 3 - RAP92077 (10.540" STROKE) - REPLACES AP37881 LIFT SYNCHRONIZING CYLINDER _____ ITEM 12 - RAP92316 - REPLACES AP38264 TUBE KIT _____ ITEM 2 - RAP92079 - REPLACES AP38267 HOSE ASSEMBLIES _____ ITEM 4 - RAP90872 (AP24632) ITEM 5 - RAP91421 (AP24818)
MECHANISM AP43166 AP43167	UNIVERSAL STRAIGHT OUT - 30.0" STROKE (WITH SYNC. CYLINDER) - AP44328, AP47659, AND AP48600 KITS SEE MR41.2685 FOR DRAWING AND PARTS INFORMATION. CYLINDER ASSEMBLY _____ ITEM 1 - RAP92076 (30.5" STROKE) - REPLACES AP38072 SYNCHRONIZING CYLINDER _____ ITEM 3 - RAP93303 (10.540" STROKE) - REPLACES AP46064 TUBE KIT _____ ITEM 2 - RAP92079 - REPLACES AP38267 HOSE ASSEMBLIES _____ ITEM 4 - RAP90872 (AP24632) ITEM 5 - RAP91421 (AP24818)
MECHANISM AP46612	PLATFORM LIFT WITH TWO CYLINDERS - 210" WIDE - PART OF AP44328 KIT SEE MR41.4005 FOR DRAWING AND PARTS INFORMATION. CYLINDER W/ SEQ. VALVE ASSY. _____ ITEM 1 - RAP93139 (4.8" STROKE) - REPLACES AP44387 CYLINDER ASSEMBLY _____ ITEM 2 - RAP93140 (4.8" STROKE) - REPLACES AP44395
MECHANISM AP47850	PLATFORM LIFT WITH TWO CYLINDERS - 148.75" WIDE - PART OF AP47659 KIT SEE MR41.4005 FOR DRAWING AND PARTS INFORMATION. CYLINDER W/ SEQ. VALVE ASSY. _____ ITEM 1 - RAP93139 (4.8" STROKE) - REPLACES AP44387 CYLINDER ASSEMBLY _____ ITEM 2 - RAP93140 (4.8" STROKE) - REPLACES AP44395
MECHANISM AP48601	PLATFORM LIFT WITH TWO CYLINDERS - 76.438" WIDE SEE MR41.4005 FOR DRAWING AND PARTS INFORMATION. CYLINDER W/ SEQ. VALVE ASSY. _____ ITEM 1 - RAP93139 (4.8" STROKE) - REPLACES AP44387 CYLINDER ASSEMBLY _____ ITEM 2 - RAP93140 (4.8" STROKE) - REPLACES AP44395
MECHANISM AP52918	PLATFORM LIFT WITH TWO CYLINDERS - 148.75" WIDE SEE MR41.4005 FOR DRAWING AND PARTS INFORMATION. CYLINDER W/ SEQ. VALVE ASSY. _____ ITEM 1 - RAP93139 (4.8" STROKE) - REPLACES AP44387 CYLINDER ASSEMBLY _____ ITEM 2 - RAP93140 (4.8" STROKE) - REPLACES AP44395