

MECHANISM AP43166 AP43167	UNIVERSAL STRAIGHT OUT – 30.0” STROKE (WITH SYNCHRONIZING CYLINDER) AP44328, AP47659, AND AP48600 KITS SEE > MR412685.HTML FOR DRAWING AND PARTS INFORMATION. CYLINDER ASSEMBLY_____ ITEM 1 - RAP92076 (30.5” STROKE) REPLACES AP38072 SYNCHRONIZING CYLINDER_____ ITEM 3 - RAP93303 (10.540” STROKE) REPLACES AP46064 TUBE KIT_____ ITEM 2 - RAP92079 - REPLACES AP38267 HOSE ASSEMBLIES_____ ITEM 4 - RAP24632 (AP24632) ITEM 5 - RAP24638 (AP24638)
--	--

SLIDE-OUT “PLATFORM LIFT” Mechanisms	
MECHANISM AP46612 (210”)	PLATFORM LIFT TWO-CYLINDER – PART OF AP44328 KIT SEE > MR414005.HTML FOR DRAWING AND PARTS INFORMATION. CYLINDER W/SEQ. VALVE ASSY.____ ITEM 1 - RAP93139 (4.8” STROKE) REPLACES AP44387 CYLINDER ASSEMBLY_____ ITEM 2 - RAP93140 (4.8” STROKE) REPLACES AP44395
MECHANISM AP47850 (148-3/4”)	PLATFORM LIFT TWO-CYLINDER – PART OF AP47659 KIT SEE > MR414005.HTML FOR DRAWING AND PARTS INFORMATION. CYLINDER W/SEQ. VALVE ASSY.____ ITEM 1 - RAP93139 (4.8” STROKE) REPLACES AP44387 CYLINDER ASSEMBLY_____ ITEM 2 - RAP93140 (4.8” STROKE) REPLACES AP44395
MECHANISM AP48601 (76-7/16”)	PLATFORM LIFT TWO-CYLINDER SEE > MR414005.HTML FOR DRAWING AND PARTS INFORMATION. CYLINDER W/SEQ. VALVE ASSY.____ ITEM 1 - RAP93139 (4.8” STROKE) REPLACES AP44387 CYLINDER ASSEMBLY_____ ITEM 2 - RAP93140 (4.8” STROKE) REPLACES AP44395
MECHANISM AP52918 (148-3/4”)	PLATFORM LIFT TWO-CYLINDER SEE > MR414005.HTML FOR DRAWING AND PARTS INFORMATION. CYLINDER W/SEQ. VALVE ASSY.____ ITEM 1 - RAP93139 (4.8” STROKE) REPLACES AP44387 CYLINDER ASSEMBLY_____ ITEM 2 - RAP93140 (4.8” STROKE) REPLACES AP44395